

—Globe and Mail, Donald Grant

Andy Obergfell, left, and Ken Parr look over plans as they piece together an original Fox Moth.

## Pioneering biplane to fly again

By DONALD GRANT

Thirty-two years ago Max Ward paid \$10,500 for his first aircraft, a small wooden biplane known as a Fox Moth.

This week a similar plane will roll out of a huge hangar at Toronto International Airport, having cost the veteran pilot and airline president more than \$50,000.

But to Max Ward the Fox Moth, this one painted silver with red trim, means more than dollars and cents.

It represents his beginning — and to some extent Canada's — in the airline business as well as hours of flying in the desolate Yellowknife area following the Second World War.

The Wardair president's plane will be only the 147th Fox Moth ever built and the first to roll out of a carpentry shop. All the others of the type — a modified version of the better-known Tiger Moth, with a bigger fuselage and three passenger seats — were produced by de Havilland in Britain and Canada.

Wardair employees have been piecing their craft together for nearly 18 months, using original plans and some parts salvaged from factory-built Fox Moths.

Some of the parts came from a Wardair-owned Fox Moth that crashed into Lake Ontario during the 1976 CNE air show. Garth Martin, the pilot and a Wardair 747 captain, scrambled from the cockpit while George Benedik was pulled out unconscious by harbor policemen who dived under three times to rescue him.

It was no easy task to find parts to put together a replacement for the wrecked plane. But the recuperating Mr. Martin found two Fox Moths in England (one Canadian-built), another in Australia and one in the United States on which some restoration had been done. He settled for the one at Newburyport, Mass., which bore serial number 7 and wooden wings dated Nov. 7, 1942.

Wardair general foreman Andy Obergfell and employees Ken Allan and Ken Parr were assigned to produce an airworthy plane.

"The fuselage was beyond anything," said Mr. Parr, pointing at the old spruce hulk now hanging in the carpentry shop. "We wanted it strictly as a pattern."

A new fuselage was painstakingly molded of spruce, then covered with nylon and painted silver.

"The wings we could use. But beyond that the rest was useless. The engine has zero time because it was reconditioned. But it's old . . . at least 30 years old."

Between the plane from the United States and the one that crashed in 1976, Mr. Parr said, "we've come up with an aircraft."

"It couldn't be closer to an original," he said proudly.

After the latest Fox Moth is tested for airworthiness, Captain Martin said, he'd like a flip in it. "Oh, I'll try it. There's no problem there," he said with a laugh, adding that Mr. Benedik, who crashed with him in 1976, will go along for the ride.

Government of Canada / Gouvernement du Canada

MEMORANDUM

NOTE DE SERVICE



PCA - Vancouver      OCA - Toronto  
 WCA - Edmonton      QCA - Montreal  
 CCA - Winnipeg      ACA - Moncton

SECURITY - CLASSIFICATION - DE SÉCURITÉ
OUR FILE - N/REFERENCE 6600-8-0 (LICA)
YOUR FILE - V/REFERENCE 5002-060102
DATE January 27, 1978

DGCA/DDG - Ottawa  
 KLA ON8

*ASA-2*  
*To note and file*  
*3/4/78*  
*NSA*  
*3/2/78*

SUBJECT / OBJET: Operation of Vintage/Heritage Aircraft at Air Shows

Two recent major accidents, with serious and fatal injuries, occurred at a large international air show in 1976 and 1977. Investigation of these accidents reveals a commonality of contributing factors in the flight of these "vintage" or "heritage" aircraft. The accident in 1976 involved a Fox Moth aircraft and that in 1977 a Fairey Firefly. Both aircraft were being flown by pilots with high total flight time experience. Operation of the aircraft in semi-acrobatic manoeuvres, i.e. steep turns or wing-overs was followed by a loss of control and subsequent crash. Further investigation indicated that neither of the pilots had extensive experience on the aircraft type, nor recent acrobatic competency.

After review of these accidents by Headquarters Branches (DLI/DAS), it has been concluded that incidents of this nature can be reduced if adequate pilot competency and proficiency requirements on type are applied. It is not intended to prohibit flight exhibitions by historic aircraft, which are extremely popular with the viewing public, but to ensure that pilots operating these aircraft are qualified on the type and competent to perform the manoeuvres on the program.

Since Regional Controllers Civil Aviation approve applications for air shows, prior to approval they are to review carefully the details of the proposed flight program, and more particularly, the aircraft type, the experience and competency of the pilot in command and the type of manoeuvres scheduled. The operation of vintage aircraft in acrobatic flight manoeuvres need not be curtailed if the aircraft is designed for such flight manoeuvres. The pilot involved in such acrobatic manoeuvres with these aircraft is to be checked for experience and competency on type by a qualified Civil Aviation Inspector, if practicable, or by an approved DFTE with acrobatic endorsement. The experience must include a minimum of ten hours of pilot in command on type within the last sixty days. The pilot shall have demonstrated to the satisfaction of either the Civil Aviation Inspector or the DFTE that the manoeuvres involved at the show can be performed safely.

McPherson  
 MacSwain  
 Mussen  
 McDone  
 Phillips  
 Burton  
 Goodbrand  
 Batchelor  
 Aston  
 Pichep  
 Little

Rec'd. in ASA FEB 3 1978 93	Rec'd in DAS FEB 2 1978 AS
-----------------------------------	----------------------------------

..../2

A letter will be required from the Civil Aviation Inspector or the DFTE attesting that the pilot has demonstrated his ability to perform satisfactorily the scheduled acrobatic flight manoeuvres during a pre-air show demonstration. In the event the foregoing requirements are not met, the aircraft should only be permitted to perform fly-passes in level flight with only turns as required to keep the aircraft within the flight demonstration area. There should be a formal written understanding between the sponsor of the air show and the approving Regional Controllers to this effect.

Recognizing that there may be extenuating circumstances, Regional Controllers should exercise their good judgement or if considered necessary, obtain further advice from Headquarters, and Regions should select and brief DFTE's to be approved for this task.

Original Signed by

H. R. FINLEY

H.R. Finley  
Acting Deputy Director General  
Civil Aeronautics

**Transport Canada**

**Transports Canada**

**ROUTE SLIP**

**BORDEREAU D'ACHEMINEMENT**

TO - À (NAME - NOM)	DESIGNATOR SYMBOLE	<input type="checkbox"/> For approval Pour approbation
<i>V.H. McPherson</i>	OLA1	<input type="checkbox"/> For Signature Pour Signature
<i>Toronto</i>		<input type="checkbox"/> Comment Observations
		<input checked="" type="checkbox"/> For your Information Pour votre Information
		<input type="checkbox"/> Per our Conversation Selon notre Conversation
		<input type="checkbox"/> Discuss with me Discuter avec moi
		<input type="checkbox"/> Take appropriate action Prendre les mesures appropriées



REMARKS - REMARQUES

*For your information & records is copy of memo from DGCA/DDG to all Regions concerning vintage aircraft & airshows.*

*Any comment? 2/21/78*

*would this have info. prevented the fire & Accident? ? ?*

*Jolly. Copies on Fox Moth & Liffly accident files, please.*

FROM - DE Signature <i>Paul Sanders</i>	Date <i>9/2/78</i>	Telephone - Téléphone
--	-----------------------	-----------------------

000005

Transport  
Canada  
AirTransports  
Canada  
AirAIRCRAFT ACCIDENT REPORT  
RAPPORT D'ACCIDENT D'AVIATION

"This accident was investigated to provide guidance toward the prevention of a recurrence. The content of this report is confined to cause-related circumstances and is published for accident prevention purposes only".

ø60102

DH-83C

C-FDJB

DATE: 5 September 1976 1316 EST  
 OPERATION: Private-Air Show Demonstration DAMAGE: Substantial  
 PLACE: Toronto CNE waterfront, Ont. 43/38N 79/26W  
 LOCALE: Lake - high waves  
 WEATHER: Cloud 4000 scattered, wind NNW 22 gusting to 29 mph, vis 15, temp 17°C  
 PILOT: Airline Transport  
 TOTAL HOURS: 15,000 ALL 41 ON TYPE  
 LAST 90 DAYS: 158 ALL 41 ON TYPE  
 CASUALTIES: Crew: 1 serious; pass: 1 serious  
 OCCURRENCE: During an air display the vintage aircraft had just commenced a low level turn when it stalled and spun into the water.

Following an into wind run-in at 300' above the lake surface the pilot initiated a planned 360° turn to the right. During the first portion of the turn, the airspeed decayed from an indicated 75K to an indicated 60K as the bank angle was increased.

Due to the downwind drift illusion created by the high winds there was a natural tendency for the pilot to apply excessive right rudder to compensate for the illusion of yaw and to increase the bank angle to compensate for drift towards the spectators.

When the bank angle reached 62° the indicated stall speed of the aircraft had increased from 40K to an indicated 60K.

As the aircraft passed through 90° of the turn, in non-coordinated flight and a high angle of bank, a violent power-on stall was experienced. The aircraft flicked to the right and entered a spin from which the pilot failed to recover.

1. Loss of control in flight.

ICAO FACTORS

- 64A16 Pilot - Failed to obtain/maintain flying speed.  
 64A23 Pilot - Improper operation of primary flight controls.  
 64A31 Pilot - Lack of familiarity with aircraft.  
 64A02 Pilot - Attempted operation beyond experience/ability level.

SAFETY PROPOSALS

Pilots performing in air shows with vintage aircraft should be encouraged to limit their performance to straight and level flybys.

Carrying passengers during air show performances should be discouraged and should never be on-board unless officials of the air show are aware that they are, particularly rescue personnel.

ASI-A3  
13/9/77

ASR ACTION

DAS recommend to DGCA that vintage aircraft be restricted to straight and level flypasts. See attached copy of memo.

P. D. Saunders,  
ASR-3  
Sept. 30, 1977

Stats  
11-000006

BEST COPY AVAILABLE

SECURITY CLASSIFICATION DE SECURITE
CONTROL NUMBER
5002-060102 (ASR-2)
YOUR FILE REFERENCE
DATE
September 29, 1977

TO: A/DAS

FROM: A/DAS

SUBJECT: Accidents During Air Shows

The accidents involving a DH83 Fox Moth (1976) and a Faircy Firefly (1977) at the CNE Airshow are examples of a type of aircraft accident that has recurred many times in the past few years during air shows or exhibition flying. A factor common to most of these accidents is inexperience; i.e., by attempting maneuvers for which the pilot had not developed an adequate skill on type. The risk is usually increased by the relatively low height at which the maneuvers are attempted.

The pilot of the above-mentioned DH83 Fox Moth was a 15,000 hour B747 Captain [redacted]

[redacted] With the exception of his initial training on Harvards 22 years earlier most of his flying had been on heavy aircraft.

[redacted] Photographic evidence of this (the first) maneuver shows the aircraft in a right turn with nearly 60° bank, (the pilot thought his turn to be about 35° bank). During this turn the aircraft stalled and flicked to the right (inward) and entered a right spin. The photography shows right aileron and full right rudder was held through the two turns to impact.

To reduce the risk of similar accidents recurring we recommend appropriate steps be taken to ensure that vintage aircraft participating in exhibition flying or airshows be restricted to straight and level fly pasts. An exception could be made for approval of other requested maneuvers only when the pilot has a proven proficiency to perform them.

s.19(1)

H.A. Fawcett,  
A/Director,  
Aviation Safety Bureau.

ASR \_\_\_\_\_

ASR-2 \_\_\_\_\_

cc: DAS: A/DAS: ASR: ASR-2  
T.M. Saunderson, SLIC



Transport  
Canada  
Air

Transports  
Canada  
Air

AIRCRAFT ACCIDENT REPORT  
RAPPORT D'ACCIDENT D'AVIATION



CAI  
02173

"This accident was investigated to provide guidance toward the prevention of a recurrence. The content of this report is confined to cause-related circumstances and is published for accident prevention purposes only".

Ø60102

DH-83C

C-FDJB

DATE: 5 September 1976 1316 EST  
OPERATION: Private-Air Show Demonstration DAMAGE: Substantial  
PLACE: Toronto CNE waterfront, Ont. 43/38N 79/26W  
LOCALE: Lake - high waves  
WEATHER: Cloud 4000 scattered, wind NNW 22 gusting to 29 mph, vis 15, temp 17°C  
PILOT: Airline Transport  
TOTAL HOURS: 15,000 ALL 41 ON TYPE  
LAST 90 DAYS: 158 ALL 41 ON TYPE  
CASUALTIES: Crew: 1 serious; pass: 1 serious  
OCCURRENCE: During an air display the vintage aircraft had just commenced a low level turn when it stalled and spun into the water.

Following an into wind run-in at 300' above the lake surface the pilot initiated a planned 360° turn to the right. During the first portion of the turn, the airspeed decayed from an indicated 75K to an indicated 60K as the bank angle was increased.

Due to the downwind drift illusion created by the high winds there was a natural tendency for the pilot to apply excessive right rudder to compensate for the illusion of yaw and to increase the bank angle to compensate for drift towards the spectators.

When the bank angle reached 62° the indicated stall speed of the aircraft had increased from 40K to an indicated 60K.

As the aircraft passed through 90° of the turn, in non-coordinated flight and a high angle of bank, a violent power-on stall was experienced. The aircraft flicked to the right and entered a spin from which the pilot failed to recover.

- 1. Loss of control in flight.

ICAO FACTORS

- 64A16 Pilot - Failed to obtain/maintain flying speed.
- 64A23 Pilot - Improper operation of primary flight controls.
- 64A31 Pilot - Lack of familiarity with aircraft.
- 64A02 Pilot - Attempted operation beyond experience/ability level.

SAFETY PROPOSALS

Pilots performing in air shows with vintage aircraft should be encouraged to limit their performance to straight and level flybys.

Carrying passengers during air show performances should be discouraged and should never be on-board unless officials of the air show are aware that they are, particularly rescue personnel.

ASI-A3  
13/9/77

ASR ACTION



Jumbo jet captain inspects Fox Moth, rebuilt with some parts from crashed predecessor

# Crashed into lake at CNE, Fox Moth to fly again

By DONALD GRANT

"It was like banging into a fence post with a car."

That's how Garth Martin described the crash of his plane, a vintage Fox Moth, into Lake Ontario last year during the annual Canadian National Exhibition air show.

"It was rough luck," said the Wardair 747 captain. "That's about it."

About 50,000 people lining the CNE waterfront witnessed the crash.

They saw the little plane that was like the one Max Ward (owner of Wardair) used to start his air service in 1946 hit the water and sink in front of them. But Mr. Martin scrambled from the cockpit in the rear fuselage as the plane sank nose first. It took down his passenger, George Benedik, unconscious in the enclosed front cabin.

Harbor policemen dived three times to rescue Mr. Benedik, who was seriously injured and spent three months in hospital.

Yesterday Mr. Martin proudly showed another Fox Moth that is being built with bits and pieces of that crash plane, plus a second Fox Moth Mr. Ward commissioned him to buy.

The plane that crashed had been bought five years before by Mr. Ward in memory of his first Fox Moth, the wooden aircraft with the 140-horsepower engine that began his air service in the bush areas of Yellowknife.

When he was asked to find another one, Capt. Martin found that only 93 had been built in Britain and 53 in Canada. And after a world-wide search he found one, forgotten by a plane restorer in Newburyport, Mass.

That pile of spiderwebs, nuts and bolts was to be the basis of the new Fox Moth, using parts of the plane that crashed. But the plane with wooden wings dated Nov. 7, 1942, was beyond using completely.

"It's been easier to build a new fuselage than restore the old one," said Capt. Martin.

Since June, under the direction of Dan McNiven, Wardair's manager of maintenance, Ken Allen, Andy Obergfell and Ken Parr have been piecing the Fox Moth together.

And who'll be making the solo flight?

"Oh I will," said Capt. Martin without hesitation.



Gouvernement  
du Canada

MEMORANDUM

NOTE DE SERVICE

TO  
A ASI OTTAWA

FROM  
DE OCAI TORONTO

SECURITY - CLASSIFICATION - DE SÉCURITÉ
OUR FILE - N/RÉFÉRENCE  5002-060102
YOUR FILE - V/RÉFÉRENCE
DATE  January 27th, 1977

SUBJECT  
OBJET

DEHAVILLAND DH-83C, C-FDJB  
ACCIDENT: TORONTO (C.N.E. WATER FRONT), ONTARIO  
SEPTEMBER 5TH, 1976

ENCLOSED IS A COPY OF THE REPORT OF AN AIRCRAFT ACCIDENT AND PHOTOS  
PERTAINING TO THE ABOVE MENTIONED AIRCRAFT ACCIDENT.

V. H. McPHERSON  
REGIONAL SUPERINTENDENT  
ACCIDENT INVESTIGATION

ENCLOSURE

SAM/rb

MINISTRY OF TRANSPORT  
AVIATION SAFETY INVESTIGATION

REPORT OF INVESTIGATION OF AN AIRCRAFT

ACCIDENT

INCIDENT

FILE NUMBER
0101 5002 - 060102
AIRCRAFT REGISTRATION
0102 C-FDJB.

LOCATION OF OCCURRENCE		PROVINCE	REGION
0103 TORONTO (C.N.E WATER FRONT)		0104 ONTARIO	0105 ONTARIO
LATITUDE	LONGITUDE	DATE	TIME (LOCAL)
0106 43° 38' N	0107 79° 26' W	0108 5 SEPT 1976	0109 14:16 EDT
LIGHT CONDITIONS AT SITE	A DAWN	C DUSK (TWILIGHT)	E NIGHT (BRIGHT)
	<input checked="" type="checkbox"/> DAYLIGHT	D NIGHT (DARK)	

PERSONNEL IDENTIFICATION

REGISTERED OWNER	NAME	ADDRESS		
	WARD AIR CANADA 1975 LTD.	26 <sup>TH</sup> FLOOR, C.N. TOWERS EDMONTON, ALTA.		
OPERATOR	NAME	ATC LICENCE CLASSIFICATION THIS FLIGHT		
	<input checked="" type="checkbox"/> 0113 SAME AS OWNER OR			
	ADDRESS			
	ATC LICENCE NUMBER			
s.19(1)	OPERATOR CODE	0111		
		<input checked="" type="checkbox"/> NONE E 4 M 7APS S 8		
		B 1 F 5 N 7AAD T 9-2		
		C 2 G 6 P 7AIRA U 9-3		
		D 3 H 7RF Q 7AC V 9-4		
		K 7FT R 7 <sup>A</sup> CONST. W 9-5		
	L 7AP			
STATUS RESPECTIVE TO THIS AIRCRAFT	0113	B RENTER	C LESSEE	D UNKNOWN
	TYPE OF OPERATOR (GENERAL AVIATION)	A FLYING SCHOOL	M FLYING CLUB	R AERIAL WORK
		Q CHARTER	F FBO-SALES/SERVICES/RENTAL	<input checked="" type="checkbox"/> PRIVATE OWNER
		I STATE - MUNICIPAL	B CORPORATE/EXECUTIVE	Y OTHER
		H STATE - PROVINCIAL	K A/C MANUFACTURER	
		G STATE - FEDERAL	C AERIAL APPLICATOR	
0114				
PILOT IN COMMAND	0115 NAME SAME AS: A OWNER B OPERATOR OR	0117 STATUS IF NOT OWNER OR OPERATOR		
	GARTH MCLEAN MARTIN	C UNAUTHORIZED USER <input checked="" type="checkbox"/> EMPLOYEE		
	ADDRESS	D RENTER G BORROWER		
	LICENCE NUMBER 0116	E CLUB MEMBER		
	XDA - 867	Y OTHER		

MATERIAL IDENTIFICATION

AIRCRAFT	MANUFACTURER	MODEL	SERIAL NUMBER	MAX T/O WEIGHT	YEAR OF MANUFACTURE
	0118 DE HAVILLAND AIRCRAFT OF CANADA	0119 DH-83C	0120 F.M-28	0121 2100	0122
AIRCRAFT CLASSIFICATION	<input checked="" type="checkbox"/> AEROPLANE	I GYROPLANE	F DIRIGIBLE	HOMEBUILT	
	B HELICOPTER	D BALLOON	E BLIMP	ULTRA-LIGHT	
	C GLIDER	Y OTHER			
LANDING GEAR	H TRICYCLE FIXED	G TAILWHEEL RETRACT	D SKI	Y	OTHER
	F TRICYCLE RETRACT	B HULL/FLOAT	E SKID		
	<input checked="" type="checkbox"/> TAILWHEEL FIXED	C AMPHIBIOUS			
WING/ROTOR	A LOW WING	C MID WING	E TWIN ROTOR	<input checked="" type="checkbox"/>	BIPLANE
	B HIGH WING	D SINGLE ROTOR	Y OTHER		
SPECIAL EQUIPMENT	A TOWING GEAR	D AMBULANCE	G AIR DROP (CARGO)	K	AIR DROP (PARACHUTIST)
	B PHOTO	E GEOPHYSICAL SURVEY	H SLING/HOIST	L	WATER BOMBING
	C AERIAL APPLICATION	F MONSOON BUCKET	Y OTHER		

### CONCLUSION DE L'AUTOPSIE

MALADIE CONNEXE		MALADIE IMPRÉVUE		BLESSURES GRAVES À L'IMPACT		AUTRES BLESSURES À L'IMPACT	
RAPPORT NON OFFICIEL		RAPPORT NON OFFICIEL		PROBABLEMENT IMMÉDIATEMENT MORTELLE		AUCUNE ÉVALUATION	
AUCUNE DOCUMENTATION NÉCESSAIRE		AUCUNE DOCUMENTATION NÉCESSAIRE		PROBABLEMENT MORTELLE EN DEÇÀ DE 10 SEC.		MANIPULATION DES COMMANDES	
PREUVE PROBABLE AU PILOTE		PILOTE PROBABLEMENT AU COURANT		PROBABLEMENT MORTELLE EN DEÇÀ DE 1 HEURE		ENTRAVÉ PAR CEINTURE DE SÉCURITÉ	
PREUVE DE TRAITEMENT		PREUVE DE TRAITEMENT		SURVIE DE PLUS DE 1 HEURE		ENTRAVÉ PAR BRETELLE DE SÉCURITÉ	
PREUVE DE TRAITEMENT				PROBABILITÉ DE PERTE IMMÉDIATE DE CONNAISSANCE		FORCES D'ÉCRASEMENT	
OCCUPATION DU SIÈGE		ÉTAT AVANT L'IMPACT			ÉTAT APRÈS L'IMPACT		
AUCUNE ÉVALUATION		AUCUNE PREUVE D'ANORMALITÉ			ASPHYXIE (FUMÉE)		
GENRE DE CONTRÔLE A CAUSÉ LA BLESSURE		RÉGIME DISPONIBLE			NOYADE		
		INCENDIE (FUMÉE)			CHOC CHIRURGICAL GRAVE		
IDENTIFICATION POSITIVE À L'AUTOPSIE		EXPLOSION			SURVIE PROLONGÉE		
		AUTRE BLESSURE					

### BIOCHIMIE

T O X I C O L O G I E	ALCOOL DANS LE SANG		ALCOOL DANS LES TISSUS		ALCOOL DANS L'URINE		MONOXYDE DE CARBONE		AUTRE PRODUITS TOXIQUES	
	INSIGNIFIANT < 10 Mg		INSIGNIFIANT		INSIGNIFIANT		INSIGNIFIANT		CONCORDE À UNE DOSE THÉRAPEUTIQUE	
	PRÉSENT 11-40 Mg		EN ACCORD AVEC L'ALCOOL DANS LE SANG		EN ACCORD AVEC L'ALCOOL DANS LE SANG		CONCORDE AVEC LA FUMÉE DE CIGARETTE		ANORMALEMENT ÉLEVÉ EN RAP. AVEC UNE DOSE THER.	
	IMPORTANT 41-150 Mg		CONCORDE AVEC LES DON. D'UN ÉTAT APRÈS-ABSORPT'N		EN ACCORD AVEC L'ALCOOL DANS LES TISSUS		CONCORDE AVEC LA PRÉSENCE D'UN INCENDIE		PROVENANT DE L'ACCIDENT	
	BEAUCOUP PLUS ÉLEVÉ QUE 150Mg		CONSOMMATION RÉCENTE		PUTRÉFACTION				PROVENANT DU PILOTAGE	
P R O F I L	QUALITÉ DU PROFIL LACTICÉNIQUE		PROBABILITÉ DE TENSION LACTICÉNIQUE		LACTICÉMIE CARDIAQUE		AUTRE ÉTAT LACTICÉMIQUE DU CORPS		AUTRE LACTICÉMIE DES TISSUS, PROUVER	
	INCOMPLET		AUCUNE PREUVE DE TENSION		RELATIVEMENT ÉLEVÉE		HYPOGLYCÉMIE		VALEUR PULMONAIRE ÉLEVÉ	
	IRRÉGULIER		VALEUR CARDIAQUE FAIBLE, 2-6 SEC.		RELATIVEMENT NORMALE		CHOC CHIRURGICAL PROLONGÉ		VALEUR PULMONAIRE FAIBLE	
	MODIFIÉ PAR LE MILIEU		GLUCOGÉNÈSE 6-20 SEC.		RELATIVEMENT FAIBLE		MODIFICATION POSSI. PAR UN AGENT TOXIQUE		ACTIVITÉ MUSCULAIRE	
	DANS LES LIMITES (FIABLE)		RÉPONSE TOTALE À LA TENSION 20 SEC. +		ANORMALEMENT FAIBLE		HYPOXIE		SPLEEN ANORMAL	
				VALEURS Na ET K DISPONIBLES						

### ÉPIDÉMIOLOGIE DE L'ACCIDENT

ANTÉCÉDENTS PERSONNELS (EN INSCRIRE JUSQU'À 3)		ANTÉCÉDENTS DE TRAVAIL (INSCRIRE JUSQU'À 3)	
BLESSURES OU OPÉRATIONS RÉPÉTÉES		ANTÉCÉDENTS PROUVÉS DE TRAVAIL MAL EXÉCUTÉ	
HYPOCONDRIE		ACCIDENTS INDUSTRIELS	
ACCIDENTS DE VOITURE/D'AVIATION		DISCIPLINE AU TRAVAIL (BON TRAVAILLANT)	
IRRESPONSABILITÉ FINANCIÈRE		FAIBLE MOTIVATION AU TRAVAIL	
TÉMÉRITÉ		FAIBLE MOTIVATION AU VOL	
ANTÉCÉDENTS FAMILIAUX PROVOQUANT UNE TENSION			
ANTÉCÉDENTS DE VOL (EN INSCRIRE JUSQU'À 3)		ÉVALUATION DE SES COLLÈGUES	
CONTRAVENTIONS ANTÉRIEURES AUX RÈGLES DE L'AIR		EXCEPTIONNELLEMENT COMPÉTENT	
CONTRAVENTIONS PROBABLES, NON PROUVÉES		PILOTE SÛR, FIABLE	
OPÉRATIONS AÉRIENNES PLUS OU MOINS LICITES		PILOTE MOYEN, CONSIDÉRANT SON EXPÉRIENCE	
FALSIFICATION POSSIBLE DE DOCUMENTS		PILOTE MOYEN, RENDEMENT PARFOIS INFÉRIEUR	
DÉCISIONS PRISES PAR IMPULSION		PILOTE MOYEN, LENT À APPRENDRE	
PEUR DE VOLER		PILOTE INFÉRIEUR À LA MOYENNE	

REMARQUES:

**MATERIAL IDENTIFICATION (CONT'D)**

ENGINE(S)	MANUFACTURER 0201 <b>DE HAVILLAND</b>	MODEL 0202 <b>GIPSY MAJOR 1-C</b>	NUMBER INSTALLED 0203 <b>ONE</b>	POWER 0204 <b>140</b>	<input checked="" type="checkbox"/> HP. lbs THRUST	
SERIAL NUMBERS	1 <b>85607A</b>	2	3	4		
ENGINE TYPE 0205	<input checked="" type="checkbox"/> RECIPROCATING C	F	TURBOSHAFT (HELICOPTERS) D	B	TURBOJET E	NONE
PROPELLER(S)/ ROTOR BLADES 0206	MANUFACTURER <b>FAIRY REED</b>	MODEL 0207 <b>94103-X1</b>	SERIAL NOS <b>FR 35796</b>	(1)	(2)	(3)
PROPELLER TYPE 0208 0209	<input checked="" type="checkbox"/> FIXED METAL B	C	VARIABLE PITCH D	E	FIXED WOODEN	REVERSIBLE
ROTOR SYSTEM 0210	A	RIGID	D	HINGELESS	G	VARIABLE DIAMETER
	B	SEMI-RIGID	E	GIMBALLED	H	CONTROLLABLE
	C	FULLY ARTICULATED	F	VARIABLE GEOMETRY	K	FULLY INTEGRATED PROPULSION SYSTEMS

**HISTORY OF THE FLIGHT**

OPERATION GENERAL AVIATION 0211	INSTRUCTIONAL	A0	DUAL	A1	SUPERVISED SOLO	A2	CHECK	A3	TRAINING (EXCEPT AIR CARRIER)
	NON-COMMERCIAL	B0	PLEASURE	B2	BUSINESS-PROFESSIONAL PILOT	B3	BUSINESS-NON-PROFESSIONAL PILOT		
		B1	PRACTICE	<input checked="" type="checkbox"/> B9	<b>AIR SHOW PARTICIPANT</b>				
	COMMERCIAL (DIRECT FINANCIAL RETURN)	CA	AERIAL APPLICATION	CB	ASSOCIATED CROP CONTROL ACTIVITIES		CC	FIRE CONTROL	
		CE	AERIAL SURVEY	CF	AERIAL ADVERTISING		CD	ASSOCIATED FIRE CONTROL ACTIVITIES	
		CG	POWER/PIPELINE PATROL	CH	AERIAL SPOTTING (OVER WATER)		CK	CONSTRUCTION (ROTORCRAFT)	
		CW	AERIAL PHOTOGRAPHY	CX	AERIAL AMBULANCE		CY	OTHER	
	MISCELLANEOUS	DA	EXPERIMENTAL	DC	DEMONSTRATION		DB	TEST	
		DD	FERRY	DY	OTHER				
	OPERATION AIR TRANSPORT 0211	DOMESTIC	SCHEDULED		PASSENGER			OTHER	
INTERNATIONAL		NON-SCHEDULED		CARGO			TRAINING		
LOAD DESCRIPTION 0212	A	NONE	E	PARACHUTIST(S)	K	PHOTO EQUIPMENT	P	SIGN/DROGUE	
	<input checked="" type="checkbox"/> B	PASSENGERS	F	PESTICIDES	L	FERTILIZER	Q	GLIDER	
	C	CARGO	G	POLES/TOWERS	M	FISH/FISH EGGS	Y	OTHER	
	D	CARGO & PASSENGERS	H	WATER/CHEMICAL	N	POTENTIALLY DANGEROUS CARGO			
LOAD POSITION 0213	<input checked="" type="checkbox"/> INTERNAL	B	EXTERNAL	C	NONE				
LAST DEPARTURE POINT 0214	<b>TORONTO ISLAND AIRPORT</b>				POINT OF INTENDED LANDING 0215	<b>TORONTO ISLAND AIRPORT</b>			
FIRST PHASE OF OPERATION 0216	<b>LOW PASS (DIB)</b>				FIRST TYPE OF OCCURRENCE 0217	<b>SPIRAL (9)</b>			
SECOND PHASE OF OPERATION 0218					SECOND TYPE OF OCCURRENCE 0219				
PRELIMINARY VERSION OF OCCURRENCE									

The pilot was attempting a low level 360 degree turn to the right, while participating in the Canadian International Air Show at the C.N.E. water front, Lake Ontario.

The aircraft struck the surface of the water in a steep nose down right wing low altitude.

AIRCRAFT DAMAGE 0220	N	NONE	M	MINOR	<input checked="" type="checkbox"/> B	SUBSTANTIAL	D	DESTROYED	Z	UNKNOWN
INJURIES TO PERSONS	PILOT IN COMMAND		FATAL	SERIOUS	MINOR	NONE	UNKNOWN	TOTAL		
			0221	0222 <b>ONE</b>	0223	0224	0225	0226	<b>ONE</b>	
	OTHER CREW		0227	0228	0229	0230	0231	0232		
	PASSENGERS		0233	0234 <b>ONE</b>	0235	0236	0237	0238	<b>ONE</b>	
PERSONS OUTSIDE AIRCRAFT		0239	0240	0241	0242	0243	0244			

**EXAMEN MÉDICAL – DONNÉES PHYSIOLOGIQUES (SUITE)**

VISION	VISION NORMALE ÉTABLIE		VISION CORRIGÉE		CORRECTION LORS DE L'ÉVÉNEMENT		PHORIE		MONOCULAIRE		AUTRE AFFECTION DE LA VISION			
	AU DERNIER EXAMEN MÉDICAL		MYOPIE		INCONNUE		MANIFESTE DE LONGUE DATE		VRAIE DE LONGUE DATE		NON TRAITÉE			
	RENDEMENT RÉCENT		HYPERMÉTROPIE		PORT DE LUNETTES						EN TRAITEMENT			
	MESURES PRISES AU COURS DES 3 DERNIERS MOIS		PRESBYTIE				PHORIE GRAVE		VRAIMENT MONOCULAIRE					
			AUTRE		PORT DE LENTILLES DE CONTACT		PHORIE PEU PRONONCÉE		MONOCULAIRE TEMPORAIRE		INCONNUE AU MOMENT DE L'ÉVÉNEMENT			
OREILLES NEZ GORGE	OUIE NORMALE ÉTABLIE		PERTE ACCEPTABLE ENREGISTRÉE		PERTE UNILATÉRALE DE PLUS DE 30 DB		EMPLOI D'UN AMPLIFICATEUR ORICULAIRE		BARATRAUMATISME OTITIQUE OU DES SINUS		AUTRES AFFECTIONS			
	PAR EXAMEN		OREILLE DROITE		OREILLE DROITE		DISPOSITIF INDIVIDUELLE		ANTÉCÉDENTS		ANTÉCÉDENTS			
	PAR AUDIOGRAMME		OREILLE GAUCHE		OREILLE GAUCHE		CASQUE D'ÉCOUTE		CRISE AIGUË		AIGUË			
		LES DEUX OREILLES		LES DEUX OREILLES				POSSIBLE						
SYSTÈME GÉNITO URINAIRE	COLIQUES RÉNALES				GROSSESSE				AUTRES AFFECTIONS					
	ANTÉCÉDENTS				SANS COMPLICATION				ANTÉCÉDENTS					
	ATTAQUE AIGUË				COMPLICATIONS GRAVES				AFFECTION AIGUË					
					ANTÉCÉDENTS DE COMPLICATION									
SYSTÈME NERVEUX CENTRAL	CONVULSION		SYNCOPE		AFFECTION CÉRÉBRO-VASCULAIRE		MIGRAINE		AUTRES CONDITIONS					
	ANTÉCÉDENTS SEULS		ANTÉCÉDENTS SEULS		ANTÉCÉDENTS SEULS		ANTÉCÉDENTS DE MAUX DE TÊTE		ANTÉCÉDENTS					
	BLESSURE ANTÉRIEURE À LA TÊTE		CIRCONSTANCES AGGRAVANTES PRÉS.		CIRCONSTANCES AGGRAVANTES		ANTÉCÉDENTS DE MIGRAINE ORDINAIRE		AFFECTION AIGUË					
	CIRCONSTANCES AGGRAVANTES		RÉGIME INSUFFISANT		AFFECTION AIGUË		AFFECTION AIGUË							
ÉTAT PSYCHIATRIQUE	PSYCHOSE		NEUROSE		TROUBLE DE PERSONNALITÉ		ALCOOLISME		AUTRES					
	ANTÉCÉDENTS		ANTÉCÉDENTS		ANTÉCÉDENTS		ANTÉCÉDENTS		ANTÉCÉDENTS					
	IRRITATION AIGUË		CIRCONSTANCES AGGRAVANTES		CIRCONSTANCES AGGRAVANTES		TRAITEMENT ANTÉRIEUR		SEULEMENT					
	TENTATIVE DE SUICIDE		TENTATIVE DE SUICIDE		ACTES RÉPÉTÉS CONTRE L'AUTORITÉ		DIMINUTION DES FACULTÉS		AFFECTION AIGUË SUSPECTÉE					
AUTRES	AFFECTIONS ORTHOPÉDIQUES		AFFECTION HORMONALE		PROTHÈSES DES MEMBRES		EFFETS DES MÉDICAMENTS		EMPLOI DES DROGUES		AUTRES AFFECTIONS NON MENTIONNÉES			
	ANTÉCÉDENTS SEULS		ANTÉCÉDENTS SEULS		VÉRIFIÉ EN VOL		EFFET POSSIBLE		ANTÉCÉDENTS SEULS		ANTÉCÉDENTS SEULS			
	AFFECTION AIGUË SUSPECTÉE		STABILISÉ PAR TRAITEMENT		INACCEPTABLE		PREUVE D'EMPLOI PERSONNEL		EMPLOI RÉCENT		EMPLOI POSSIBLE			
	AFFECTIONS MUSCULAIRES						MÉDICAMENTS PRESCRITS		EMPLOI RÉCENT POSSIBLE		EMPLOI PROBABLE/CONNU			
	ANTÉCÉDENTS SEULS		STABILISATION DOUTEUSE		IMPLICATION IMPROBABLE		EFFET PROBABLE DES MÉDICAMENTS		DOSSIER DE TRAITEMENT ANTÉR.					
AFFECTION AIGUË SUSPECTÉE														
ORIENTATION	ERREURS DE PERCEPTION		DANGER MAL PERÇU				DANGER PERÇU				RÉACTION AMORCÉE			
			DIMINUTION TECHNIQUE DE LA VISION				ILLUSION VISUELLE POSSIBLE				RÉACTION PROBABLEMENT INCORRECTE			
			DONNÉES VISUELLES INSUFFISANTES				DANGER PROBABLEMENT MAL INTERPRÉTÉ				TEMPS INSUFFISANT POUR TERMINER LA MANOEUVRE			
			DISTRACTION POSSIBLE				DANGER PROBABLEMENT IGNORÉ				PERTE DE CONTRÔLE			
			IGNORANCE PROBABLE DU DANGER											
	AUTRES ERREURS D'ORIENTATION		FONCTIONS VESTIBULAIRES (ALCOOL NON EN CAUSE)				AUTRES SENS				RÉACTION AMORCÉE			
			DÉSORIENTATION (CONDITIONS PRÉSENTES)				AMORCE DE CHANGEMENT DE DIRECTION				RÉACTION INCORRECTE PROBABLE			
			DÉSORIENTATION NON PERÇUE PROBABLEMENT INDUITE				AMORCE DE CHANGEMENT DE VITESSE				RÉACTION AGRAVANTE POSSIBLE			
			DÉSORIENTATION PERÇUE ET PRODUITE				CHANGEMENT DE DIRECTION DE VITESSE PROBABLEMENT INDUIT				PERTE DE CONTRÔLE			
			CAUSE PROBABLE DE DÉSORIENTATION (MÉDICAMENT, MALADIE)								DÉSORIENTATION PLUS POUSSÉE INDUITE			

**HISTORY OF THE FLIGHT (CONT'D)**

TYPE OF FLIGHT PLAN 0301	<input checked="" type="checkbox"/> NONE	<input type="checkbox"/> VFR	<input type="checkbox"/> IFR	<input type="checkbox"/> UNKNOWN
	FLIGHT NOTIFICATION-FILED	FLIGHT NOTIFICATION-VERBAL	OTHER	

TYPE OF CLEARANCE 0302	<input checked="" type="checkbox"/> NONE	<input type="checkbox"/> TAXI	<input type="checkbox"/> ENROUTE	<input type="checkbox"/> APPROACH/DEPARTURE
---------------------------	--	-------------------------------	----------------------------------	---

AERONAUTICAL DEPARTURE BRIEFING 0303	1 AIS AVAILABLE & USED - INFORMATION VALID	3 AIS AVAILABLE AND NOT USED
	2 AIS AVAILABLE & USED - INFORMATION INVALID	<input checked="" type="checkbox"/> AIS NOT AVAILABLE

DURATION OF FLIGHT 0304 HR <b>10</b> MIN.	AIRCRAFT SPEED		ALTITUDE OF OCCURRENCE (AGL) 0307 feet	COLLISION OR NEAR COLLISION			
	AT TIME OF OCCURRENCE IN FLIGHT 0305 <b>60</b> Kt	AT IMPACT 0306 Kt		REGISTRATION OF OTHER AIRCRAFT 0308	EVASIVE ACTION TAKEN 0309		
				YES	NO	UNK	

AIRSPACE SEGMENT 0310	E	UNCONTROLLED AIRSPACE	P	MOVEMENT AREA	K	HOLDING AREA
	<input checked="" type="checkbox"/>	CONTROLLED AIRSPACE	C	CONTROL ZONE	N	MANOEUVRING AREA
	B	CONTROL AREA	J	INITIAL APPROACH AREA	Y	OTHER
	G	ADVISORY AIRSPACE	L	INTERMEDIATE APPROACH AREA		
	I	ADVISORY AREA	M	FINAL APPROACH AREA		

EMERGENCY CIRCUMSTANCES (Select up to 2) 0311	A	LOW ON FUEL	M	AIRFRAME BUFFET/VIBRATION	C	PASSENGER DISTURBANCE
	D	FIRE WARNING	N	UNUSUAL NOISE	P	PHYSICAL CONDITION OF OCCUPANT (NOT FLIGHT CREW)
	E	LATERAL CONTROL PROBLEM	R	PROP/ENGINE VIBRATION	S	UNLAWFUL INTERFERENCE (HIJACKING, SABOTAGE)
	F	PITCH CONTROL PROBLEM	T	LANDING GEAR MALFUNCTION	U	PHYSICAL CONDITION OF FLIGHT CREW
	G	DIRECTIONAL CONTROL PROBLEM	V	PRESSURIZATION PROBLEM	H	WEATHER ADVERSE/UNFAVOURABLE
	J	AIRCRAFT DAMAGE SUSPECTED OR KNOWN	X	KNOWN OR SUSPECTED REDUCED AIRCRAFT PERFORMANCE	I	VISUAL & LIGHT CONDITIONS
	K	MECHANICAL DISCREPANCY SUSPECTED OR KNOWN	B	SMOKE INSIDE AIRCRAFT	Y	OTHER
	L	DOOR/PANEL OPEN	Q	FUMES INSIDE AIRCRAFT		

FORCED LANDING-PRECAUTIONARY LANDING 0312	A	F.L. ON AERODROME/HELIPORT	B	F.L. OFF AERODROME ON LAND	C	DITCHING
	D	P.L. ON AERODROME	E	P.L. OFF AERODROME		

TYPE OF INSTRUMENT APPROACH FLOWN 0313	E	NDB STRAIGHT-IN	G	ILS RADAR MONITOR STRAIGHT-IN	3	ILS CAT I OR ABOVE MANUAL CONTROL
	F	NDB CIRCLING	H	ILS RADAR MONITOR CIRCLING	5	ILS CAT I AUTOPILOT CONTROL
	C	VOR STRAIGHT-IN	I	ILS STRAIGHT-IN	6	ILS CAT II AUTOPILOT CONTROL
	D	VOR CIRCLING	J	ILS CIRCLING	4	ILS CAT II MANUAL CONTROL
	X	VORTAC	K	LOC BCRS STRAIGHT-IN	7	ILS CAT III AUTOLANDING
	P	SURVEILLANCE RADAR STRAIGHT-IN	L	LOC BCRS CIRCLING	R	VISUAL STRAIGHT-IN
	Q	SURVEILLANCE RADAR CIRCLING	I	LOC FRONT CRS STRAIGHT-IN	S	VISUAL FULL CIRCUIT
	T	PAR STRAIGHT-IN	J	LOC FRONT CRS CIRCLING	Y	OTHER

INJURY INDEX 0314	F	FATAL	<input checked="" type="checkbox"/> SERIOUS	M	MINOR	N	NONE
----------------------	---	-------	---	---	-------	---	------

INJURIES TO PERSONS	FATAL	SERIOUS	MINOR	NONE	UNKNOWN	TOTALS
	PILOT IN COMMAND	0221	0222 <b>ONE</b>	0223	0224	0225
CO-PILOT	0315	0316	0317	0318	0319	0320
DUAL STUDENT	0321	0322	0323	0324	0325	0326
SUPERVISORY PILOT	0327	0328	0329	0330	0331	0332
FLIGHT ENGINEER/SYSTEMS OPERATOR	0333	0334	0335	0336	0337	0338
NAVIGATOR/RADIO OPERATOR	0339	0340	0341	0342	0343	0344
CABIN CREW	0345	0346	0347	0348	0349	0350
SUPERNUMERARY CREW	0351	0352	0353	0354	0355	0356
PASSENGERS	0233	0234 <b>ONE</b>	0235	0236	0237	0238 <b>ONE</b>
TOTAL ABOARD	0357	0358	0359	0360	0361	0362
OTHER (AIRCRAFT)	0363	0364	0365	0366	0367	0368
OTHER (GROUND)	0369	0370	0371	0372	0373	0374
<b>TOTALS</b>	0375	0376 <b>TWO</b>	0377	0378	0379	0380 <b>TWO</b>

MILITARY INVOLVEMENT 0381	Y	YES	<input checked="" type="checkbox"/> NO
------------------------------	---	-----	--

DAMAGE TO OTHER PROPERTY 0382	A	SCHOOL	B	HOUSE(S)	F	COMMERCIAL BLDG	C	CHURCH
	E	OFFICE BUILDING	D	APARTMENT(S)	G	SHOPPING CENTRE		OTHER

**EXAMEN MÉDICAL – DONNÉES PHYSIOLOGIQUES**

IDENTITÉ		NOM		STATURE	DATE DU DERNIER EXAMEN	NOM DU MÉDECIN EXAMINATEUR ET/OU SON NUMÉRO	
PILOTE							
COPILOTE				Cm			
MÉCANICIEN	AGE	SEXE		POIDS	PROFIL	LIEU DE L'EXAMEN	
CONTRÔLEUR DU TA		HOMME					
PASSAGER		FEMME					
SITUATION DE FAMILLE		EMPLOI		NIVEAU D'INSTRUCTION ATTEINT		ORIGINE ETHNIQUE	

I N C A P A C I T É	PROBABILITÉ	SOUDAINE TOTALE	INSIDIEUSE TOTALE	SOUDAINE PARTIELLE	INSIDIEUSE PARTIELLE
	EXCLUE				
	POSSIBLE				
	PROBABLE				
	CONFIRMÉE				
	PREUVE				
	RAPPORTS ET ANTÉCÉDENTS MÉDICAUX				
	PILOTE OU TÉMOINS				
	AUTOPSIE				
	BIOCHIMIE				
ANALYSE DE LA TRAJECTOIRE DE VOL					

R E N D E M E N T	DÉTÉRIORATION GRAVE DES CAPACITÉS		DÉTÉRIORATION INSIDIEUSE DES CAPACITÉS (À LONG TERME)		CAPACITÉS RESTREINTES PRONONCÉES		CAPACITÉS RESTREINTES INSIDIEUSES	
	ÉVIDENTE		ÉVIDENTE		ÉVIDENTE		ÉVIDENTE	
	NON ÉVIDENTE FONCTIONNEMENT NORMAL CONSTATÉ		NON ÉVIDENTE FONCTIONNEMENT CONSTATÉ		EXCLUE SELON LES DOSSIERS MÉDICAUX		EXCLUE SELON LES DOSSIERS MÉDICAUX	
	NE POUVAIT ÊTRE EXAMINÉE		NE POUVAIT ÊTRE EXAMINÉ					
	P <sub>OS</sub>	P <sub>ROB</sub>	P <sub>OS</sub>	P <sub>ROB</sub>	P <sub>OS</sub>	P <sub>ROB</sub>	P <sub>OS</sub>	P <sub>ROB</sub>
		RÉSISTANCE À LA FATIGUE DE VOL		VIEILLISSEMENT PHYSIOLOGIQUE (OU FATIGUE)		PARALYSIE PARTIELLE		OBESITÉ CROISSANTE
		FORTE ANGOISSE		LÉGÈRE ANGOISSE CHRONIQUE		OBESITÉ ET INCOMPATIBILITÉ ANTHROPOMÉTR.		PROTHÈSE (FONCTIONNEMENT RESTREINT)
		PRÉOCCUPATION CORPORELLE (MALADIE-DOULEUR)		EXASPÉRATION ET CONTRARIÉTÉ		GROSSESSE		GROSSESSE
	SURCHARGE SENSORIEL NERF À BOUT		FATIGUE CHRONIQUE DE VOL		PROTHÈSE		DALTONISME	
	DIÈTE INSUFFISANTE (HYPOGLYCÉMIE)		ÉVALUATION D'APTITUDE (CAPACITÉ DIMINUÉE)		VÊTEMENT ET RESTRICTION		CONDITION MÉDICAL OU TRAITEMENT	

ÉTAT MÉDICAL CONCERNANT LE SYSTÈME CARDIO-VASCULAIRE	ARTÉRIOSCLÉROSE	THROMBOSE CORONAIRE	ARYTHMIÉ	HYPERTENSION	AUTRE ÉTAT DU S.C.V.
	LÉGÈRE	RÉCENTE	AIGUE	AUX LIMITES	ANTÉCÉDENT SEULEMENT
	MODÉRÉE	ANCIENNE	DE LONGUE DATE BÉNIGNE	MODÉRÉE NON TRAITÉE	ÉTAT GRAVE
	GRAVE		ANTÉCÉDENTE	TRAITÉE	

ÉTAT MÉDICAL CONCERNANT LE SYSTÈME GASTRO-INTESTINAL	ULCÈRE PEPTIQUE	VÉSICULE BILIAIRE	NAUSÉE/VOMISSEMENT	FONCTIONNEMENT ANORM. DES INTESTINS	AUTRE ÉTAT GI
	ANTÉCÉDENT SEULEMENT	NON SYMPTOMATIQUE	CRISE AIGUË	CRISE AIGUË	ÉTAT GRAVE
	SOINS EN COURS	ANTÉCÉDENT DE COLIQUE	ANTÉCÉDENT	ANTÉCÉDENT	ANTÉCÉDENT SEULEMENT
	COMPLEXE				

ÉTAT MÉDICAL CONCERNANT LE SYSTÈME RESPIRATOIRE	INFECTION AIGUË	INFECTION CHRONIQUE	HYPERVENTILATION	ENGORGEMENT (ASTHME)	AUTRE ÉTAT RS
	ANTÉCÉDENT	ANTÉCÉDENT SEULEMENT	ANTÉCÉDENT	ANTÉCÉDENT	ANTÉCÉDENT
	ÉTAT PRÉSENT	TOUX CHRONIQUE	PREUVE DE L'ÉTAT	PREUVE DE CRISE AIGUË	ÉTAT GRAVE
		TOUX AIGUË IRRITANTE			

REMARQUES:

---

**ELEVATION VIEW OF LOCALE**

---

SKETCH IN SIGNIFICANT RUNWAYS, OBSTRUCTIONS, FLIGHT PATH ETC. SHOW IMPORTANT DISTANCES & DIMENSIONS

---


**PLAN VIEW OF LOCALE**

---

SKETCH IN SIGNIFICANT LANDING AREA, OBSTRUCTIONS, AIRCRAFT PATH ETC. SHOW IMPORTANT DISTANCES & DIMENSIONS, AND THE WIND VECTOR.

SEE MAP APPENDIX II.

**APTITUDE À L'ATERRISSAGE BRUTAL – BLESSURES**

2501 IDENTIFICATION		2502 GRAVITÉ DES BLESSURES	2503 AUTOPSIE		2504 RANGÉE DEVANT  ARRIÈRE 2505	2506 DE FACE		
PILOTE			A	MÉDECIN		R	F	AVANT
COPILOTE			B	PATHOLOGISTE		C	S	CÔTÉ
AUTRE MEMBRE DE L'ÉQUIPAGE	F		MORTELLES	C		SPÉCIALISTE - MÉDECIN AÉRONAUTIQUE	M	ARRIÈRE
ÉQUIPAGE DE LA CABINE	S		GRAVES	D		AUTRE		
PASSAGER	M		LÉGÈRES	E		CAM PRÉSENT		
PERSONNE À L'EXTÉRIEUR DE L'AVION	N	AUCUNE						

L'ESPACE CI-DESSOUS EST SUFFISANT POUR PRÉCISER JUSQU'À DIX BLESSURES À LA PERSONNE MENTIONNÉE SUR CETTE PAGE. LA HUITIÈME REVISION "CLASSIFICATION INTERNATIONALE DES MALADIES" SECTION XVII, SERVIRA À DÉTERMINER LA CATÉGORIE DES BLESSURES.

INSCRIRE LE CODE PARTICULIER AINSI QU'UNE DESCRIPTION DES BLESSURES

INSCRIRE À DROITE LE CODE APPROPRIÉ À L'ÉVÉNEMENT QUI A PROVOQUÉ DES BLESSURES.

ÉVÉNEMENT AYANT CAUSÉ DES BLESSURES		
A HEURTÉ L'INTÉRIEUR DE L'AÉRONEF À L'IMPACT		A
A ÉTÉ HEURTÉ PAR DES OBJETS VOLANTS À L'INTÉRIEUR DE L'AÉRONEF		B
BRULURES SEULEMENT		C
BRULURES À LA SUITE D'AUTRES BLESSURES		D
ECRASÉ DANS L'ÉPAVE		E
CONTACT AVEC L'HÉLICE ENTRÉE/ÉCHAPPEMENT		F
CHUTE HORS DE L'AÉRONEF (OU PROJETÉ)		G
HEURTÉ PAR L'AÉRONEF		H
TIRÉ SOUS L'EAU		J
HEURTÉ PAR LE ROTOR PRINCIPAL		K
HEURTÉ PAR LE ROTOR DE QUEUE		L
A HEURTÉ L'INTÉRIEUR DE L'AÉRONEF LORS D'UNE TURBULENCE		M
A ÉTÉ HEURTÉ PAR UNE PIÈCE DÉPLACÉE/STRUCTURE		N

CODE

2507      2508

2509      2510

2511      2512

2513      2514

2515      2516

2517      2518

2519      2520

2521      2522

2523      2524

2525      2526

s.19(1)

**PERSONNEL INFORMATION - PILOT**

PILOT AT CONTROLS 0501	<input checked="" type="checkbox"/>	PILOT-IN-COMMAND	G	INSTRUCTOR	E	NONE
	<input type="checkbox"/>	CO-PILOT	D	SUPERVISORY PILOT	Y	OTHER
	<input type="checkbox"/>	STUDENT	F	BOTH PILOTS		

**PILOT IN COMMAND**

AGE 0502	SEX 0503	SURNAME 0504	INITIALS 0505	LICENCE NUMBER 0506/0507	<input checked="" type="checkbox"/> CANADIAN <input type="checkbox"/> FOREIGN
	<input checked="" type="checkbox"/> M <input type="checkbox"/> F	<b>MARTIN</b>	<b>G.M.</b>	<b>XDA - 867</b>	

STATION OCCUPIED 0508	<input checked="" type="checkbox"/>	PILOT	D	NAVIGATOR	G	OTHER
	<input type="checkbox"/>	SECOND IN COMMAND	E	REST POSITION		
	<input type="checkbox"/>	FLIGHT ENGINEER	F	PASSENGER CABIN		

SPECIAL FUNCTION 0509	<input type="checkbox"/>	NONE	C	COMPANY EXAMINER	E	TECHNICIAN	<input checked="" type="checkbox"/>	OTHER <b>AIR SHOW PARTICIPANT</b>
	<input type="checkbox"/>	INSTRUCTOR	D	MOT EXAMINER	F	STUDENT		

PILOT LICENCES 0510	<input type="checkbox"/>	STUDENT	<input checked="" type="checkbox"/>	AIRLINE TRANSPORT	V	PRIVATE ROTORCRAFT
	<input type="checkbox"/>	PRIVATE	T	GLIDER	W	COMMERCIAL ROTORCRAFT
	<input type="checkbox"/>	COMMERCIAL	U	FREE BALLOON	X	SENIOR COMMERCIAL ROTORCRAFT ENDORSEMENT
	<input type="checkbox"/>	SENIOR COMMERCIAL	I	NONE	Y	AIRLINE TRANSPORT ROTORCRAFT ENDORSEMENT
	<input type="checkbox"/>	OTHER				

TYPE RATING 0511	<input checked="" type="checkbox"/>	YES	X	NO	LAST CHECK ON TYPE 0512	WEEKS
---------------------	-------------------------------------	-----	---	----	----------------------------	-------

INSTRUMENT RATING 0513/0514	<input checked="" type="checkbox"/>	AEROPLANE		BOTH	<input checked="" type="checkbox"/>	CLASS I	LAST CHECK <b>DEC. 11, 1975</b>	F	FLIGHT
	<input type="checkbox"/>	HELICOPTER			2	CLASS II	INSTRUMENT RATING 0515/0516	WEEKS	S

INSTRUCTOR RATING 0517	<input type="checkbox"/>	YES	<input checked="" type="checkbox"/>	NO	CLASS- 0518
---------------------------	--------------------------	-----	-------------------------------------	----	----------------

CLASS RATINGS (Select up to 2) 0519	<input checked="" type="checkbox"/>	AEROPLANE SE LAND	D	AEROPLANE ME SEA	H	HELICOPTER TYPE
	<input checked="" type="checkbox"/>	AEROPLANE ME LAND	AC	AEROPLANE SE LAND & SEA	Y	OTHER
	<input type="checkbox"/>	AEROPLANE SE SEA	BD	AEROPLANE ME LAND & SEA		

ENDORSEMENTS 0520	<input checked="" type="checkbox"/>	NIGHT	B	BLOCK AIRSPACE	A	AEROBATIC	T	TRSA
----------------------	-------------------------------------	-------	---	----------------	---	-----------	---	------

FLYING TIMES (to nearest hour - if unknown complete with X)

	ALL TYPES	THIS TYPE	DUAL THIS TYPE	THIS U/C CONFIG	SINGLE ENGINE	MULTI ENGINE	ACTUAL INSTRUMENT	SIMULATED INSTRUMENT	NIGHT	ROTORCRAFT
TOTAL HOURS	[REDACTED]									
HRS LAST 90 DAYS	[REDACTED]									

HOURS LAST 30 DAYS 0541	HOURS LAST 3 DAYS 0542	HOURS LAST 24 HOURS 0543	DUTY TIME PRIOR TO OCCURRENCE 0544	REST TIME BEFORE DUTY 0545	HOURS AWAKE SINCE LAST REST PERIOD 0546	LANDINGS ON TYPE LAST 90 DAYS (FIXED WING) 0547	TOTAL INSTRUMENT LAST 30 DAYS 0548
			X	X	X	X	X

MEDICAL STATUS 0549	<input checked="" type="checkbox"/>	VALID MEDICAL WITH NO WAIVERS/LIMITATIONS	2	VALID MEDICAL WITH WAIVERS/LIMITATIONS	3	NON-VALID MEDICAL
------------------------	-------------------------------------	---	---	--	---	-------------------

FLYING SCHOOL	ATC LICENCE NUMBER	CODE 0550
---------------	--------------------	--------------

PRIME INSTRUCTOR - NAME 0551/0552	<input type="checkbox"/>	FULL-TIME INSTRUCTOR AT SCHOOL	DUAL LAST 6 MONTHS	DUAL LAST YEAR
	<input type="checkbox"/>	PART-TIME INSTRUCTOR AT SCHOOL		
FLIGHT TEST EXAMINER - NAME & LICENCE 0553/0554	<input type="checkbox"/>	MOT	C	COMPANY
	<input type="checkbox"/>	DFTE	0555	0556

NOTES:

**APTITUDE À L'ATTERRISSAGE BRUTAL (SYSTÈMES ET PROCÉDURES)**

SYSTÈMES/ PROCÉDURES GÉNÉRALES	SYSTÈMES/PROCÉDURES SPÉCIFIQUES	E X I G E	À BORD OU DISPONIBLE			UTILISÉ PORTÉ			A CAUSÉ/ CONTRIBUÉ AUX BLESSURES			A MINIMISÉ/ EMPÊCHÉ LES BLESSURES			A FAIT DÉFAUT		
			OUI	NON	?	OUI	NON	?	OUI	NON	?	OUI	NON	?	OUI	NON	?
SYSTÈME D'ATTACHES DE L'ÉQUIPAGE	CEINTURES DE SÉCURITÉ 2401/2402																
	BRETELLES DE SÉCURITÉ 2403/2404																
	COURROIE D'ATTACHE DE CEINTURE 2405/2406																
	ROULEAU D'INERTIE 2407/2408																
	GUIDE DE BRETELLES 2409/2410																
SYSTÈMES D'ATTACHES DES PASSAGERS	CEINTURES DE SÉCURITÉ 2411/2412																
	BRETELLES DE SÉCURITÉ 2413/2414																
	COURROIE D'ATTACHE DE CEINTURE 2415/2416																
	ROULEAU D'INERTIE 2417/2418																
	GUIDE DE BRETELLES 2419/2420																
SIÈGES	SIÈGE/PILOTE 2421/2422																
	SIÈGE/COPILOTE 2423/2424																
	PILOTE EXAMINATEUR 2425/2426																
	SIÈGE/PASSAGER 2427/2428																
ENVIRONNEMENT IMMÉDIAT DU POSTE DE PILOTAGE	DESSIN 2429/2430																
	LOCALISATION 2431																
	ATTACHES 2432/2433																
ENVIRONNEMENT IMMÉDIAT DE LA CABINE	DESSIN 2434/2435																
	LOCALISATION 2436																
	ATTACHES 2437/2438																
COMPARTIMENT À BAGAGES	ENDROIT 2439																
	ATTACHES 2440/2441																
MARCHANDISES	ENDROIT 2442																
	ATTACHES 2443/2444																
ÉVACUATION D'URGENCE	PORTES DE L'AÉRONEF 2445/2446																
	SORTIES DE SECOURS 2447/2448																
	RAMPE D'ÉVACUATION 2449/2450																
	CÂBLES 2451/2452																
	ÉCLAIRAGE DE SORTIE 2453/2454																
	ÉCLAIRAGE DE SECOURS INTÉRIEUR 2455/2456																
	SURVEILLANCE 2457/2458																
	AVERTISSEMENT 2459/2460																
AMERRISSAGE	AUTRE 2461/2462																
	GILET DE SAUVETAGE – ACCESSIBILITÉ 2463/2464																
	GILET DE SAUVETAGE – TYPE 2465/2466																
	RADEAU DE SAUVETAGE – ACCESSIBILITÉ 2467/2468																
RADEAU DE SAUVETAGE – TYPE 2469/2470																	

**AIRCRAFT INFORMATION**

MANUFACTURER <b>DE HAVILLAND</b>		MODEL <b>DH 83C</b>		TOTAL AIRFRAME TIME <b>2910</b>		TSO <b>44</b>				
0800		0801		0802	HRS	0803	HRS			
AIRCRAFT WEIGHT 0804	<input checked="" type="checkbox"/> A	AT OR BELOW AUTHORIZED WEIGHT		CENTRE OF GRAVITY 0805	A	EXCEEDED FORWARD LIMIT				
	<input type="checkbox"/> B	ABOVE AUTHORIZED WEIGHT			B	EXCEEDED AFT LIMIT				
CALCULATED AUW <b>1954.2</b>	C OF G POSITION			C OF G PERMISSIBLE RANGE						
	OR <b>16.30</b> INCHES			OR <b>12.0</b> IN TO <b>17.75</b> IN						
0806/0807	<input checked="" type="checkbox"/> AFT OF DATUM			TO						
	FORWARD OF DATUM			FORWARD OF DATUM						
FUEL TYPE 0808	<input checked="" type="checkbox"/> C	80/87	L	AUTOMOBILE GASOLINE	G	JP-3	J	JP-6	Y	OTHER
	<input type="checkbox"/> D	100/130	E	KEROSENE	H	JP-4	K	MIXED FUEL		
	<input type="checkbox"/> A	115/145	F	JP-1	I	JP-5	Z	UNKNOWN		
	<input type="checkbox"/> B									

**POWERPLANT & PROPELLER INFORMATION**

T S O HRS	NO. 1 ENGINE 0809	NO. 2 ENGINE 0810	NO. 3 ENGINE 0811	NO. 4 ENGINE 0812	NO. 1 PROP. 0813	NO. 2 PROP. 0814	NO. 3 PROP. 0815	NO. 4 PROP. 0816	
AIRCRAFT EQUIPPED TO MINIMUM IFR STANDARD				<input checked="" type="checkbox"/> Y	YES				
AIRCRAFT EQUIPPED FOR PRECISION APPROACHES 0817	A	CAT I		C	CAT III A		E	CAT III C	
	B	CAT II		D	CAT III B				
RADAR (AIRBORNE WEATHER) 0818	A	SERVICEABLE NOT IN OPERATION		C	OPERATED SATISFACTORILY		E	NOT INSTALLED	
	B	UNSERVICEABLE		D	OPERATED UNSATISFACTORILY		F	INSTALLED OPERATION NOT REPORTED	
STALL WARNING/PREVENTION SYSTEM 0819	A	WARNING INDICATOR INSTALLED		D	WARNING INDICATOR & STICKPUSHER INSTALLED		WARNING INDICATOR 0820	V	VISUAL
	C	STICKPUSHER INSTALLED		B	WARNING INDICATOR OR STICKPUSHER NOT INSTALLED			A	AURAL

**AIRCRAFT EQUIPMENT & SYSTEMS**

AVAIL	IN USE	DESCRIPTION	AVAIL	IN USE	DESCRIPTION
		VHF COMMUNICATION 0821			AUTOPILOT 0838
		HF COMMUNICATION 0822			ANTI-COLLISION LIGHTS 0839
		UHF COMMUNICATION 0823			FLIGHT CREW OXYGEN 0840
		VOR 0824			PASSENGER OXYGEN 0841
		ADF 0825			AUXILIARY POWER 0842
		TACAN 0826			RADAR ALTIMETER 0843
		DME 0827			GROUND PROXIMITY WARNING 0844
		ILS COMPLETE SYSTEM 0828			ALTITUDE ALERTING 0845
		ILS LOCALIZER ONLY 0829			COLLISION AVOIDANCE 0846
		ILS GLIDE PATH ONLY 0830			AREA NAVIGATION 0847
		TRANSPONDER 0831			VLF NAVIGATION 0848
		TRANSPONDER (MODE C) 0832			MLS 0849
		ENGINE ANTI-ICE/DE-ICE 0833			HEAD-UP DISPLAY 0850
		PROPELLER DE-ICE 0834			INERTIAL NAVIGATION 0851
		WINDSHIELD ANTI-ICE/DE-ICE 0835			INTEGRATED FLIGHT DATA 0852
		AIRFRAME ANTI-ICE/DE-ICE 0836			TURBULENCE DETECTION 0853
		DUAL CONTROLS 0837			

**AIRCRAFT CONFIGURATION AT IMPACT**

LANDING GEAR 0854	<input checked="" type="checkbox"/> FIXED	U	UP	T	TRANSIT	D	DOWN	AMPHIBIOUS FLOATS-WHEELS 0855				U	UP	D	DOWN
FLAPS 0856	<input checked="" type="checkbox"/> NONE			U	UP	P	PARTIAL	D	DOWN						
POWER 0857	<input checked="" type="checkbox"/> NONE	P	PARTIAL	<input checked="" type="checkbox"/> FULL	R	REVERSE		A	ASSYMETRIC						
MIXTURE 0858	<input checked="" type="checkbox"/> RICH	L	LEAN	A	AUTO		C	IDLE CUT-OFF							
CARB HEAT 0859	H	HOT	<input checked="" type="checkbox"/> COLD	P	PARTIAL		<input checked="" type="checkbox"/> X	NOT INSTALLED							
INDUCTION HEAT 0860	H	HOT	C	COLD	P	PARTIAL		<input checked="" type="checkbox"/> X	NOT INSTALLED						

**ENQUÊTE**

ENQUÊTE PAR	NOMBRE D'ENQUÊTEURS		AIDE REÇUE DE DNHW		AIDE REÇUE DU LAB. DE L'ADM. CENT		ENQUÊTE PAR COURRIER	
	CA1	T1	2103		2104		2105	
			OUI		OUI		PARTIELLEMENT	
	2101	2102	NON		NON		NON	
AUTRE AIDE								
2106								

PAGES PRÉSENTÉES	1	2	3	4	5	6	7	8	9	10	11	C1	C2	C3	C4
	12	13	14	15	16	17	18	19	20	21	M1	M2	M3		

DOCUMENTS ANNEXES	ENTREVUES 2107	A	ÉQUIPAGE DE VOL	E	PERSONNEL D'ENTRETIEN	K	MÉDECIN PERSONNEL
		B	TÉMOINS OCCULAIRES	F	ÉPOUX/ÉPOUSE	L	DIRECTION
		C	INSTRUCTEUR/PILOTE INSPECTEUR	G	PASSAGERS		
		D	ÉQUIPAGE DE LA CABINE	H	EXPÉDITEUR		
	RAPPORTS 2108	A	MATÉRIAUX DE LABO	D	MÉDICAL	G	CORONER
		B	TECHNIQUES	E	DCIEM	H	POLICE
		C	ENREGISTREUR DE DONNÉES	F	PATHOLOGISTE	K	LABO DE CRIMINOLOGIE
	DONNÉES D'OPÉRATION 2109	A	PERFORMANCE	D	TRANSCRIPTION DE RUBAN ATS	G	LISTE DES BLESSÉS
		B	CONDITIONS MÉTÉOROLOGIQUES	E	TRANSCRIPTION DE RUBAN CVR		
		C	PHOTOGRAPHIES	F	CARTES ET GRAPHIQUES		

ENQUÊTE	TEMPS ÉCOULÉ ENTRE L'ACCIDENT ET L'ARRIVÉE DE L'ENQUÊTEUR SUR LES LIEUX	TEMPS ÉCOULÉ ENTRE L'ACCIDENT ET LA RÉCEPTION DE LA NOTIFICATION PAR LA RÉGION
	2110 Heures	2111 Heures

SIGNATURE DE L'ENQUÊTEUR

---

OBSERVATIONS DU SURINTENDANT RÉGIONAL

SURINTENDANT RÉGIONAL

DATE

REMARQUES:

**METEOROLOGICAL INFORMATION**

WEATHER BRIEFING	<input checked="" type="checkbox"/>	BRIEFING AVAILABLE & PROVIDED	N	BRIEFING FACILITIES NOT USED		
	<input type="checkbox"/>	BRIEFING NOT AVAILABLE	Z	NOT REPORTED		
1001						
BRIEFING AGENCY	A	NONE	D	COMPANY FACILITY	G	OTHER OBSERVER
	B	ACCREDITED FORECASTER	E	OTHER PILOT	<input checked="" type="checkbox"/>	OTHER <b>ALL PILOTS BRIEFED PRIOR TO FLYING IN THE AIR SHOW.</b>
	C	ACCREDITED BRIEFER	F	SELF BRIEFING		
1002						
WEATHER VS FORECAST	<input checked="" type="checkbox"/>	SUBSTANTIALLY CORRECT	E	CONSIDERABLY WORSE THAN FORECAST		
	<input type="checkbox"/>	CONSIDERABLY BETTER THAN FORECAST				
1003						

**WEATHER CONDITIONS AT SITE OF OCCURRENCE**

WIND DIRECTION	328°	RELATIVE BEARING OF WIND TO TRACK OF AIRCRAFT 	CLOUD BASE HEIGHT	TEMPERATURE	DEWPOINT
1004	°M		1007	1010	1013
WIND SPEED	20 Gusting 26		1008	1011	1014
1005	Knots	CALM	1009	1012	1014
			1006		
			1007	1010	1013
			1008	1011	1014
			1009	1012	1014

SKY CONDITION	A	CLEAR	E	BROKEN/LOWER SCATTERED	I	OBSCURED
	<input checked="" type="checkbox"/>	SCATTERED ABOVE 1000'	G	OVERCAST/LOWER SCATTERED	H	PARTIALLY OBSCURED
	C	SCATTERED BELOW 1000'	F	OVERCAST		
	1015	D	BROKEN			

RESTRICTING PHENOMENA	A	DUST	F	SMOKE	K	PRECIPITATION
	B	FOG	G	BLOWING DUST	<input checked="" type="checkbox"/>	NONE
	C	SHALLOW FOG	H	SANDSTORM	Y	OTHER
	1016	E	FREEZING FOG	I	BLOWING SNOW	

TYPE OF PRECIPITATION (Select up to 2)	C	DRIZZLE	F	SNOW	I	THUNDERSHOWERS
	D	RAIN	G	SNOW GRAINS/ICE PELLETS	<input checked="" type="checkbox"/>	NONE
	E	RAIN SHOWERS	H	SNOW SHOWERS	Y	OTHER
	1017	A	HAIL	J	FREEZING DRIZZLE	
	B	SLEET	K	FREEZING RAIN		

SIGNIFICANT WEATHER (Select up to 3)	A	TURBULENCE IN CLOUD	H	VARIABLE CLOUD BASE	C	TORNADO
	B	CLEAR AIR TURBULENCE	M	LIGHT PRECIPITATION	D	HURRICANE, TYPHOON
	G	SEVERE LINE SQUALL	L	HEAVY PRECIPITATION	E	MOUNTAIN WAVE
	J	WIND VARIABLE	R	THUNDERSTORM	S	NOT SIGNIFICANT
	<input checked="" type="checkbox"/>	WIND GUSTY	Q	SEVERE ICING	Y	OTHER
	1018	K	WIND GUSTY & VARIABLE	N	TEMPERATURE BELOW 0°C	

**CONDITIONS AT POINT OF FIRST IRREGULARITY OF FLIGHT (If applicable)**

AIRCRAFT ALTITUDE ASL	551	TEMPERATURE	17 °C	RESTRICTING PHENOMENA	SIGNIFICANT WEATHER
1019		1022			
GENERAL TERRAIN ELEV. ASL	251	DEWPOINT	05 °C	1025	1027
1020		1023		PRECIPITATION	DEGREE OF TURBULENCE
AIRCRAFT HEIGHT AGL	300	DIFFERENCE BETWEEN DEWPOINT & TEMPERATURE	12 °C	1026	1028
1021		1024			L LIGHT
					M MODERATE
					S SEVERE

NOTES:

---

## ANALYSE DE L'ÉVÉNEMENT

---

**POURQUOI** — DÉCRIRE DANS QUELLE MESURE L'ENVIRONNEMENT, L'AÉRONEF ET LE PERSONNEL EN CAUSE ONT INFLUÉ SUR L'ÉVÉNEMENT.  
ÉNUMÉREZ LES FACTEURS AYANT CAUSÉ L'INCIDENT OU INFLUÉ SUR LES CIRCONSTANCES QUI ONT ENTOURÉ CE DERNIER.

**WRECKAGE & IMPACT INFORMATION** 1101 WRECKAGE RECOVERED  YES  NO


1102	TYPE OF TERRAIN	A	MOUNTAINOUS	C	ROLLING		
		B	HILLY	<input checked="" type="checkbox"/>	LEVEL/FLAT		
1103	SURFACE CONDITION GENERAL	3	HARD	H	TREE COVERED	<input checked="" type="checkbox"/>	WATER
		F	ROCKY	I	BUILT-UP (CITY-DENSE)	N	SWAMP
		G	SANDY	M	BUILT-UP (SUBURBAN-COUNTRY-SPARSE)	Y	OTHER
1104	SURFACE CONDITION SPECIFIC	O	PAVED	S	MUD, WET SOIL	1	SNOW
		P	LOOSE	<input checked="" type="checkbox"/>	HIGH WAVES	2	ICE
		Q	COMPACT	U	SWELLS	Y	OTHER
		J	CULTIVATED	V	CALM/GLASSY WATER		
		R	LOW VEGETATION/GRASS	E	FROZEN GROUND		

ELEVATION OF FIRST POINT OF IMPACT 1105	LENGTH OF WRECKAGE TRAIL 1106	IMPACT ANGLE (RELATIVE TO TERRAIN/OBJECT) 1107
251 Feet	N/A Feet	 Degrees
76.5 Metres	 Metres	

- CIRCLE THE SILHOUETTES WHICH MOST CLOSELY DESCRIBE ANGLE OF GROUND CONTACT
- DRAW A SQUARE AROUND SILHOUETTES TO DESCRIBE ATTITUDE OF AIRCRAFT AT REST

REAR ELEVATION 1108

STARBOARD ELEVATION 1109



AERODROME PROXIMITY 1112	A	ON AIRPORT	F	WITHIN .4 Km	<input checked="" type="checkbox"/>	WITHIN 4.8 Km	DIRECTION FROM AERODROME TO SCENE OF OCCURRENCE  290° °M 1113
	B	ON SEAPLANE BASE	G	WITHIN .8 Km	<input type="checkbox"/>	WITHIN 6.4 Km	
	C	ON HELIPORT	H	WITHIN 1.2 Km	<input type="checkbox"/>	WITHIN 8 Km	
	D	ON/BARGE/SHIP/PLATFORM	I	WITHIN 1.6 Km	<input type="checkbox"/>	BEYOND 8 Km	
	E	IN CIRCUIT	J	WITHIN 3.2 Km	<input type="checkbox"/>		

COMPLETE P13 IF AIRCRAFT WAS OPERATING INTO OR OUT OF AN AERODROME WITHIN 8 KM

OFF AIRPORT OR WATER AREA USED FOR TAKEOFF/LANDING

LENGTH 1114	ft	METRES	WIDTH 1115	ft	METRES	
WATER CONDITIONS (Select up to 2), 1116	A	GLASSY	C	LIGHT SWELL	E	HEAVY SWELLS
	B	WAVES < 0.3 metres	D	WAVES .3m to 1m.	F	WAVES > 1 metre
WATER SURFACE HAZARDS (Select up to 2) 1117	A	SAND BAR	C	SUBMERGED OBSTRUCTION	E	BOATS
	B	SHOAL	D	FLOATING OBJECTS	Y	OTHER
HAZARDS BORDERING AREA 1118	A	HIGH GROUND	D	FENCE	HEIGHT ABOVE SURFACE	
	B	WIRES/POLES	E	BUILDINGS		
	C	TREES	F	OTHER		

NOTES:

**ÉPANDAGE AÉRIEN**

1701	GENRE D'OPÉRATIONS		A	PULVÉRISATION DE CULTURES	F	ENGRAIS (LIQUIDE)	K	ARROSAGE DE VILLES	Q	CHASSE AUX OISEAUX		
	B	PULVÉRISATION-AUTRE	G	DÉFOLIATION (POUDRE)	L	AGITATION D'ARBRES	R	ESSAI				
	C	ENSEMENCEMENT DE CULTURES	H	DÉFOLIATION (LIQUIDE)	M	MESURES CONTRE LE GEL	S	TRANSBORDEMENT				
	D	ENSEMENCEMENT DE FORÊTS	I	ARROSAGE DE CULTURES	N	FAIRE TOMBER LES FRUITS DES ARBRES	T	PRATIQUE				
	E	ENGRAIS (POUDRE)	J	ARROSAGE DE FORÊTS	P	RELEVÉ DE RÉGION	W	CONTRÔLE D'INCENDIE				
1702	GENRE DE CULTURES/TERRAIN		A	HARICOTS	G	VERGERS	M	PÂTURAGE	S	ÉPINARDS		
	B	TRÈFLE	H	RAISINS	N	POIS	T	FRAISES				
	C	MAÏS	I	CHAMPS DE GRAINS	P	PATATES	U	TABAC				
	E	LIN	J	LAITUE	Q	RIZ	V	TOMATES				
	F	FORÊT/ARBRES	L	DÉMOUSTICATION	R	SAUGE	Y	AUTRE				
	PRODUIT CHIMIQUE UTILISÉ 1703		A	SEC-TOXIQUE	B	SEC-NON TOXIQUE	C	LIQUIDE-TOXIQUE	D	LIQUIDE-NON TOXIQUE		
INFLUENCE TOXIQUE SUR LE PILOTE 1704		A	NON AFFECTÉ		B	AFFECTÉ EN VOL		C	AFFECTÉ AU SOL AVANT LE VOL			
1705	LE PILOTE A ÉTÉ EXPOSÉ DURANT		A	MOINS DE 15 MIN.	D	MOINS DE 2 HEURES	G	MOINS DE 5 HEURES				
	B	MOINS DE 30 MIN.	E	MOINS DE 3 HEURES	H	PLUS DE 5 HEURES						
	C	MOINS D'UNE HEURE	F	MOINS DE 4 HEURES								
1706	ANTI-TOXINES		A	DISPONIBLES ET UTILISÉES		B	DISPONIBLES-NON UTILISÉES		C	NON DISPONIBLES		
1707	CEINTURES DE SÉCURITÉ		A	NON ATTACHÉES	B	ATTACHÉES CORRECTEMENT	C	MAL ATTACHÉES	D	DÉFECTUEUSES		
1708	ÉQUIPEMENT RESPIRATOIRE		A	DISPONIBLE-UTILISÉ		B	DISPONIBLE NON UTILISÉ		C	NON DISPONIBLE		
1709	CASQUE PROTECTEUR		A	DISPONIBLE-UTILISÉ		B	DISPONIBLE NON UTILISÉ		C	NON DISPONIBLE		
1710	VÊTEMENTS SPÉCIAUX		GANTS 1711			LUNETTES PROTECTRICES 1712		GARNITURE ANTICHOC DU POSTE DE PILOTAGE		GARNITURE ANTICHOC 1714		
	A	UTILISÉS	A	UTILISÉS	A	UTILISÉES	A	INSTALLÉE	A	INSTALLÉE		
B	NON UTILISÉS	B	NON UTILISÉS	B	NON UTILISÉES	B	NON-INSTALLÉE	B	NON INSTALLÉE			
1715	EMPLACEMENT DU RÉSERVOIR/CHUTE		A	À L'AVANT DU PILOTE	C	AILES	E	CÔTÉS	Y	AUTRE		
	B	À L'ARRIÈRE DU PILOTE	D	VENTRE	F	REPLI À L'ÉLINGUE						
1716	OBSTACLES Choisir 2 au plus		A	ARBRES	C	CLÔTURES	E	PYLONES ÉLECTRIQUES	Y	AUTRE		
	B	FILS/POTEAUX	D	BÂTIMENTS	F	AUCUN						
1717	TERRAIN SOUS TRAITEMENT		A	UNI-PLAT	C	ACCIDENTÉ	E	MARÉCAGEUX/EAU				
	B	ONDULÉ	D	MONTAGNEUX	F	ARBRES ABONDANTS						
1718	VOL PAR RAPPORT AU VENT		A	VENT TRAVERSIER	B	VENT DEBOUT	C	VENT ARRIÈRE	D	CALME		
1719	PROCÉDURE DE VIRAGE		A	DÉBUT D'UN VIRAGE CONVENTIONEL			C	DEUXIÈME 1/3 DU VIRAGE				
	B	PREMIER 1/3 DU VIRAGE	D	DERNIER 1/3 DU VIRAGE								
1720	CONTRÔLE DES RÉCOLTES HEURES DE VOL DU PILOTE				ALTITUDE - ZONE SOUS TRAITEMENT 1721				PRODUITS CHIMIQUES UTILISÉS 1722			
REMARQUES:												

**SURVIVAL DATA**

1401 SURVIVABILITY	<input checked="" type="checkbox"/> A	SURVIVABLE	C	NON SURVIVABLE	1402 POST CRASH ESCAPE	<input checked="" type="checkbox"/> A	UNHAMPERED	C	NOT APPLICABLE	
	B	PARTIALLY SURVIVABLE	D	AIRCRAFT MISSING		B	WITH DIFFICULTY	D	UNDETERMINED	
1403 IMPACT DAMAGE-AIRCRAFT WITHOUT PASSENGER CABIN	A	EXTREME	C	MODERATE	E	NONE				
	B	SEVERE	D	MINOR						
1404 IMPACT DAMAGE-AIRCRAFT WITH PASSENGER CABIN	1404 COCKPIT		1405 FORWARD CABIN		1406 CENTRE CABIN		1407 AFT CABIN			
	A	EXTREME	<input checked="" type="checkbox"/> A	EXTREME	A	EXTREME	A	EXTREME		
	B	SEVERE	B	SEVERE	B	SEVERE	B	SEVERE		
	<input checked="" type="checkbox"/> C	MODERATE	C	MODERATE	C	MODERATE	C	MODERATE		
	D	MINOR	D	MINOR	D	MINOR	D	MINOR		
E	NONE	E	NONE	E	NONE	E	NONE			
1408 SEATING CONFIGURATION	<input checked="" type="checkbox"/> A	FORWARD FACING	C	COMBINATION FORWARD & REAR						
	B	REAR FACING	D	OTHER						
1409 SEAT BELT SIGN	<input checked="" type="checkbox"/> A	NOT INSTALLED	A	ON	B	OFF				
SHOULDER HARNESS	1410 PILOT			1411 CO-PILOT						
	A	INSTALLED/USED/HELD	C	INSTALLED/NOT USED	A	INSTALLED/USED/HELD	C	INSTALLED/NOT USED		
B	INSTALLED/USED/FAILED	<input checked="" type="checkbox"/> C	NOT INSTALLED	B	INSTALLED/USED/FAILED	D	NOT INSTALLED			
1412 EVACUATION ASSISTANCE BY GROUND RESCUE GROUPS	<input checked="" type="checkbox"/> A	RENDERED EFFECTIVELY	C	AVAILABLE-UNABLE TO RENDER ASSISTANCE						
	B	ARRIVED TOO LATE	X	NOT AVAILABLE						
1413 NUMBER OF SEATS FAILED	ONE		1414 NUMBER OF SEAT BELTS FAILED	NIL		1415 FATALITIES FROM BURNS	0		1416 FATALITIES FROM TOXIC FUMES	0
1417 MEANS OR METHOD OF EXIT (Select up to 4)	<input checked="" type="checkbox"/> A	MAIN DOOR FORWARD	E	AUXILIARY DOOR AFT	I	COCKPIT WINDOW				
	B	MAIN DOOR AFT	F	AUXILIARY DOOR OTHER	J	OTHER WINDOW				
	C	MAIN DOORS FORE & AFT	G	MAIN & AUXILIARY DOORS	K	BREAK IN FUSELAGE				
	D	AUXILIARY DOORS FORWARD	H	EMERGENCY WINDOW EXITS	L	THROWN CLEAR				
1418 EVACUATION TIME	A	0-30 SEC	D	91-120 SEC	G	4-5 MIN	1419 NUMBER OF OCCUPANTS EVACUATED	TWO	1420 NUMBER OF OCCUPANTS NOT EVACUATED	0
	B	31-60 SEC	E	2-3 MIN	H	OVER 5 MIN				
	C	61-90 SEC	<input checked="" type="checkbox"/> F	3-4 MIN	Z	UNKNOWN				
1421 CHUTE/SLIDE	A	AVAILABLE USED EFFECTIVELY	B	AVAILABLE-USED-MALFUNCTIONED	C	AVAILABLE-NOT USED	<input checked="" type="checkbox"/> D	NOT AVAILABLE		
	1422 ROPE		1423 LADDER		1424 EMERGENCY EXITS		1425 EMERGENCY LIGHTS			
A	AVAILABLE-USED	A	AVAILABLE-USED	A	USED-FUNCTIONED NORMALLY	A	ENERGIZED PROPERLY			
B	AVAILABLE-NOT USED	B	AVAILABLE-NOT USED	B	NOT USED-FUNCTIONED NORMALLY	B	DID NOT ENERGIZE			
<input checked="" type="checkbox"/> C	NOT AVAILABLE	<input checked="" type="checkbox"/> C	NOT AVAILABLE	C	WOULD NOT OPEN	<input checked="" type="checkbox"/> D	NOT AVAILABLE			
1426 DITCHING-WATER CONDITIONS & AIRCRAFT INTEGRITY	OPEN SEA		CALM SURFACE		AIRCRAFT BROKE UP					
	SHELTERED AREA		ROUGH SURFACE		AIRCRAFT REMAINED INTACT					
1427 DITCHING-AIRCRAFT SANK/STAYED AFLOAT	A	SANK IMMEDIATELY (INSUFFICIENT TIME FOR EVACUATION)								
	B	STAYED AFLOAT-SHORT PERIOD OF TIME (PARTIAL EVACUATION)								
	C	STAYED AFLOAT-EXTENDED PERIOD (COMPLETE EVACUATION)								
	D	STAYED AFLOAT-EXTENDED PERIOD AFTER EVACUATION								

NOTES:

**DONNÉES CONCERNANT L'INCENDIE**

L'INCENDIE A DÉBUTÉ 1501/1502		A	EN VOL	C	PLUS D'UNE MINUTE APRÈS L'IMPACT	E	INDÉTERMINÉ							
		B	MOINS DE 1 MINUTE APRÈS L'IMPACT	D	DURANT LE RAVITAILLEMENT EN CARBURANT	Y	AUTRE							
INDICES D'INCENDIE 1503		A	SYSTÈME D'ALERTE	C	VISUEL	E	EXPLOSION	Y	AUTRE					
		B	AUTRES INSTRUMENTS	D	ODEUR	F	COMMUNICATION EXTÉRIEURE							
DOMMAGES CAUSÉS PAR LE FEU 1504		AUCUN	C	0-25%	B	26-50%	B	51-75%	A	76-100%				
FONCTIONNEMENT DU SYSTÈME D'ALERTE DE L'AÉRONEF 1505		▶			A	A BIEN FONCTIONNÉ		C	NON INSTALLÉ					
		B	N'A PAS FONCTIONNÉ			D	INCONNU							
ENDROIT OU L'INCENDIE A DÉBUTÉ 1506	GENERAL	A	GROUPES PROPULSEUR	D	POSTE DE PILOTAGE	G	EMPENNAGE	J	COMPARTIMENT DES CIRCUITS					
		B	SOUTE AUX BAGAGES	E	PUIT DES ROUES	H	TOILETTE	Y	AUTRE					
		C	CARLINGUE	F	AILE	I	GROUPE ÉLECTROGÈNE							
	EXACT	A	CIRCUIT D'OXYGÈNE	D	BOÎTE DE RACCORDEMENT	G	SECTION DE LA TRANSM.	L	TUYAU D'ÉCHAPPEMENT					
		B	TABLEAU DE BORD	E	COMPARTIMENT DU GROUPE RÉCHAUFFEUR	H	JATO	M	PNEUS					
		C	COMPARTIMENT DES ACCUMULATEURS	F	SECTION AVIONIQUE	K	FREIN DE ROUES	Y	AUTRE					
MATIÈRES COMBUSTIBLES 1508	A	CARBURANT PRINCIPAL	F	ISOLEMENT ÉLECTRIQUE			M	CARGAISON						
	B	CARBURANT AUXILIAIRE	G	MATÉRIAUX D'ACOUSTIQUE			N	MATÉRIAUX EXTÉRIEURS						
	C	LIQUIDE HYDRAULIQUE	H	MÉTAL			P	INDÉTERMINÉ						
	D	HUILE MOTEUR	K	EXPLOSIFS			Y	AUTRE						
	E	HUILE TRANSMISSION	L	CAPITONNAGE										
SOURCE DE L'INFLAMMATION 1509	A	GAZ D'ÉCHAPPEMENT	E	SOUS-SYSTÈMES DE L'AÉRONEF			K	COURT CIRCUIT						
	B	ÉTINCELLES (FRICTION DÉRAPAGE)	F	OCCUPANTS DE L'AÉRONEF (EX. CIGARE ALLUMÉ)			L	ÉCLAIRS						
	C	ÉTINCELLES ÉLECTRIQUES	G	CARGAISON			M	ÉLECTRICITÉ STATIQUE						
	D	SURFACES BRULANTES (CONDUITS D'ÉCHAPPEMENT)	H	EXPLOSIFS			Y	AUTRE						
SYSTÈME D'EXTINCTEURS MANUELS 1510	A	ACTIVITÉ-EFFICACE (DANS L'ENDROIT CHOISI)	C	ACTIVITÉ-DÉFECTUEUX DANS L'ENDROIT CHOISI			E	NON INSTALLÉ						
	B	ACTIVITÉ-DÉFECTUEUX	D	NON ACTIVITÉ										
DISPOSITIF DE NEUTRALISATION GÉN. 1511	A	DISPONIBLE, A FONCTIONNÉ EFFICACEMENT	B	DISPONIBLE-INEFFECTIF			C	NON INSTALLÉ						
SYSTÈME D'EXTINCTEURS/ AGENTS UTILISÉS	ÉQUIPEMENT FIXE 1512	A	CO <sub>2</sub> BIOXYDE DE CARBONE	C	DB DIBROMODI-FLUOROMÉTHANE			E	MB - BROMURE DE MÉTHYLE					
		B	CB <sub>2</sub> CHLOROBROMÉTHANE	D	BT BROMO-FLUOROMÉTHANE			Y	AUTRE					
	ÉQUIPEMENT PORTATIF 1513	A	CO <sub>2</sub> BIOXYDE DE CARBONE	C	SOLUTIONS D'EAU			E	TÉTRACHLORURE DE CARBONE					
		B	CB <sub>2</sub> CHLOROBROMÉTHANE	D	PRODUIT CHIMIQUE SEC			Y	AUTRE					
CARBURANT ET HUILE À BORD	CARBURANT	AU DÉCOLLAGE		À LA PREMIÈRE IRRÉGULARITÉ			AU MOMENT DE L'INCIDENT							
	Kg	1514		1515		1516								
	HUILE													
	Litres	1517		1518		1519								
DONNÉES SUR LA PERTE DE LIQUIDES 1520	A	BRIS DES CANALISATIONS DE CARBURANT	C	BRIS DES CANALISATIONS HYDRAULIQUES			E	PERTE D'HUILE MOTEUR						
	B	BRIS DU COMPARTIMENT DE CARBURANT	D	PERTE D'HUILE TRANSMISSION			Y	AUTRE						
AÉRONEF DOTÉ DE PROTECTION CONTRE L'IMPACT ▶				COMPARTIMENT D'HUILE 1521		Y	OUI	X	NON	CANAL. DE CARB. 1522	Y	OUI	X	NON
AMPLEUR DE L'INCENDIE – POUR S'ÉLOIGNER DU FEU LES OCCUPANTS ÉURENT À PARCOURIR 1523				Mètres		DISTANCE AU PLUS PROCHES APPAREILS DESTINÉS À COMBATTRE LES INCENDIES 1524				Km				
INCENDIE CONTRÔLÉ EFFICACEMENT ▶		TEMPS ÉCOULÉ – DE L'ACCIDENT À L'ALERTE 1525		Min.		TEMPS ÉCOULÉ – DE L'ACCIDENT AU CONTRÔLE DE L'INCENDIE 1526				Min.				
INCENDIE NON CONTRÔLÉ EFFICACEMENT ▶		TEMPS ÉCOULÉ – DE L'ACCIDENT À L'ALERTE 1527		Min.		TEMPS ÉCOULÉ – DE L'ACCIDENT À L'ARRIVÉE SUR LES LIEUX 1528				Min.				
ÉVIDENCE DE PRODUITS TOXIQUES ▶				1529		OUI		X	NON					
ÉMANATIONS DE GAZ TOXIQUES 1530	A	HCl CHLORURE D'HYDROGÈNE	E	NO <sub>2</sub> BIOXYDE D'AZOTE			K	PHOSGÈNE						
	B	SO <sub>2</sub> BIOXYDE DE SOUFRE	F	CYANURES			L	FLUORURE D'HYDROGÈNE						
	C	BENZINE	G	CHLORE			Y	AUTRE						
	D	HYDROCARBURES NON SATURÉS	H	ARSINE										

---

## ANALYSIS OF OCCURRENCE – DESCRIPTION

---

### – WHAT – A DETAILED DESCRIPTION OF THE CIRCUMSTANCES OF THE OCCURRENCE

At approximately 14:15 hours EDT, September 5th, 1976, a DeHavilland model DH-83C (Fox Moth) aircraft, CF-DJB, struck the surface of Lake Ontario in a nosedown, right wing low attitude, in a spin, approximately 30 to 50 feet west of the West island off Ontario Place in the Toronto Harbour. The pilot and one passenger were seriously injured and the aircraft substantially damaged as a result of the accident.

The pilot was participating in the 1976 Canadian International Airshow held at the water front of the Canadian National Exhibition. The aircraft had departed from the Toronto Island Airport and had proceeded in a westerly direction, entering at about the mid stage area of the show, at which time the pilot commenced a planned 360° turn to the right at an altitude of approximately 300 feet above the water surface. As the aircraft turned through approximately 90° of the turn the nose pitched down and the aircraft entered a spin to the right. The aircraft continued to spin with the engine developing high power and struck the water surface while on a north westerly heading and came to rest right side up in the water with the nose and cabin area submerged in approximately 10 to 15 feet of water.

The pilot escaped from the cockpit area of the aircraft on his own and was able to advise the rescue personnel that a passenger was still trapped in the cabin area of the aircraft, at which time a Toronto Harbour Police diver entered the water and was successful on his 3rd dive in freeing the passenger from the wreckage and brought him to the surface where artificial respiration restored the passengers breathing.

The weather reported at time of the accident was cloud 4,000 scattered, visibility 15+ miles, temperature +17°C, and the wind from 320° at 20 gusting 26 knots.

### INSTALLATIONS AU SOL

D I S P.	U T I L I S É	DESCRIPTION		D I S P.	U T I L I S É	DESCRIPTION	
		PAR	1101			ANÉMOMÈTRES	1113
		RADAR DE VEILLE	1102			INDICATEUR DE DIRECTION D'ATERRISSAGE	1114
		RADAR DE VEILLE SECONDAIRE	1103			BALISAGE LATÉRAL, DE SEUIL DE FIN DE PISTE	1115
		ILS - SYSTÈME COMPLET	1104			BALISAGE DU PROLONGEMENT D'ARRÊT	1116
		ILS - TRAJECTOIRE DE DESCENTE SEULEMENT	1105			BALISAGE D'AXE DE PISTE	1117
		ILS - RADIOPHARE D'ALIGNEMENT DE PISTE	1106			BALISAGE DE ZONE D'IMPACT DE PISTE	1118
		VORTAC	1107			BALISAGE LATÉRAL DE VOIE DE CIRCULATION	1119
		VOR/TVOR	1108			BALISAGE D'AXE DE VOIE DE CIRCULATION	1120
		NDB	1109			BARRES D'ARRÊT	1121
		DME	1110			VLF - STATION AU SOL	1122
		SYSTÈME D'ATERRISSAGE MICRO-ONDE	1111			VHF/UHF DF	1123
		BALISAGE D'APPROCHE	1112			VASI	1124

TYPE DE BALISAGE D'APPROCHE	1125		TYPE DE VASIS	1126	
	1	SIMPLIFIÉ (SOURCE SIMPLE)		2	VASIS
	2	SIMPLIFIÉ (BARRETTE)		1	VASIS À 3 BARRES
	3	PRÉCISION - CAT I CALVERT		4	AVASIS À 3 BARRES
	4	PRÉCISION - CAT II CALVERT		5	AVASIS
	5	PRÉCISION - CAT II		3	T-VASIS
	6	PRÉCISION - CAT III		6	AT-VASIS
	Y	AUTRE		7	AUTRE

PISTE UTILISÉE	A		C		E		G	
	À VUE		CAT-I		CAT-IIIA		CAT-IIIC	
	INSTRUMENTS		CAT-II		CAT-IIIB			

### COMMUNICATIONS

COMMUNICATIONS BILATÉRALES 1128	A	ÉTABLIES ET SATISFAISANTES	B	ÉTABLIES NON-SATISFAISANTES	X	NON ÉTABLIES
DERNIÈRE STATION AU SOL EN CONTACT	A	TOUR DE CONTRÔLE DE L'AÉROPORT	D	CENTRE D'INFORMATION DE VOL	G	CLUB DE PILOTAGE/UNICOM
	B	CONTRÔLE D'APPROCHE	E	SERVICE D'INFORMATION DE VOL	Y	AUTRE
	C	CENTRE DE CONTRÔLE RÉGIONAL	F	OPÉRATEUR STATION AU SOL		
1129						
DOSSIER DES COMM. ATS 1130	A	DISPONIBLE	B	PARTIELLEMENT DISPONIBLE	X	NON DISPONIBLE
DOSSIER DES COMMUNICATIONS RT Choisir 2 au plus 1131	A	DISPONIBLE EN FONCTIONNEMENT			D	TRANSCRIPTIONS FAITES
	B	DISPONIBLE NON EN FONCTIONNEMENT			F	TRANSCRIPTIONS NON FAITES
	C	DISPONIBLE ET EN FONCTIONNEMENT PARTIEL			E	TRANSCRIPTIONS PARTIELLEMENT FAITES

REMARQUES:

s.19(1)

**ANALYSIS OF OCCURRENCE**

— WHY — DISCUSS THE EFFECT OF THE ENVIRONMENT, THE AIRCRAFT AND THE PERSONNEL INVOLVED ON THE OCCURRENCE.

Examination of the aircraft wreckage did not reveal any evidence of mechanical failure of the aircraft or components, related to the cause of the accident.

The aircraft was being operated within the center of gravity limits and below the authorized maximum allowable gross weight.

C-FDJB had been purchased by Wardair in February 1973 and transported from Kenora, Ontario to Edmonton where the aircraft underwent a complete overhaul at the Wardair maintenance base in Edmonton. The work was completed and the aircraft returned to flying status in July 1976.

Mr. Martin began flying the aircraft on July 17th, 1976. After flying the aircraft locally in the Edmonton area for approximately 7 hours between July 17th and 19th, he departed from Edmonton July 20th and flew the aircraft to Toronto, arriving in Toronto on July 23rd.

After arriving in the Toronto area the aircraft had been flown locally for another 11 hours which included a performance at the Niagara Air Show August 29th, 1976, with Mr. Martin as the pilot. Performance in the Niagara Show was limited to two or three flybys with no maneuvering.

The aircraft was scheduled to perform during the third and fourth days of the Canadian International Air Show, with Mr. Martin as pilot. Maneuvers planned were two, three hundred and sixty degree turns, one left and one right followed by two lazy eights, a stall turn, and a final fly past. Maneuvers were to be carried out at an altitude of approximately 300 feet above the water surface.

According to the pilot the aircraft was performing normally on the day of the accident. The departure from Toronto Island Airport and the short flight to the stage area of the air show was routine until part way through the first three hundred and sixty degree turn to the right when the aircraft suddenly flicked on him and entered a spin to the right. The pilot stated he could not remember much of the spin but did recall he was flying the aircraft at about 60 knots and had banked the aircraft about 35° prior to it entering the spin.

35MM movies of the flight show the angle of bank increasing throughout the turn with right rudder being applied and held on throughout the spin to the right.

Strong, gusty, northwest winds prevailed at the time of the accident, which at the particular point in the turn where the aircraft entered the spin, were causing the aircraft to drift in towards the spectators on the island at Ontario Place, as well as being in a downwind flight condition at approximately 300 feet above the water, giving the pilot the impression he was flying at a higher airspeed than he actually was.

The above mentioned factors probably contributed to the cause of the accident.

[REDACTED]

[REDACTED]

In spite of the fact that Mr. Martin is an experienced airline pilot, [REDACTED] Maneuvers which he had planned to carry out at low altitude, within a defined area, with strong gusty winds, in an aircraft such as the Fox Moth, would require a pilot experienced in this type of flying and thoroughly familiar with the flight characteristics of the Fox Moth or at least a similar type aircraft.

### RENSEIGNEMENTS MÉTÉOROLOGIQUES

RENSEIGNEMENTS MÉTÉO 1001	T	RENSEIGNEMENTS DISPONIBLES ET FOURNIS	N	RENSEIGNEMENTS NON UTILISÉS
	U	RENSEIGNEMENTS NON DISPONIBLES	Z	NON RAPPORTÉS

SOURCE DE RENSEIGNEMENTS 1002	A	AUCUNE	D	SERVICES DE LA COMPAGNIE	G	AUTRE OBSERVATEUR
	B	MÉTÉOROLOGISTE RECONNU	E	AUTRE PILOTE	Y	AUTRE
	C	PRÉVISIONNISTE RECONNU	F	ÉTUDE PERSONNELLE		

CONDITIONS MÉTÉO VS PRÉVISIONS 1003	A	SUBSTANTIELLEMENT LES MÊMES	E	CONSIDÉRABLEMENT PIRES QUE PRÉVUES
	C	CONSIDÉRABLEMENT MEILLEURES QUE PRÉVUES		

### CONDITIONS ATMOSPHÉRIQUES SUR LES LIEUX DE L'INCIDENT

DIRECTION DU VENT 1004		HAUTEUR DE LA BASE DES NUAGES 1007	TEMPÉRATURE 1010 °C	POINT DE ROSÉE 1013 °C
VITESSE DU VENT 1005		VISIBILITÉ 1008	ALTITUDE-DENSITÉ 1011 Pds	DIFFÉRENCE ENTRE LA TEMPÉRATURE ET LE POINT DE ROSÉE 1014 °C
		RVR 1009	CALAGE ALTIMÉTRIQUE QNH 1012	
		CALME 1006		

ÉTAT DU CIEL 1015	A	TEMPS CLAIR	E	FRAGMENTÉ/ÉPARS PLUS BAS	I	OBSCURCI
	B	NUAGES ÉPARS AU-DESSUS DE 1000P.	G	COUVERT/ÉPARS PLUS BAS	H	PARTIELLEMENT OBSCURCI
	C	NUAGES ÉPARS AU-DESSOUS DE 1000 PIEDS	F	COUVERT		
	D	FRAGMENTÉ				

PHÉNOMÈNES ADVERSES 1016	A	POUSSIÈRE	F	FUMÉE	K	PRÉCIPITATION
	B	BROUILLARD	G	TEMPÊTE DE POUSSIÈRE	J	AUCUNE
	C	BROUILLARD LÉGER	H	TEMPÊTE DE SABLE	Y	AUTRE
	E	BROUILLARD GLACIAL	I	TEMPÊTE DE NEIGE		

TYPE DE PRÉCIPITATION Choisir 2 au plus 1017	C	BRUINE	F	NEIGE	I	ORAGES
	D	PLUIE	G	NEIGE/FLOCONS/GRANULES DE GLACE	L	AUCUNE
	E	AVERSES	H	GIBOULÉES	Y	AUTRE
	A	GRÊLE	J	BRUINE VERGLACÉE		
	B	GRÉSIL	K	PLUIE VERGLACÉE		

CONDITIONS MÉTÉOROLOGIQUES IMPORTANTES Choisir 3 au plus 1018	A	TURBULENCE DANS LES NUAGES	H	BASE DE NUAGE VARIABLE	C	TORNADE
	B	TURBULENCE DANS L'AIR CLAIR	M	LÉGÈRE PRÉCIPITATION	D	OURAGAN, TYPHON
	G	LIGNE DE GRAINS	L	FORTE PRÉCIPITATION	E	ONDE OROGRAPHIQUE
	J	VENT VARIABLE	R	ORAGE	S	NON SIGNIFICATIF
	I	VENT EN RAFALE	Q	GIVRAGE CONSIDÉRABLE	Y	AUTRE
	K	VENT EN RAFALE ET VARIABLE	N	TEMPÉRATURE SOUS 0°C		

### CONDITIONS MÉTÉOROLOGIQUES AU MOMENT DE LA PREMIÈRE ANOMALIE DU VOL (S'IL Y A LIEU)

ALTITUDE ASL DE L'AÉRONEF 1019	TEMPÉRATURE 1022 °C	PHÉNOMÈNES ADVERSES 1025	CONDITIONS MÉTÉOROLOGIQUES IMPORTANTES 1027	
ALTITUDE ASL GÉNÉRALE DU TERRAIN 1020	POINT DE ROSÉE 1023 °C		PRÉCIPITATION 1026	DEGRÉ DE TURBULENCE 1028
ALTITUDE/SOL DE L'AÉRONEF 1021	DIFFÉRENCE ENTRE LE POINT DE ROSÉE ET LA TEMPÉRATURE 1024 °C	M MODÉRÉE		
		F FORTE		

NOTES:

- 2 -

-WHY- cont.

It is apparent from the 35MM movies that the pilot was increasing the angle of bank throughout the turn and at the same time applying right rudder, when the aircraft stalled and spun to the right. After the aircraft entered the spin, right rudder was held on throughout two rotations of the spin and was still being applied when the aircraft struck the water. The engine was still developing high power at the time of impact.

Mr. Martin was carrying a passenger in the front passenger compartment of the aircraft, however, had not informed the Air Show officials that a passenger would be carried during the show. Only the Pilot-In-Command's name was listed on the Daily Crew and Passenger Listing form for the flight.

---

**ANALYSIS OF OCCURRENCE — FINDINGS/PREVENTION/SAFETY PROPOSALS**

---

— FINDINGS — LIST THE FINDINGS

- 1/ The aircraft was performing at low level in an Air Show.
- 2/ Strong gusty winds prevailed at the time of the show.
- 3/ The aircraft stalled and entered a spin while the pilot was executing a turn.
- 4/ The proper technique for spin recovery was not taken by the pilot.
- 5/ The aircraft continued to spin until it struck the water.

---

— HOW PREVENTED — DESCRIBE HOW THE OCCURRENCE COULD HAVE BEEN PREVENTED AND THE TASK OR MISSION ACCOMPLISHED

Had the pilot limited the show to a fly past instead of attempting to maneuver the aircraft within the confines of the air show stage, it is highly unlikely that the accident would have occurred.

Attempting to maneuver the aircraft at low level with the strong gusty wind was probably the major contributing factor of the accident.

---

— SAFETY PROPOSALS — A CONCISE LISTING

Pilots performing in air shows with vintage aircraft should be encouraged to limit their performance to straight and level flybys.

Carrying passengers during air show performances should be discouraged, and should never be on-board unless officials of the air show are aware that they are, particularly rescue personnel.

**FONCTIONNEMENT DÉFECTUEUX OU DÉFAILLANCE DE L'AÉRONEF OU DES CIRCUITS**

LIGNE	CIRCUIT	ÉLÉMENT/CIRCUIT	SOUS-CIRCUIT SOUS-ÉLÉMENT	PIÈCES
1				
2				
3				
4				
5				
6				

**DÉTAILS**

1	
2	
3	
4	
5	
6	

**INVESTIGATION**

INVESTIGATED BY	NUMBER OF INVESTIGATORS		ASSISTANCE FROM DNHW		ASSISTANCE FROM HQ LAB		INVESTIGATION BY CORRESPONDENCE	
	CAI	TI	2103		2104		2105	
	<b>ONE</b>	<b>ONE</b>	YES	NO	YES	NO	PARTIALLY	
2101	2102	<input checked="" type="checkbox"/>	NO					
OTHER ASSISTANCE								

PAGES SUBMITTED	<input checked="" type="checkbox"/>	6	7	<input checked="" type="checkbox"/>	9	<input checked="" type="checkbox"/>	11	C1	C2	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>				
	<input checked="" type="checkbox"/>	13	<input checked="" type="checkbox"/>	15	16	17	<input checked="" type="checkbox"/>	M1	M2	M3					

DOCUMENTS	INTERVIEWS	<input checked="" type="checkbox"/> A	FLIGHT CREW	E	MAINTENANCE PERSONNEL	K	PERSONAL PHYSICIAN
		B	EYEWITNESS	F	SPOUSE	L	MANAGEMENT
		C	INSTRUCTOR/CHECK PILOT	<input checked="" type="checkbox"/>	PASSENGERS		
		D	CABIN CREW	H	DISPATCH		
	REPORTS	A	MATERIALS LAB	D	MEDICAL	G	CORONER
		B	TECHNICAL	E	DCIEM	<input checked="" type="checkbox"/>	POLICE
		C	DATA RECORDER	F	PATHOLOGIST	K	CRIME LAB
	OPERNL DATA	A	PERFORMANCE	D	ATS TAPE TRANSCRIPTION	G	CASUALTY LIST
		B	WEATHER	E	CVR TAPE TRANSCRIPTION		
		<input checked="" type="checkbox"/> C	PHOTOGRAPHS	<input checked="" type="checkbox"/>	MAPS & CHARTS		

INVESTIGATION	ELAPSED TIME FROM ACCIDENT TO INVESTIGATOR'S ARRIVAL ON SCENE	0 Hrs	ELAPSED TIME FROM ACCIDENT TO RECEIPT OF NOTIFICATION BY REGION	0 Hrs
2110			2111	

INVESTIGATOR'S SIGNATURES

*C. Battelle*      *S. J. Morrison*  
(IIC)

REGIONAL SUPERINTENDENT'S COMMENTS

*S. J. Morrison*      26 Jan 1977  
REGIONAL SUPT      DATE

NOTES:

### RENSEIGNEMENTS SUR L'AÉRONEF

CONSTRUCTEUR 0800		MODÈLE 0801		HEURES TOTALES DE LA CELLULE 0802 Hres		TSO 0803 Hres				
POIDS DE L'AÉRONEF 0804	A	IDENTIQUE OU INFÉRIEUR AU POIDS AUTORISÉ		CENTRE DE GRAVITÉ 0805	A	LIMITE AVANT DÉP.	C	DANS LES LIMITES		
	B	SUPÉRIEUR AU POIDS AUTORISÉ			B	LIMITE ARRIÈRE DÉPASSÉE	D	LIMITES LATÉRALES DÉPASSÉES		
ESTIMATION TOTALE DU POIDS DE L'AÉRONEF 0806/0807	POIDS DU C DE G			TOLÉRANCE DU C DE G						
	OU _____ POUCES			_____ % MAC OU _____ PCS À _____ PCS						
		_____ % MAC		À		_____ % MAC				
TYPE DE CARBURANT 0808	A	80/87	L	ESSENCE D'AUTOMOBILE	G	JP-3	J	JP-6	Y	AUTRE
	C	100/130	E	KÉROSÈNE	H	JP-4	K	CARBURANT MÉLANGÉ		
	D	115/145	F	JP-1	I	JP-5	Z	INCONNU		

### RENSEIGNEMENTS SUR LE GROUPE PROPULSEUR ET L'HÉLICE

T S O HRS	MOTEUR N° 1 0809	MOTEUR N° 2 0810	MOTEUR N° 3 0811	MOTEUR N° 4 0812	HÉLICE N° 1 0813	HÉLICE N° 2 0814	HÉLICE N° 3 0815	HÉLICE N° 4 0816	
AÉRONEF ÉQUIPÉ SELON LES NORMES MINIMALES IFR				<input checked="" type="checkbox"/> Y	OUI		<input type="checkbox"/> X	NON	
AÉRONEF ÉQUIPÉ POUR LES AP. DE PRÉCISION 0817	A	CAT. I		C	CAT. III A		E	CAT. III C	
	B	CAT. II		D	CAT. III B				
RADAR MÉTÉO DE BORD 0818	A	UTILISABLE NON EN FONCTIONNEMENT		C	UTILISATION SATISFAISANTE		E	NON INSTALLÉ	
	B	INUTILISABLE		D	UTILISATION NON SATISFAISANTE		F	A BORD FONCTIONNEMENT NON RAPPORTÉ	
SYSTÈME AVERTISSEUR DE DÉCROCHAGE 0819	A	INDICATEUR INSTALLÉ		D	INDICATEUR & POUSSEUR DE MANCHE INSTALLÉS		INDICATEUR	V	VISUEL
	C	POUSSEUR DE MANCHE INSTALLÉ		B	INDICATEUR & POUSSEUR DE MANCHE NON INSTALLÉS			A	SONORE

### ÉQUIPEMENT DE BORD ET CIRCUITS

D I S P.	U T I L I S É	DESCRIPTION	D I S P.	U T I L I S É	DESCRIPTION
		COMMUNICATIONS VHF 0821			PILOTE AUTOMATIQUE 0838
		COMMUNICATIONS HF 0822			FEUX ANTICOLLISION 0839
		COMMUNICATIONS UHF 0823			OXYGÈNE POUR L'ÉQUIPAGE 0840
		VOR 0824			OXYGÈNE POUR LES PASSAGERS 0841
		ADF 0825			SOURCE AUXILIAIRE DE COURANT 0842
		TACAN 0826			RADAR ALTIMÉTRIQUE 0843
		DME 0827			AVERTISSEUR DE PROXIMITÉ DU SOL 0844
		SYSTÈME COMPLET ILS 0828			AVERTISSEUR D'ALTITUDE 0845
		ALIGNEMENT DE PISTE ILS SEULEMENT 0829			DISPOSITIF ANTICOLLISION 0846
		TRAJECTOIRE DE DESCENTE ILS SEULEMENT 0830			NAVIGATION DE SURFACE 0847
		TRANSPONDEUR 0831			NAVIGATION VLF 0848
		TRANSPONDEUR (MODE C) 0832			MLS 0849
		MOTEUR ANTIGIVRAGE/DÉGIVRAGE 0833			PRÉSENTATION À HAUTEUR DE L'OEIL 0850
		DÉGIVREUR D'HÉLICE 0834			NAVIGATION, PAR INERTIE 0851
		CIRCUIT ANTIGIVRAGE/DÉGIVRAGE DE PARE-BRISE 0835			DONNÉES INTÉGRÉES DE VOL 0852
		CIRCUIT ANTIGIVRAGE/DÉGIVRAGE DE LA CELLULE 0836			DÉTECTION DE TURBULENCE 0853
		DOUBLES COMMANDES 0837			

### CONFIGURATION DE L'AÉRONEF À L'IMPACT

TRAIN D'ATTERRISSAGE 0854	F	FIXE	U	ÉLEVÉ	T	EN MOUVEMENT	D	BAISSÉ	FLOTTEURS-ROUES AMPHIBIES 0855		U	ÉLEVÉ	D	BAISSÉ
VOLETS 0856	N	AUCUN			U	ÉLEVÉS	P	PARTIELS	D	BAISSÉS				
PUISSANCE MOTEUR 0857	N	AUCUNE	P	PARTIELLE	F	MAXIMALE	R	INERTIE	A	ASSYMETRIQUE				
MÉLANGE 0858	R	RICHE	L	FAIBLE	A	AUTO	C	ÉTOUFFOIR						
CHAUFFE-CARBURATEUR 0859	H	CHAUD	C	FROID	P	PARTIEL	X	NON INSTALLÉ						
CHAUFFAGE PAR INDUCTION 0860	H	CHAUD	C	FROID	P	PARTIEL	X	NON INSTALLÉ						

**CRASHWORTHINESS—SYSTEMS & PROCEDURES**

SYSTEM/ PROCEDURE GENERAL	SYSTEM/PROCEDURE SPECIFIC	N E E D E D	ON BOARD OR AVAILABLE			USED/ WORN			PRODUCED/ CONTRIB. TO INJURIES			MINIMIZED/ PREVENTED INJURIES			FAILED		
			YES	NO	?	YES	NO	?	YES	NO	?	YES	NO	?	YES	NO	?
RESTRAINT SYSTEM CREW	LAP BELT 2401/2402		X			X			X		X			X			
	SHOULDER HARNESS 2403/2404			X													
	LAP BELT TIE DOWN STRAP 2405/2406			X													
	INERTIA REEL 2407/2408			X													
	SHOULDER STRAP GUIDE 2409/2410			X													
RESTRAINT SYSTEM PASSENGERS	LAP BELT 2411/2412		X			X			X		X			X			
	SHOULDER HARNESS 2413/2414			X													
	LAP BELT TIE DOWN STRAP 2415/2416			X													
	INERTIA REEL 2417/2418			X													
	SHOULDER STRAP GUIDE 2419/2420			X													
SEATS	SEAT/PILOT 2421/2422		X			X			X		X			X			
	SEAT/COPILOT 2423/2424																
	SEAT/JUMP 2425/2426																
	SEAT/PASSENGER 2427/2428		X			X			X		X			X			
IMMEDIATE ENVIRONMENT COCKPIT	DESIGN 2429/2430																
	LOCATION 2431																
	RESTRAINT 2432/2433																
IMMEDIATE ENVIRONMENT CABIN	DESIGN 2434/2435																
	LOCATION 2436																
	RESTRAINT 2437/2438																
CABIN BAGGAGE	LOCATION 2439																
	RESTRAINT 2440/2441																
CARGO	LOCATION 2442																
	RESTRAINT 2443/2444																
EMERGENCY EVACUATION	AIRCRAFT DOORS 2445/2446																
	EMERGENCY EXITS 2447/2448																
	CHUTES 2449/2450																
	ROPES 2451/2452																
	EXIT LIGHTING 2453/2454																
	INTERIOR EMERGENCY LIGHTING 2455/2456																
	SUPERVISION 2457/2458																
	WARNING 2459/2460																
	OTHER 2461/2462																
WATER LANDINGS	LIFE VESTS—ACCESSIBILITY 2463/2464																
	LIFE VESTS—TYPE 2465/2466																
	LIFE RAFTS—ACCESSIBILITY 2467/2468																
	LIFE RAFTS—TYPE 2469/2470																

**RENSEIGNEMENTS SUR LE PERSONNEL – PILOTE**

PILOTES AUX COMMANDES	A	PILOTE COMMANDANT DE BORD	G	INSTRUCTEUR	E	AUCUN
	B	CO-PILOTE	D	PILOTE SURVEILLANT	Y	AUTRE
	0501 C	ÉLÈVE	F	LES DEUX PILOTES		

**PILOTE COMMANDANT DE BORD**

AGE	0503	SEXE	NOM DE FAMILLE	INITIA- LES	NUMÉRO DE LICENCE	C	CANADIENNE
0502		H	0504	0505	0506/0507	F	ÉTRANGÈRE

POSTE OCCUPÉ	A	PILOTE	D	NAVIGATEUR	G	AUTRE
	B	COMMANDANT ADJOINT	E	POSTE DE REPOS		
	0508 C	MÉCANICIEN DE BORD	F	CABINE DES PASSAGERS		

FONCTION SPÉCIALE	A	AUCUNE	C	EXAMINATEUR DE LA CIE.	E	TECHNICIEN	Y	AUTRE
	0509 B	INSTRUCTEUR	D	EXAMINATEUR DU MDT	F	ÉLÈVE		

LICENCES DE PILOTE	A	ÉLÈVE	D	DE LIGNE	V	GIRAVION PRIVÉ
	B	PRIVÉE	T	PLANEUR	W	PROFESSIONNELLE GIRAVION
	C	PROFESSIONNEL	U	BALLON LIBRE	X	PROFESSIONNELLE DE 1 <sup>ère</sup> CLASSE ANNOTATION DE GIRAVION
	B	PROFESSIONNELLE 1 <sup>ère</sup> CLASSE	I	AUCUNE	Y	DE LIGNE, ANNOTATION DE GIRAVION
	0510 H	AUTRE				

QUALIFICATION DE TYPE	Y	OUI	X	NON	DERNIÈRE VÉRIFICATION DE CE TYPE	SEMAINES
0511					0512	

QUALIF. DE VOL AUX INSTRUMENTS	A	AVION	LES DEUX	1	CLASSE I	DERNIÈRE VÉRIFICATION DE QUALIFICATION DE VOL AUX INSTRUM.	F	VOL
	0513/0514	HÉLICOPTÈRE		2	CLASSE II	0515/0516	S	SIMULATEUR

QUAL. D'INS.	Y	OUI	X	NON	CLASSE	0518
0517						

CLASSIFIC. DES QUALIFIC. EN CHOISIR jusqu'à deux	A	AVION SE SOL	D	AVION ME MER	H	TYPE D'HÉLICOPTÈRE
	B	AVION ME SOL	AC	AVION SE SOL ET MER	Y	AUTRE
	0519 C	AVION SE MER	BD	AVION ME SOL ET MER		

ANNOTATIONS	N	NUIT	B	BLOC D'ESPACE AÉRIEN	A	ACROBATIES AÉRIENNES	T	TRSA
0520								

**TEMPS DE VOL (À l'heure près – Si inconnu inscrire X)**

	TOUS TYPES	CE TYPE	EN DOUBLE COMMANDE	CE TYPE D'ATTER.	MONOMOTEUR	MULTI- MOTEUR	RÉEL AUX INSTRUMENTS	SIMULÉ AUX INSTRU.	DE NUIT	GIRAVION					
HEURES TOTALES	0521	0523	0525	0527	0529	0531	0533	0535	0537	0529					
H. DERN. 90 JOURS	0522	0524	0526	0528	0530	0532	0534	0536	0538	0540					
HEURES, DERNIERS 30 JOURS	0541	HEURES, DERNIERS 3 JOURS	HEURES, DERNIERS 24 HEURES	HEURES EN SERVICE AVANT L'INCIDENT	HEURES DE REPOS AVANT LE SERVICE	HEURES EN ÉVEIL DEPUIS LE DERNIER REPOS	ATERRISSAGE DE CE GENRE, DERNIERS 90 JOURS	HEURES TOTALES AUX INSTRU. DERNIERS 30 JOURS	0542	0543	0544	0545	0546	0547	0548

FICHE MÉD.	1	CERTIFICAT MÉDICAL VALIDE SANS RESTRICTION/LIMITATION	2	CERTIFICAT MÉDICAL VALIDE AVEC RESTRICTIONS/LIMITATIONS	3	CERTIFICAT MÉDICAL NON VALIDE
0549						

ÉCOLE DE PILOTAGE	NUMÉRO DE LICENCE C.T.A.	CODE
		0550

INSTRUCTEUR PRINCIPAL – NOM	F	INSTRUCTEUR À PLEIN TEMPS À L'ÉCOLE	EN DOUBLE COMMANDE AU COURS DES DERNIERS SIX MOIS	EN DOUBLE COMMANDE AU COURS DE LA DERNIÈRE ANNÉE
	P	INSTRUCTEUR À TEMPS PARTIEL À L'ÉCOLE		
EXAMINATEUR DE VOL D'ESSAI – NOM ET LICENCE	M	MDT	C	COMPA- GNIE
0551/0552	D	DFTE	0555	0556
0553/0554				

**CRASHWORTHINESS-INJURIES**

IDENTIFICATION <small>2501</small>		DEGREE OF INJURY	AUTOPSY <small>2503</small>		FRONT		REAR	FACING <small>2506</small>	
<input checked="" type="checkbox"/>	PILOT		<input type="checkbox"/>	FATAL				A	PHYSICIAN
<input type="checkbox"/>	CO-PILOT	<input type="checkbox"/>	SERIOUS	B	PATHOLOGIST	<input type="checkbox"/>	C	S	SIDE
<input type="checkbox"/>	OTHER FLIGHT CREW	<input checked="" type="checkbox"/>	MINOR	C	FLIGHT SURGEON	<input type="checkbox"/>	L	R	REAR
<input type="checkbox"/>	CABIN CREW	<input type="checkbox"/>	NONE	D	OTHER				
<input type="checkbox"/>	PASSENGER	<input type="checkbox"/>							
<input type="checkbox"/>	PERSON OUTSIDE AIRCRAFT	<input type="checkbox"/>							

THERE IS SPACE BELOW FOR SPECIFYING UP TO TEN INJURIES FOR THE PERSON COVERED BY THIS PAGE. THE "EIGHTH REVISION, INTERNATIONAL CLASSIFICATION OF DISEASES, SECTION XVII WILL BE USED TO CATEGORIZE ALL INJURIES.

ENTER THE PROPER CODE IN THE SPACE PROVIDED AS WELL AS A NARRATIVE DESCRIPTION OF THE INJURY.

ENTER THE APPROPRIATE CODE FOR THE "EVENT CAUSING INJURY" AT THE RIGHT.

EVENT CAUSING INJURY	
STRUCK INTERIOR OF AIRCRAFT AT IMPACT	<b>A</b>
STRUCK BY FLYING OBJECT INSIDE AIRCRAFT	B
BURNS ONLY	C
BURNS FOLLOWING OTHER INJURIES	D
CRUSHED IN WRECKAGE	E
CONTACT WITH PROP/INTAKE/EXHAUST	F
FELL FROM AIRCRAFT (OR THROWN)	G
STRUCK BY AIRCRAFT	H
PULLED UNDERWATER	J
STRUCK BY MAIN ROTOR	K
STRUCK BY TAIL ROTOR	L
STRUCK INTERIOR OF AIRCRAFT IN TURBULENCE	M
STRUCK BY DISPLACED COMPONENT/STRUCTURE	N

	CODE	
	2507 <input type="text" value="8"/> <input type="text" value="2"/> <input type="text" value="4"/> <input type="text" value="0"/>	
	2509 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/>	
	2511 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/>	
	2513 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/>	
	2515 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/>	
	2517 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/>	
	2519 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/>	
	2521 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/>	
	2523 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/>	
	2525 <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/> <input type="text" value=""/>	

NOTES:

---

**VUE EN ÉLEVATION DU LIEU**

FAIRE UN CROQUIS DES PISTES, OBSTACLES, TRAJECTOIRE DE VOL, ETC. INDIQUER LES DISTANCES ET DIMENSIONS IMPORTANTES.

---


**VUE EN PLAN DU LIEU**

FAIRE UN CROQUIS DE LA ZONE D'ATERRISSAGE, DES OBSTACLES, DE LA TRAJECTOIRE DE L'AÉRONEF, ETC. INDIQUER LES DISTANCES ET DIMENSIONS IMPORTANTES, ET LE VECTEUR VENT.

s.19(1)

**CRASHWORTHINESS-INJURIES**

IDENTIFICATION <small>2501</small>		DEGREE OF INJURY	AUTOPSY	
A	PILOT		<small>2503</small>	A
B	CO-PILOT	<small>2502</small>	B	PATHOLOGIST
C	OTHER FLIGHT CREW	F	C	FLIGHT SURGEON
D	CABIN CREW	X	D	OTHER
E	PASSENGER	M	E	CAM. PRESENT
F	PERSON OUTSIDE AIRCRAFT	N		




THERE IS SPACE BELOW FOR SPECIFYING UP TO TEN INJURIES FOR THE PERSON COVERED BY THIS PAGE. THE "EIGHTH REVISION, INTERNATIONAL CLASSIFICATION OF DISEASES, SECTION XVII WILL BE USED TO CATEGORIZE ALL INJURIES.

ENTER THE PROPER CODE IN THE SPACE PROVIDED AS WELL AS A NARRATIVE DESCRIPTION OF THE INJURY.

ENTER THE APPROPRIATE CODE FOR THE "EVENT CAUSING INJURY" AT THE RIGHT.

EVENT CAUSING INJURY	
STRUCK INTERIOR OF AIRCRAFT AT IMPACT	<b>A</b>
STRUCK BY FLYING OBJECT INSIDE AIRCRAFT	B
BURNS ONLY	C
BURNS FOLLOWING OTHER INJURIES	D
CRUSHED IN WRECKAGE	E
CONTACT WITH PROP/INTAKE/EXHAUST	F
FELL FROM AIRCRAFT (OR THROWN)	G
STRUCK BY AIRCRAFT	H
PULLED UNDERWATER	<b>J</b>
STRUCK BY MAIN ROTOR	K
STRUCK BY TAIL ROTOR	L
STRUCK INTERIOR OF AIRCRAFT IN TURBULENCE	M
STRUCK BY DISPLACED COMPONENT/STRUCTURE	N



CODE	
2507	2508
2509	2510
2511	2512
2513	2514
2515	2516
2517	2518
2519	2520
2521	2522
2523	2524
2525	2526

NOTES:

---

**VUE EN ÉLEVATION DU LIEU**

FAIRE UN CROQUIS DES PISTES, OBSTACLES, TRAJECTOIRE DE VOL, ETC. INDIQUER LES DISTANCES ET DIMENSIONS IMPORTANTES.

---

**VUE EN PLAN DU LIEU**

FAIRE UN CROQUIS DE LA ZONE D'ATTERRISSAGE, DES OBSTACLES, DE LA TRAJECTOIRE DE L'AÉRONEF, ETC. INDIQUER LES DISTANCES ET DIMENSIONS IMPORTANTES, ET LE VECTEUR VENT.

APPENDIX 2

STATEMENT

## AIRCRAFT ACCIDENT INVESTIGATION DIVISION

## ONTARIO REGION

Aircraft Type DEHAVILLAND FOX MOTH	Registration C-FDJB	Date September 5th, 1976
Interviewer S. A. Musson	Statement date/time	

Statement taken

In long hand     By recorder     Over telephone     Personal presence

STATEMENT OF WITNESS

Your name	GARTH M. MARTIN	Age	
Address	[REDACTED]		Phone
Occupation	ATR Pilot - Wardair	Aviation Experience	ATR
Where were you when the accident happened? Pilot-In-Command of C-FDJB			

In your own words, state what you know of the accident.

Q - If you could just start off Garth and tell me pretty well everything you can recall about the flight, from the take-off at the Island and that sort of thing.

A - Well we took off from the Island, right about 10 minutes after 2 o'clock, 'cause I was suppose to be on stage at 2:15, I took off, did a right turn and I held just to the east of the button of runway 33. I started my run in to the stage at a minute and 20 seconds prior to 2:15. I was just south of Ontario Place when Boss Control said a sail plane, which was ahead of me, was running a little late and I did a 360 to the left and continued in well outside the, south of Ontario Place. As the sail plane left the stage area and went back to the Island I came in about, a little bit to the west of centre stage in a right turn, a right 360, which was going to be followed by a left 360, further to the west in front of the crowd and I was about half way around the 360 when the airplane flicked to the right and went into a spin. Now I don't really remember anything of the, of the spinning itself nor the impact but I was aware of people at the airplane, which I understand happened very quickly after the airplane was in the water because when they ah came to the airplane, now I don't know whether they were right at the airplane or just close to it, by the time I was aware of what's going on. And ah, my seatbelt had either, I have a bruise on my thigh so my seatbelt either had broken lose somewhat or else I had undone it and stood up because of the water. I think I was probably standing on the seat and ah they were coming to get me and I said don't worry about me get my partner out of the cabin.

Q - It was you that mentioned that?

A - Yes. I think I mentioned that at least 2 or 3 times and pointed down into the, in front of me on the right hand side because the people were on the right hand side of the airplane. I said I'm okay, get my partner out, which they did, and to my knowledge he was in the boat, I saw them doing mouth to mouth resuscitation with him in the boat before I got out of there, the airplane into the rescue boat myself.

Q - How about turbulence? Can you recall was it turbulent at all?

A - There was a gusty wind, this is my views, probably what did me in.

Q - How about altitude?

A - 300 ft, that's above the water.

Q - The other thing too, were you wearing a shoulder harness? Was there a shoulder harness in this aircraft?

A - No shoulder harness in the airplane, just a seatbelt.

Q - We wondered about that because some people had said there was a shoulder harness, and I wondered if it had failed and just got lost in the water.

A - No, just a seatbelt.

Q - So as far as you can recall there was no difficulty with the aircraft, there didn't seem to be any, it was probably routine up until the point where it flicked.

A - Routine, and it completely surprised me because it flicked up to the right, if it flicked to the left I might have had a little chance but it flicked to the right and I knew it had gone to the right I could see water above me.

Q - Do you have any idea what airspeeds you were at, at that particular time?

A - Well I entered it at 75 knots and it seems to me I remember seeing 60 knots in the last, you know, just prior to it...

Q - What does it normally cruise at?

A - It cruises about 75 knots.

Q - 75 knots aye. How about the flights before, were you having any difficulties with the airplane, was there anything, the rigging or anything at all?

A - No, I had rigging difficulties when we first rebuilt the airplane but fixed the trimming and had the airplane re-rigged as well.

Q - Where was that done?

A - I was re-rigging it as I flew eastbound with attachable trim taps then here we ah removed all of those except for the one fixed tap, which is on the rudder, and ah attached trimming devices on them.

Q - Okay, so it was just a matter of the trim taps more than anything else.

A - Yes. And then we got the rigging diagrams and re-rigged the airplane as well and we were able to remove a little bit of the trimming devices we'd put on.

Q - I see. Was that done here in Toronto?

A - Done here in Toronto, at Brampton, yes.

Q - Brampton aye?

A - Yes. As a matter of fact by [REDACTED] and myself.

Q - How about, were there any fixed trims at all on the ailerons? Have you ever had any fixed trims at all on the ailerons?

A - Not a fixed trim. I had on like a portable one, if you will, you know, the attached ones I had on the flight down from the west.

Q - That wasn't on here at all then?

A - No, that had been replaced by the trimming device under the trailing edge bottom of the right hand aileron.

Q - So you were quite happy with the way it was flying, you hadn't been having any difficulty in as far as rigging....

A - No, I wasn't having any difficulty with it, it flew pretty well hands off at cruising, at cruising speed.

- 3 -

Q - How about your flying history up to this point. I've been through your file now, and you've done a lot of heavy aircraft flying and that. Have you done much light airplane flying?

A - Well the ah, the Otter with the reserve not so much the last 2 years.

Q - How long ago would that be?

A -

Q - Most of the other stuff's been fairly heavy I guess?

A - Fairly heavy, yes.

Q - Had you ever flown anything like that? Had you flown a Tiger Moth at all?

A - No I hadn't.

Q - So it was you first?

A - Yes.

Q - I guess there's not really much opportunity to be checked out on something like that, I guess you just talk to somebody and go in, that's about all you can do aye?

A -

Q - Had you done spins or stalls in this aircraft?

A - Yah, I had done stalls and just a start of a spin.

Q - What speed did it usually stall at?

A - It was stalling about 40 knots, maybe a touch under.

Q - Much the same as any other light airplane sort of thing.

A - Yah.

Q - Did it have a tendency to drop a wing in a stall?

A - If anything, a little bit to the left but not very much.

Q - How about power on stalls. Have you done any power on stalls?

A - No, power off stalls.

Q - Okay. How about the, ah, had you attended the briefing for the airshow that morning?

A - Yes I had.

Q - Was there any part of that briefing that influenced anything that you did at the airshow?

A - No, I don't ah, I'd attended all the briefings for the previous three days in a row.

Q - This was the first day you were scheduled to fly though aye?

A - First day, yes.

Q - So there was nothing at the briefing that you...you were happy with everything the way it was going and this sort of thing, and there was nothing.

A - Yah, I was happy and there was a gusty wind.

Q - Is there a weather briefing available to you before the show?

A - Yes there was a weather briefing at the....

Q - They give you upper winds and surface winds and all that sort of thing.

A - Yes.

000047

.....4

Q - And you had flown it in the Niagara Air Show?

A - The previous weekend, yes.

Q - Did you do basically the same maneuvers?

A - No, we'd had three airplanes in trail formation.

Q - It was more a formation type I guess rather than a solo.

A - Yah, it was sort of in ah 1/4 mile trail, with the three airplanes around a couple of times.

Q - How about here. Was there any opportunity before the airshow to practice the run here?

A - Not to practice on the site, no.

Q - You didn't aye?

A - No.

Q - Had you been through the routine previous?

A - Oh yes, I'd been through the routine a number of times for timing purposes.

Q - Yah, right. But not right on location sort of thing?

A - Not on the site itself, no.

Q - I guess there was no real purpose of Mr. Bennidict being on board other than just for the ride sort of thing.

A - Yes. He's the mechanic that's done most of the work on the Fox Moth so I asked him if he'd like to go for a ride and he wanted to go so there was no reason why he couldn't.

Q - What's the seating arrangement in that, it was damaged so bad we weren't able to tell, how many seats are actually up front in there?

A - There is a, the hammock seat and there is a forward seat, which was not yet installed.

Q - I see. This hammock seat, was it in the centre sort of thing of the cabin?

A - It's right in the area where the door is.

Q - So he'd be sitting in there facing forward I guess aye?

A - Facing forward, yes.

Q - There's no shoulder harness in there either?

A - No, just a lap belt.

Q - How much fuel do you think was on board at the time of the accident?

A - I figure 16 gallons.

Q - Sixteen aye. And that was where it was fueled at Malton?

A - It was fueled at Malton the day before and I had flown half an hour or just slightly more than a half an hour in practice on the Saturday and then when I, and that was from Malton and when I refueled it, just fueled to not quite full cause it always spills over and I have to keep wiping it up, and it's 25 gallons and ah then I had flown from Malton to the Island which involved close to half an hour again when I left on the Sunday at noon. So there'd been an hours flying on the airplane plus taxing and what not as well as the five minutes or so airborne before getting (clearance). So I would say 16 gallons, you know, within a gallon.

Q - Yah, right. The weight and balance as far as what had been figured for the aircraft was well within limits, you weren't having any trouble with....there was some discussion as to whether the ballast should be in there or out.

A - Yes, well what I was hoping to get down to situation with the airplane where I could have a disposable ballast so that I could carry three people.

Q - In other words in order to carry three people in it the way it was you had to take the ball out, I guess, to stay within the limits.

A - Yes.

Q - Or else take some fuel off I guess.

A - Yah, well ah this was it, I really had a restriction to two people and I wanted to get that up to three and then when I didn't fly anybody have a disposable ballast, because we were putting a, just obtained a front seat and we were putting that in or would have been putting that in very shortly.

Q - What were the ah they were going to donate the aircraft to the museum aye and then were you just going to fly it on special occasions sort of thing.

A - No not ah, we weren't really donating it no we were hangaring it with the Historical Society as a convenience to us and it worked out well with there planes as well because the security of the hangars up there at Malton we weren't happy with.

Q - I see.

A - So we felt happier keeping the airplane up there worked out better, but no our plan was to keep the airplane available to the public sort of thing.

Q - I see. And how did you get involved with flying, were you just interested in the airplane and volunteered for it?

A - No, I was asked to do it by the sales department under Mr. Ward.

Q - Okay, I don't think, is there anything else you want to add to the end of the statement?

A - Well I don't really know, are you interested in what I think?

Q - Yes, of course, yah, you were there, closer than I was.

A - I know when I, the wind was north northwest and was gusty and this is what I feel what probably did me in. When I got around to that point in the turn  I was downwind, you know, then whether I got in a lull or gust quit and got into a lull, bang that was it. But I had no warning at all, it just flicked and flicked it away.

Q - Quite violently then aye?

Original As is

A - Yes.

Q - I guess you don't have any recollection of how much control you had on at that time. Do you have any idea of how much rudder you might have had on?

A - No, I'm not certain of that.

Q - Does it require much rudder control in the turns?

A - Not ah not too much no. I found that the rudder control was more required with changes of speed, you know, at approach speed or a higher speed, you know, if you were dipping down and then that speeds it up a little bit, you require some rudder and consequently on final approach you require a little rudder too because it was set for cruising.

Q - Yah, right. I noticed there was quite a bit of trim on the rudder. I tend to agree with you a bit about the wind because the part I saw when it seemed to get into trouble was definitely downwind at that point and it just seemed to be at that critical point.

A - The winds, as I was mentioning on the phone with you, there was this report of people hearing a crack no snap or anything like that I don't, I don't recall anything like that, I wouldn't have heard it in any event. The only other thing I can mention is ah did hear it from Boss Control later, the airshow committee, or was it Bill McVeen I guess it was mentioned talking to Bill Cole, he got pulled up 50 feet in one, in one wind sheer there and had an occasion too, so, you know, I knew the wind was there and it may have been more than I had anticipated.

- 6 -

Q - I know the other thing I noticed too was that at one point the wind was kind of drifting you to the crowd and I wondered if you could recall, you know, do you recall sort of tightening the turn a little more than you intended to do?

A - No I don't recall any of this. I sort of had a fixed ah in all my practicing in turns and what not I figured I had about a 35° bank turn with the struts ahead of me and everything else.

Q - Okay, that's fine, thankyou.



---

CERTIFIED CORRECT  
S. A. Musson

s.19(1)

INTERVIEW WITH MR. J. BENEDIK  
PASSENGER ON BOARD CF-DJB

Mr. Benedik was interviewed September 3rd, 1976. He stated he did not remember much about the flight. He could remember arriving at the Island Airport, getting on board CF-DJB, and fastening his seat-belt.


He stated that it had been pre-arranged with Mr. Martin that he would ride as passenger, and that he had been on board the aircraft during the Niagara Air Show.

Mr. Benedik stated he had worked on CF-DJB and that to his knowledge there were no problems with the aircraft.

[REDACTED]

[REDACTED]


Dr. Murray Naiberg was present during the interview.



CERTIFIED CORRECT  
S. A. Musson

APPENDIX 11

MAP



**CANADIAN DIRECT**

**ACCIDENT & SITE**

**FLIGHT PATHS**

**LAKE ONTARIO**

**SCALE OF FEET**

APPENDIX III

HARBOUR POLICE REPORT

# THE TORONTO HARBOUR COMMISSIONERS

## TORONTO HARBOUR POLICE

Artificial resuscitation

### A1 RAFT CRASH - DROWNING REPORT - Life restored

Main

Station.

Date Sunday September 5th 1976

- |   |  |
|---|--|
| <ol style="list-style-type: none"> <li>1. (a) Name, (b) sex, (c) age, (d) height and (e) weight of person imperiled.</li> <li>2. P.O. address.</li> <li>3. Day and hour of accident.</li> <li>4. Distance and direction from station.</li> <li>5. Was scene of accident visible from station?</li> <li>6. Cause of accident.</li> <li>7. Temperature of water and atmosphere.</li> <li>8. Length of time under water.</li> <li>9. By whom taken from water.</li> <li>10. Did patient rise to the surface after falling into water? If so, how many times?</li> <li>11. Did patient breathe when taken from the water? (Also state what other signs of life were apparent, if any).</li> <li>12. How soon after notification of accident did members of Service arrive on scene?</li> <li>13. Was patient breathing when taken in charge by members of Service? (Also state what other signs of life were apparent, if any.)</li> <li>14. Were patient's jaws clenched?</li> <li>15. How soon after artificial respiration was begun did patient show signs of life?</li> <li>16. What were the first signs of life shown by the patient?</li> <li>17. What signs of life, if any, were shown by the patient while water was being expelled from the lungs?</li> <li>18. State probable quantity of water expelled or drained through the mouth.</li> <li>19. Length of time artificial respiration was employed.</li> <li>20. What means were employed during process of artificial respiration to impart warmth to the extremities?</li> <li>21. What means were employed to restore circulation?</li> <li>22. What stimulants, if any, were administered?</li> <li>23. Result.</li> </ol> | <ol style="list-style-type: none"> <li>1. (a) Benedik, Jiri Jan (George).....</li> <li>    (b) male [REDACTED]</li> <li>2. [REDACTED]</li> <li>3. 1416 hours, Sun. Sept. 5/76</li> <li>4. 50' west of Ontario Place</li> <li>5. No. Wind- 320°, 16Knots to 21 knots</li> <li>6. aircraft crash CNE Air show</li> <li>7. Water 10°C, Air 17°C.</li> <li>8. 4 to 5 minutes</li> <li>9. Robert Riekstins, T.H.P.</li> <li>10. No.</li> <li>11. No.</li> <li>12. No.</li> <li>13. No - none.</li> <li>14. [REDACTED]</li> <li>15. [REDACTED]</li> <li>16. [REDACTED]</li> <li>17. Nil.</li> <li>18. [REDACTED]</li> <li>19. [REDACTED]</li> <li>20. None.</li> <li>21. [REDACTED]</li> <li>22. None.</li> <li>23. Respiration and pulse restored.</li> </ol> |
|---|--|

s.19(1)

CASE HISTORY

At 1415 hours Sunday September 5th 1976 a DeHavilland Fox Moth bi-plane performing at the C.N.E. air show apparently lost control and crash landed in an upright (pan cake) attitude facing in a northwest direction about 30 to 50 feet west of the west island off Ontario Place and came to rest in about 10 to 15 feet of water just northwest of the helicopter launching pad.

At 1416 hours, T.H.P. boats #'s 10, Rescue 1 and 2 outboards responded and on arrival of L/H R. Riekstins & L/G D. Shaw, a person on shore indicated that a person was in the aircraft, which at this time was submerged with only the tail showing above water.

R. Riekstins immediately dove into the water and found the victim strapped into the forward seat and motionless.

On the 3rd dive Riekstins was able to release the seat belt and pull victim from the aircraft and to the surface.

The victim was put aboard the Sunnyside Boston whaler and P/O B. Butler started mouth to nose A/R (due to injuries to victims mouth). External cardiac massage was started by L/H E. Follert as the victim was being transported to the First Aid station at C.N.E. Aquarama boat ramp.

On arrival at ramp the victim abruptly showed signs of life, breathing laboured but steady and pulse weak but steady.

Victim was transported by Metro ambulance #904 with M.T.P.D. escort. L/H E. Follert assisted in ambulance and accompanied victim to Toronto Western hospital.

Staff Dr. Wilkinson and staff attended victim at hospital.

Pilot of aircraft who had also sustained injuries was taken to St. Josephs hospital for treatment for [REDACTED]

Pilot was a Garth Martin [REDACTED]

Victim was a passenger and aircraft mechanic employed by Wardair.

Aircraft was removed from water at about 2000 hours on Sun Sept 5/76 by Derrick #50 with the assistance of T.H.P. Scuba divers Hales & Kennedy.

At time of this report 1000 hours Sept. 6th 1976 the victim was reported to be in critical condition.

Examined and forwarded, Sun 6th Sept. 1976

3/Officer R. Carroll Officer in Charge.

  
Superintendent of Toronto Harbour Police.

E. G. Nobrey.


APPENDIX

PLANNED MANEUVERS FOR THE  
AIR SHOW


---

WARD AIR "FOX"


1. Two 360's




2. LAZY EIGHT WITH PRACTICALLY A STALL TURN AT EACH END



3. LAZY EIGHT IN OPPOSITE DIRECTION.





4. STALL TURN AND FINAL FLY PAST



APPENDIX *V*

PHOTOGRAPHS







000062




000063



000064

- V. K. McPHERSON
- W. G. MacSWAIN
- S. A. HUSSON
- A. J. McWELL
- R. A. Phillips
- J. D. BURTON
- B. ASTON
- C. M. BATCHELOR
- R. D. GOODBRAND
- R. BISHOP
- S. M. LIU



# FLIGHT SAFETY BULLETIN

BOX 734, STATION B, OTTAWA, CANADA K1P 5S4  
THIS LITERATURE MADE POSSIBLE BY VOLUNTARY CONTRIBUTIONS TO THE COPA FLIGHT SAFETY FUND

January 1977

No. 108

*Please note?*

## FLY HIGH

Imagine for a moment that you are about to perform a steep 720° turn for your commercial flight test. Think of all the steps necessary for a satisfactory performance. Complete the maneuver in your mind, roll out to level flight and then let's discuss it. Did you perform the maneuver at a safe altitude? Clear traffic? Where did you look to maintain level flight? Did you use 50 degrees of bank? Were you able to hold the altitude within 100 feet? What would you do if you were losing altitude? Did you add power as the bank increased? The fact that this maneuver is frequently failed on commercial and flight instructor flight tests because of inability to maintain 100 feet altitude plus or minus is not the point of this article. In recent months there has been an alarming number of low flying complaints and accidents resulting from low altitude maneuvers. The majority of these incidents involve pilots who have flown in a manner far beyond their ability. If 200-hour pilots have trouble demonstrating steep turns without losing 100 feet of altitude while watching the nose of the aircraft to maintain proper pitch altitude, how can he be expected to make steep turns at 50 feet above the ground while watching persons or events on the ground. Pipeline patrol pilots must obtain waivers to fly at lower altitude, usually 500 feet AGL. Some of the most proficient pilots in the country who fly aerobatic demonstrations at airshows are required to demonstrate their ability for years before being allowed to perform at altitudes below 500 feet. In spite of this, each week reports are received which indicate inexperienced pilots are operating aircraft within 100 feet of the ground. Some aerodynamics and illusions should be discussed at this point.

When an aircraft is banked, lift must be increased in order to maintain level coordinated flight. Accompanying any increase in lift is the penalty of induced drag. In other words the force we produce when we pull back on the stick is not straight up but rather up and back. The "up" part is lift; the back part is induced drag. Undesirable as it is, it cannot be avoided. The chart shows that induced drag is increased 300% in a 60° banked turn. Unless you have sufficient horsepower to overcome a 300% increase in drag, your airspeed will start to decrease. Now, at a time when the airspeed is decreasing, the stall speed is increasing. An aircraft that normally stalls at 50 MPH will stall at 100 MPH if placed in a 75 degree bank turn. It will stall at 100 MPH in something less than 75 degrees of bank if it sustains heavier "G" forces because of turbulence on rough control handling.

So much for aerodynamics: Now for the illusions. For the sake of this discussion, wind shear and its effects are not being considered. Although the aircraft itself is not affected differently whether flown upwind or downwind, its path over the ground is affected. An aircraft making a 360 degree constant bank turn will not follow a circular path over the ground in anything but calm air. If wind is present, the rate of turn must vary in order to stay in one location, such as a pilot might do to circle his home to "thrill the folks". If he is operating at a low altitude, the ground becomes one of the pilot's main references as he attempts to maintain a perfect circle, and less and less time is spent looking for pitch information or traffic. As he turns from an upwind direction to a downwind direction, three things happen that could affect his judgment.

1. His groundspeed increases, developing a false sense of security since he thinks his airspeed has increased.
2. Because of the aircraft's drift into the center of the circle, the rate of bank may be increased in order to see the point of interest. The steeper bank tightens the turn and . . .
3. The most disturbing element is the illusion that the aircraft is in a severe slip. If the illusion is accepted, the pilot will correct the slip automatically by applying bottom rudder which tends to cause further overbanking which he compensates for by opposite aileron. This can progressively deteriorate until a stall/spin configuration is reached at too low an altitude to recover. This is not just a theory. It has happened all too frequently in traffic patterns when a turn from a left downwind to final takes place at a low altitude with a left crosswind on final.

Records of the earliest flights by the Wright Bros. describe an incident near Dayton, Ohio, where the brothers were preparing to demonstrate a roundtrip flight for the U.S. Army. Wilbur was flying the new craft in a circular path when it seemed to develop severe instability — the ground seemed to rush up to meet him. Shaken, he landed to discuss the problem with Orville who had watched the flight which appeared normal. They decided to fly the same course again with a piece of string tied in front of the pilot in the same way sailplane pilots do today in order to obtain first hand slip-skid information. The flight proved the stability of the aircraft and unleashed the problem of the "downwind turn". This article was not designed to help you fly safely close to the ground. Its sole purpose is to convince you to see Canada from a safe altitude. Buzzing, hedge hopping, low altitude maneuvers by inexperienced pilots are dangerous and stupid. Flying loses supporters each day because of inconsiderate low flights. Don't add to this problem — don't become a statistic.

### STATIC ELECTRICITY IN CLOTHING

Recently, a pilot received first- and second-degree burns when his underclothes were ignited by static electricity. He was preflighting a Twin Bonanza which had just been refueled and moved into the hangar because of cold weather. The fuel expanded as the temperature increased. When the pilot opened the fuel cap during his inspection, fuel gushed out, soaking his arm and legs. The pilot went immediately to the locker room and removed his Nomex flight suit. Static electricity ignited the fumes as he started to remove his winter underwear.

In another incident, a fuel tanker operator received second- and third-degree burns when the fuel he was recirculating was ignited by static electricity. He was wearing a cotton uniform and a nylon jacket.

Outer clothing builds a charge not only by absorbing part of the body charge but also by rubbing against the body and underwear. When the charged clothes are removed, the electrical tension or voltage increases to a danger point. If the clothes are wet with fuel, the danger is even greater. Fuel-soaked clothes can burst into flames as they are removed. Sparks can also be generated by worn footwear. Soles so worn that nails are exposed present a serious danger since fuel spills in refueling areas are common and fuel vapors near the ground ignite easily.

Recent tests by the Air Force indicate that the buildup of static electricity does not differ greatly by uniform type. A blend or synthetic uniform is no more dangerous than a pure cotton uniform. The tests do show that it is possible to exceed 2,650 volts when the uniform is removed. Theoretically, 2,650 volts can ignite gasoline-air mixtures (vapor). Other variables such as temperature and humidity may affect the static buildup, but regardless of this, the tests indicate there is a potential danger and it differs little with uniforms or mixes of uniforms.

If fuel gets on your clothes, leave the refueling area immediately and deluge or thoroughly soak the clothes before you take them off. If there is not enough water at the site to soak the clothes thoroughly, ground yourself to a piece of grounded equipment by taking hold of it before you take off the fuel-soaked clothes.

*Flying is for those who are willing to be just a little more careful*

CF-10513

<sup>J.</sup>  
Interview with Mr. Benedik -  
Passenger on board CF-105B



Mr. Benedik was interviewed Sept 3 1976  
He stated he did not remember much about the flight  
He could remember arriving at the Island  
airport, ~~at~~ getting on board CF-105B, and  
fastening his seat belt.

He stated that it had been pre-arranged  
with Mr. Martson that he would ride as  
passenger, and that he had been on board the  
aircraft during the Niagara Ski show.

Mr. Benedik stated he had worked on CF-105B  
and that to his knowledge there were no problems  
with the aircraft.



P.O. Murray Roberg was present during the  
interview.


s.19(1)

*Steve*

s.19(1)



BENEDIC



CFB Tor. - 6336200  
(401)

1330 - 1430 - 8000'

1330 1345 - 150 1976

CANADIAN INTERNATIONAL AIR SHOW

FLIGHT SCHEDULE

September 3, 4, 5, 6

7500' - 5 mi.

FULL Show Rev # 4 Date: 31 Aug 76 WX: CIG 7500 Vis 5 NM

#	EVENT	A/C TYPE & NO	ARPT	DURATION			REMARKS
				On Stage	Time	Off Stage	
1	Canadian Forces Call signs	CF 104 (2) ZIPS	TR	1330:00	7:00	1337:00	Fri-Sat-Sun Only Hold if req'd 089/15 "5T" Tacan Alt as req'd
1A	US Air Force Thunderbirds	T38 Talon (5)	TR	1330:00	12:00	1342:00	Mon Only Hold if req'd 089/15 "5T" Tacan Alt as req'd
2	US Air Force	B-52	RME	1337:00	5:00	1342:00	Fri Only Hold if req'd 089/15 "5T" Tacan Alt as req'd
2A	Helicopter Demo	Bell Long Ranger	TZ	1337:00	5:00	1342:00	Sat-Sun Only
3	Quebec Gov't Air Service	CL 215 (2) Smoky 142	TZ	1342:00	5:00	1347:00	Hold east of TZ if req'd
4	US Navy	P-3 Orion	ZD	1347:00	4:00	1351:00	Fri-Sun Only Hold if req'd 089/15 "5T" Tacan Alt as req'd
4A	Helicopter Demo	Hughes 500	TZ	1347:00	4:00	1351:00	Sat-Mon Only
5	Descenders Parateam	Cessna 180 6 jumps (3+3) 2 aircraft	TZ	1351:00	5:00	1356:00 to 1325	Streamer drop prior to show - Hold in position at jump alt

1976

CANADIAN INTERNATIONAL AIR SHOW

FLIGHT SCHEDULE

September 3, 4, 5, 6

FULL Show Rev # 4 Date: 31 Aug 76 WX: CTG 7500 Vis 5 NM

#	EVENT	A/C TYPE & NO	ARPT	DURATION			REMARKS
				On Stage	Time	Off Stage	
6	Ed Mahler	PJ-295 <i>P.J.</i>	TZ	1356:00	8:00	1404:00	
7	US Air Force	F-15 Eagle <i>Eagle</i>	TR	1404:00	6:00	1410:00	Hold if req'd 089/15 "5T" Tacan Alt as req'd
8	Oscar Boesch Peter Ober	ASW Sailplane Cessna 172	TZ	1410:00	5:00	1415:00	Tow-by during CL 215 Hold in position at release altitude (3,000 ft)
9	US Army Silver Eagles	Hughes 500 (7) <i>silver</i>	ZD TZ	1415:00	15:00	1430:00	Fri-Sat Only Form up and hold Gibraltar Point
9A	Garth Martin	Wardair Fox Moth	TZ	1415:00	4:00	1419:00	Sun-Mon Only
9B	Parade of Helicopters	Various	TZ	1419:00	6:00	1425:00	Sun-Mon Only
9C	Canadian Warplane Heritage	Harvards (4)	TZ	1425:00	5:00	1430:00	Sun-Mon Only Form up and hold east of TZ
10	Frank Tallman	Grumman Duck <i>Duck</i>	TZ	1430:00	8:00	1438:00	
11	Canadian Forces Skyhawks	Otter <i>2+2+5</i>	TZ	1438:00	8:00	1446:00	<sup>7500</sup> Streamer drop during Ed Mahler - Hold in position at jump alt (8,000 ft)

1976

CANADIAN INTERNATIONAL AIR SHOW

FLIGHT SCHEDULE

September 3, 4, 5, 6

FULL Show Rev # 4 Date: 31 Aug 76 WX: CIG 7500 Vis 5 NM

#	EVENT	A/C TYPE & NO	ARPT	DURATION			REMARKS
				On Stage	Time	Off Stage	
12	Canadian Forces Air Reserve	Otters (3) Tracker Dakota Twin Otter <i>Otters</i>	<del>ZH</del> TZ	1446:00	4:00	1450:00	Form up and hold east of TZ
13	Gerry Younger	Pitts Special	TZ	1450:00	8:00	1458:00	
14	Jerry Billing	Spitfire Mark IX <i>Spit.</i>	<del>ZD</del>	1458:00	5:00	1503:00	Hold east of TZ if req'd
15	US Air Force	SR 71 Blackbird	Beale YZ	1503:00	5:00	1508:00	Fri-Mon Only Hold if req'd 089/15 "5T" Tacan Alt as req'd
15A	Canadian Forces JATO Demo	C-130 Hercules	ZD	1503:00	5:00	1508:00	Sat-Sun Only Hold if req'd 089/15 "5T" Tacan Alt as req'd
16	WW II Warbirds	Mitchell Corsair Mustang Firefly Lightning	TZ	1508:00	8:00	1516:00	Form up and hold east of TZ
17	Canadian Forces	CF 5 (5) <i>Pogo</i>	TR	1516:00	5:00	1521:00	Hold if req'd 089/15 "5T" Tacan Alt as req'd
18	Canadian Reds Rod Ellis Bill Cowan	Pitts Special (2)	TZ	1521:00	10:00	1531:00	Form up and hold east of TZ
19	Royal Air Force	Vulcan <i>Vulcan</i>	TR	1531:00	6:00	1537:00	Hold if req'd 000070 ; "5T" Tacan Alt as req'd

1976

CANADIAN INTERNATIONAL AIR SHOW

FLIGHT SCHEDULE

September 3, 4, 5, 6

FULL Show Rev # 4 Date: 31 Aug 76 WX: CIG 7500 Vis 5 NM

#	EVENT	A/C TYPE & NO	ARPT	DURATION			REMARKS
				On Stage	Time	Off Stage	
20	de Havilland Demo	Dash 7	TZ ZD	1537:00	4:00	1541:00 <i>Seabourgh Spt</i>	Fri-Sat Only Hold east of TZ as req'd
21	Joe Hughes Steve Trevor	Super Stearman	TZ	1541:00	8:00	1549:00	Fri Only
22	Canadian Forces Snowbirds	Tutors (9)	SN				Hold if req'd 170/10 "5T" Tacan Alt as req'd
				1549:00	23:00	1612:00	Fri
				1541:00	23:00	1604:00	Sat
				1537:00	23:00	1600:00	Sun, Mon
<p><u>NOTES:</u></p> <p>#1 Canadian Warplane Heritage Harvards will be providing pre-show fly-bys along the waterfront outside breakwater.</p> <p>#2 Back-up segments if required will be provided by:</p> <ul style="list-style-type: none"> <li>- Canadian Warplane Heritage Harvards</li> <li>- Canadian Forces' Rescue Helicopter</li> <li>- Civil Helicopters</li> </ul>							

1976

CANADIAN INTERNATIONAL AIR SHOW

FLIGHT SCHEDULE

September 3, 4, 5. 6

LOW Show Rev # 4 Date: 31 Aug 76 WX:CIG 1500 Vis 3 NM

---

---

Note:

The Flight Schedule for the LOW and FULL Show are essentially the same. The difference being that some routines in high performance aircraft and para demonstrations will be modified or replaced to accommodate the reduced ceiling. Stage times will remain the same.

1976

CANADIAN INTERNATIONAL AIR SHOW

FLIGHT SCHEDULE

September 3, 4, 5, 6

FLAT Show Rev # 4 Date: 31 Aug 76 WX:CIG 2500 Vis 3 NM

---

---

Note:

The Flight Schedule for the FLAT Show and FULL Show are essentially the same. The difference being that some manoeuvres in high performance aircraft may be limited.

1976

CANADIAN INTERNATIONAL AIR SHOW

FLIGHT SCHEDULE

September 3, 4, 5, 6

LIMITED VIS Show Rev # 4 Date: 31 Aug 76 WX: CIG Unlimited Vis 2 NM

#	EVENT	A/C TYPE & NO	ARPT	DURATION			REMARKS
				On Stage	Time	Off Stage	
1	Canadian Reds Rod Ellis Bill Cowan	Pitts Special (2)	TZ	1330:00	10:00	1340:00	Form up and hold east of TZ
2	Helicopter Demo	Bell Long Ranger	TZ	1340:30	5:00	1345:30	
3	Descenders Parateam	Cessna 180	TZ	1346:00	5:00	1351:00	Streamer drop prior to show - Hold in position at jump alt
4	Ed Mahler	PJ-295	TZ	1351:30	10:00	1401:30	
5	Quebec Gov't Air Service	CL 215 (2)	TZ	1402:00	7:00	1409:00	Form up and hold east of TZ if req'd
6	Oscar Boesch Peter Ober	ASW Sailplane Cessna 172	TZ	1409:30	5:00	1414:30	Nil tow-by Hold in position at release alt (3000 ft)
7	Gerry Younger	Pitts Special	TZ	1415:00	10:00	1425:00	
8	Canadian Warplane Heritage	Harvards (4)	TZ	1425:30	7:00	1432:30	Form up and hold east of TZ
9	Canadian Forces Skyhawks	Otter/Huey	TZ	1433:00	8:00	1441:00	Streamer drop during Sailplane
10	Frank Tallman	Grumman Duck	TZ	1441:30	10:00	1451:30	

1976

CANADIAN INTERNATIONAL AIR SHOW

FLIGHT SCHEDULE

September 3, 4, 5, 6

LIMITED VIS Show      Rev #  4       Date:  31 Aug 76       WX:  CIG 7500       Vis  2       NM

#	EVENT	A/C TYPE & NO	ARPT	DURATION			REMARKS
				On Stage	Time	Off Stage	
11	Jerry Billing	Spitfire Mark IX	TZ	1452:00	5:00	1457:00	
12	Garth Martin	Wardair Fox Moth	TZ	1457:30	4:00	1501:30	
13	de Havilland Demo	Dash 7	ZD TZ	1502:00	4:00	1506:00	Fri-Sat Only Hold east of TZ as req'd
13A	Canadian Forces Helicopter Demo	Voyageur Huey	TZ	1502:00	4:00	1506:00	Sun-Mon Only
14	Joe Hughes Steve Trevor	Super Stearman	TZ	1506:30	10:00	1516:30	Fri Only
15	WW II Warbirds	Mitchell Corsair Mustang Firefly Lightning	TZ	1517:00	10:00	1527:00	Fri Form up and hold east of TZ
				1506:30	10:00	1516:30	Sat-Sun-Mon Form up and hold east of TZ
16	US Army Silver Eagles	Hughes 500 (7)	ZD TZ	1527:30	15:00	1542:30	Fri Form up and hold Gibraltar Point
				1517:00	15:00	1532:00	Sat Form up and hold Gibraltar Point

ANNEX "C" to  
MEDICAL SUPPORT  
FOR CIAS 1976

DAILY CREW AND PASSENGER LISTING

C O N F I D E N T I A L

FLIGHT MANIFEST

DATE OF FLIGHT: \_\_\_\_\_

NAME (FULL)

S.I.N.

DOB

EMERGENCY NOTIFICATION

CAPTAIN:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

AIR CREW:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

PASSENGERS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

NOTE: This form is for confidential medical use only and under normal circumstances will be destroyed at the end of the day's flight operation.

C O N F I D E N T I A L

(When Completed)

## To Spin or Not to Spin!

**T**HERE WAS A time, only a couple of decades ago, when pre-solo student pilots were given training in spins before being allowed to wing it on their own. The theory was that by introducing the concept of spins early in the game, student pilots would respect stalls and what could happen if things were allowed to get out of hand. And, if a spin were to develop accidentally, they would at least have a rudimentary knowledge of how to break out and recover.

This notion paralyzes many people in the flight training business today, who are aware of the apprehension most students have of simple, straight-ahead stalls, let alone a full-blown spin. There is little overall enthusiasm for spin training, despite the "let's bring them back" urging of old-time aviators.

To understand the need for early-on spin training back in the '40s, we must remember the vast differences between flying then and now. The basic light training aircraft was a two-place tail-dragger, fabric-covered, 65 horsepower, no starter, no radio, no stall warner, very few instruments. The emphasis was placed on *flying* this sometimes obstinate beast, not holding a 25° bank angle on instruments or communicating with Stage III radar. It hasn't been so long ago that airplanes were not as safe and easy to fly, especially at slow speeds, due to design compromises that gave more leeway to performance rather than safety. By comparison, today's aircraft are like filter-tip cigarettes; the flavor's gone, but at least they're safer. After all, in the late '30s and '40s it was more or less expected that light sporting airplanes would be used for such aerobatics as they might be capable of loops, snap-rolls, spins, hammerheads and the like. No wonder then, that the desirability of spin training persisted on into the 1950s.

In addition, the concept of flight training was much more "open" in those days, with little or no supervision by instructors after solo. Since the light no-electrical trainer would be used primarily for 70-mph cruising in a 200-mile radius of home, as soon as the student mastered enough of flying to take it around by himself he had just about seen it all. With the admonition not carry any passengers, he was free to "build time" pretty much as he chose toward the 40 hours needed to take a private checkride.

Thus, spin training was considered necessary as part of pre-solo instruction, in order to prevent the untimely loss of an unsupervised student during this time-building period. Also, a spin demonstration was part of the private checkride.

There came the day every student expected and dreaded, when his instructor came out of the line shack carrying two parachutes and announced that this was the day he was to learn about spins. Cramped into a Cub with the bulk of an unfamiliar chute, he climbed the airplane laboriously to an extra couple of thousand feet of altitude, where the instructor kicked the bird over into a "tails-pin." Then, after counting a turn or two, recovery would be made by jabbing opposite rudder and forward stick, and the student was free to try it himself, if his lunch survived the first go-round. Being familiar with Cub-style stalls and their vigorous recovery technique, most students quickly learned to enter and recover from spins, and initial spin training was not as formidable a task as it might seem today.

In the evolution of flight training, practical instruction has taken the place of teaching simple control of the airplane to the end that today's students are expected to learn extensive cross-country navigation procedures using radio aids, as well as the rudiments of communication with various ATC agencies. Basic instrument proficiency must be developed, and specialized operations beyond normal flying have to be covered. There is little or no "time building" any more, just a jam-packed program without any let-up which most students are lucky to complete in 50 hours. After solo, the student has little more freedom than before, having only the right to be dispatched by a CFI to practice specific operations on his own.

To the credit of the designers of both pilots and airplane, accidental spins




Illustration: Stephen Kidd

Document disclosed under the Access to Information Act / Document divulgué en vertu de la Loi sur l'accès à l'information

don't happen very often. The FAA still enough of a problem to be bothersome. Aircraft are now certificated under specified limitations, which more often than not include "All acrobatics, including spins, prohibited." Such utility category aircraft that are approved for spins are designed with just enough control travel to permit an adept pilot to do the maneuver, not enough to penetrate deeper into the stall. In many cases, a blast of throttle is needed at entry to provide enough yaw to initiate the spin.

Most FBOs do not want their aircraft spun, even when it is within the airplane's limitations, due to the wear and tear on the attitude and directional gyros. These instruments have gimbal stops that are reached in the extreme attitudes of spins, and tumbling of the gyros can result, requiring some minutes of straight and level flight to erect the gyro once more. While today's newly-manufactured gyros withstand much more punishment than the old war-surplus jobs used up through the mid-'60s, they still have limits and can be damaged by prolonged aerobatics. Gyro damage, of course, was seldom a problem in J-3 Cubs.

Spins are not required for any FAA flight training, other than that given for Flight Instructor, Airplane, and even then a logbook entry showing spin instruction given by a CFI may be accepted, without spins being demonstrated on the checkride. Small wonder, then, that many instructors dislike the thought of spins, having only been lightly introduced to them about as much as a pre-solo student of the '40s. With the industry's reluctance to scare any prospective students away, spins are seldom mentioned outside the ground training manual. The FAA has taken a harder line on spins in recent years, encouraging instructors to do as they see fit, as long as the airplane is certificated for spins, though there is little sentiment for actually putting spins back in the curriculum.

Today, we teach how not to spin, by detecting a stall as it develops and recovering into straight and level flight. In a Cessna 150 most students will experience a power-on stall that gets away from them, and the need for rudder use is rather graphically brought home, as the wing goes vertical, the windshield fills with trees, and all the aileron in the world does no good. In 15 years, I have had only one student actually enter a full spin, requiring my assistance to break. When a stall goes awry, I usually just let the student spiral on down, until he answers my pleas for opposite rudder and gets it out by himself. Then we have a little lecture. . . .

Often, however, a student expresses an interest in learning about these fearsome maneuvers which he has heard described in story and song, and asks me if I will do him one. Do him one, heck, I'll make him do one! After all, we've been teach-

in spins all along, it only takes a little more effort to perform a spin. In most cases, a one-turn spin suffices for familiarization, since precision spins of three turns or more are actually an acrobatic maneuver, not a training item.

The spin itself, of course, is simply a stall in which the aircraft is rotating about the vertical, or yaw, axis. It is yaw that initiates the spin, either accidentally, such as with an uncoordinated, ball-out-of-center entry to the stall, or a deliberate tromp on the rudder as the stall breaks. Avoiding spins is easy; at the moment of stall the ailerons should be neutral and the ball nearly centered. This should produce, in modern aircraft, a mild enough stall that a recovery can be made long before any spin-tendency of the aircraft can take hold. Antagonize the airplane with cross-control at the moment of the stall, however, and you'd better look out.

As long as the stall is maintained, the spin will continue, but most spin-approved light airplanes will recover quickly, assuming loading is within proper C.G. limits. Entry is accomplished through a simple power-off stall, applying and holding full rudder in the direction of the desired spin (usually to the left) as the stall breaks. As the pilot holds the yoke back to maintain the stall, the airplane will probably drop one wing over into a steep bank; during this

incipient phase, lasting perhaps a half-turn, the airplane is giving you one last chance to back out, as it is actually in a steep descending turn, rather than a true spin. Ailerons should be kept neutral and the nose will continue to drop into what looks to be a vertical nose-down position despite full-up elevator. The rate of turn suddenly accelerates as the nose stabilizes into the spin position, and the windshield fills with whirling section lines.


The Cessna 150 actually spins in a 70° nose-down attitude, although it looks worse, and takes about two seconds per turn, losing 250-300 feet per turn. If you multiply out that rate of descent, you will see why prompt recovery is vital, and why 3000 feet AGL is little enough as an entry altitude. Count the turns aloud and begin recovery about a quarter-turn before the desired stopping point. Don't be gentle kick and hold full opposite rudder, followed by a vigorous shove forward on the stick. The throttle should have been at idle, if it wasn't pull it back before starting the recovery. Since the recovery attitude will be nearly vertical and the airplane is now free to accelerate, care must be taken to pull out of the dive rapidly but smoothly, to avoid undue build-up of airspeed and stress on the airplane. During the spin the airplane is stalled and there is minimal G-load, but the pull-out from the recovery will

probably place three G's on the airplane, even if done smoothly.

Experimentation in modern airplanes will lead you to believe that recovery can be accomplished by merely relaxing rudder pressure and maintaining full back stick to pull out quickly. Don't let this become a habit; there may come the day such technique won't work, and it is better to practice using the standard NACA recovery outlined above rather than short-cutting. Not all airplanes and all loadings react the same. Don't be a test pilot — perform spins only in airplanes specifically designed for them, with loading well within limits. If you experience an increasing G-load while entering or during a spin, roll out and recover immediately, since you are not in a spin, but a diving spiral, which can put much more damaging stress on the airplane if allowed to continue.

By all means, have a knowledgeable instructor go through spins with you, don't attempt them the first time without guidance. Parachutes no longer are required if the spins are done for training purposes. Spins can be just another maneuver when thoroughly understood by the pilot, and having mastered them gives one further confidence of having full control in all situations, however extreme. While no longer a pre-solo hazard to a student's composure, they still are useful tools of learning.

## ROBERTSON EQUIPPED 400'S DELIVER



- Shorter Takeoffs & Landings
- Slower Liftoffs & Approaches
- Faster High-Altitude Climb Rates
- Longer Life for Brakes, Wheels, Tires & Structure
- Greater Productivity
- Safety — Safety — Safety

Call toll-free  
**(800) 426-7692**

Robertson Aircraft Corporation  
 839 W. Perimeter Road, Renton, WA 98055

I currently own \_\_\_\_\_  
 or intend to buy \_\_\_\_\_  
(Make & Model of Aircraft)

Please send me:  
 Brochure for Robertson 400-Series A/C  
 Bulletin — "How To Save Time & Money With Robertson"

Name \_\_\_\_\_  
 Street \_\_\_\_\_  
 City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_  
 Phone (Home) \_\_\_\_\_ (Office) \_\_\_\_\_



"THE EXTRA MARGIN OF SAFETY"  
**ROBERTSON AIRCRAFT CORPORATION**

Headquarters: Renton Municipal  
 Airport, Renton, WA 98055

(206) 228-5000 Cable: RSTOL

Dedicated to the betterment of general aviation.

H. MCPHERSON  
 S.A. MUSSOY  
 A.J. MCDONELL  
 R.A. PHILLIPS  
 J.P. ANDONEY  
 J.D. BURTON  
 R.D. GOODBRAND  
 C.M. BATCHELOR  
 B. ASTON



# FLIGHT SAFETY BULLETIN

P. O. BOX 734 STATION B, OTTAWA, CANADA K1P 5S4  
 THIS LITERATURE MADE POSSIBLE BY VOLUNTARY CONTRIBUTIONS TO THE COPA FLIGHT SAFETY FUND

December 1976

No. 107

## TIPS ON THE USE OF AILERONS AND RUDDER

Recent stall/spin accidents indicate improper use of rudders. Through coordinated use of rudder and ailerons, involvement in this type of accident can be greatly diminished.

The slip stream helps the rudder maintain its effectiveness even at slower speeds when much of the effectiveness of the ailerons has been lost. The rudder, therefore, is the tool for coordinated control as the aircraft approaches, enters, and recovers from a stall. In the "olden days", students were taught from the beginning that approaches to and recoveries from stalls were done with the rudder only, while keeping the ailerons in neutral position. This changed more than a decade ago when the FAA flight test guide started allowing the use of ailerons in these situations. This came about because modern aircraft generally have less elevator travel and do not stall as completely. Also, well designed ailerons are still effective at lower speeds. It was never intended, however, to omit using the rudder in stalls and recoveries therefrom.

To have the proper insight for flight control, pilots need to understand lift and drag properties of ailerons. When ailerons are streamlined (neutral), both wings generally display the same characteristics (Figure A).



Figure A

Rolling the aircraft, however, to the left for example, the left aileron comes up and the right one goes down. (Figure B)



Figure B

Attempting to raise a wing by applying down aileron creates more lift on that wing, by increasing the camber (curvature) of the wing. The increase in camber also increases the drag on the wing with the down aileron. If this increase in drag is not corrected by aileron design or proper application of rudder, the aircraft will yaw toward the wing with the down aileron (adverse yaw). This yawing action will cause a decrease in the speed of the wing in relation to the other wing. When operating near stall speeds, this yawing action, with the difference in speed of the two wings, can result in an earlier stall on the wing with the down aileron. This early stall on one wing will greatly increase the probability of a spin.

The above is not difficult to demonstrate. We can, on most single-engine, propeller-driven aircraft, easily maintain directional control in a straight-ahead, power stall with the rudder alone. On the other hand, if you put your feet on the floor and attempt to use only ailerons to maintain heading and/or the wings level through the same stall, you will have a much less responsive aircraft and, at least some of them, will spin toward the lower aileron as the stall occurs. This proves that below certain speeds ailerons become ineffective. A demonstration like the above should convince most pilots that proper use of rudder would help prevent stall/spin accidents. Rudders and ailerons should be used together for coordinated flight, and while modern aircraft do respond to ailerons alone, omitting the rudder can spell disaster at slow speeds. The often forgotten training maneuver of delayed stall recovery, using rudder alone to maintain heading and level wings as the nose of the aircraft passes through the horizon, was an excellent one. It is no longer used since it is not a required flight maneuver, but it is a good demonstration and confidence building maneuver.

A pilot who flies through a stall or slow flight regime without using rudder at all, fighting for control, slamming the ailerons from stop to stop, is not in full control of the aircraft. Unfortunately, this is seen with increasing frequency. As pilots, we should make an effort to be on the lookout for this mistake and start using the rudder anytime the ailerons are being deflected. Ailerons and rudder work together for coordinated flight, and the habit must be built with conscious effort if we are to remain masters of our aircraft throughout the speed envelope.

**"KNOW YOUR AILERONS BUT DON'T FORGET THE RUDDER!"**

### SAFETY MEANS FLYING HIGH

Pilots pay high insurance premiums because the odds are not good enough, yet so many fly low where the odds are poorest. From a VFR general aviation viewpoint the factors listed below are affected by altitude.

1. Traffic (collision exposure) is less at higher altitudes.
2. Visibility for "see and be seen" concept improves with altitude, notably so around 8,500 feet.
3. Air contaminants (salt air, auto pollution, factory smoke, etc.) corrode aircraft, affect engine and instrument performance and personal well being. The first 1,500 feet should be avoided.
4. The higher you are, the smoother the air; resulting in more accurate instrument and navigation flying, less airframe stress and better pilot performance.
5. Communication range improves with altitude. Try calling your FBO on 123.0 a hundred out, once at 1,000 feet and again at 10,000 feet. The number of people who will hear you on 121.5 is square when you double your altitude.
6. Noise imposed on the people lessens with altitude, especially the first several thousand feet. Above 7,000 feet the public won't know you are up there.
7. Breathing air does not become a factor until above 6,000 feet and shorter flights with healthy people can safely be made at 10,000.

*Flying is for those who are willing to be just a little more careful*

TZ-1

SEPT. 5/76

17:00 2

40	⊙	15+	17/05	320/20+26
30.02		cu 3		

MEMO

VAR. 8°W

15  
00  
22  
20  
000080

A/c 1458 - = 15132.0

OIL  
3 gal. 27 -28 = ~~756.0~~

FUEL  
16 gal. 115.2 11 = 1267.2

PIC07 183 71.6 = 13102.8

PASS 141 19 = 2679

BRIE CASE 10 -12.6 = -126.0

PORT. RADIO 10 70 = 700.0

TOOL KIT 10 -12.6 = -126.0

1954.2

31872.8

C of G = +16.30

5 \* 7  
11

YORK UNIVER

HEAL & FINCH

- EXCALIBUR - NEWSPAPER

BILL WILLSON

CENTRAL SQUARE

Bill Wilson

C.A.T.C.A. - ONE

CANADIAN AIR TRAFFIC CONTROL

ASS

25, STAIN CRT

WESTON ONT

M3A1-1R1

PH 638-3963

0513

MAG SWITCHES — BOTH ON.

TRIM — MIN RANGE

SEAT BELT — NO FAILURE.

~~THE~~ SHOULDER HARNESS?? — FAILURE

CONTROL STICK — JAMMED FORWARD  
& TO THE RIGHT.

ALT — 30.04

AIRSPEED INDICATOR — 0

BANK & TURN

OIL PRESS — 0

RPM — 2475

COMPASS

DH - 83C


SER# FM 28

PASS SEAT BELT — UNKNOWN NO FAILURE

PILOT SEAT BELT — UNKNOWN — NO FAILURE

- ST JOSEPH -

JOHN MILLER.  
WARA AIR OPDS.



CF D5B

~~442 - 72 -~~ 4 SEP 7. :30 PRACTICE  
442 - 72 5/SEP 7 :30

310-

PRE-FLIGHT (Commence At Port Side Of Cockpit)

- BRAKES - SET
- MAGS - OFF
- FUEL - OFF
- ELEV. TRIM - FULL AFT
- FIRE EXT. - SECURE
- FORWARD CABIN - SECURITY CHECK + SHIP'S PAPERS
- VENTURI
- PORT MAINPLANES
- PORTAILERON
- PORT UNDERCARRIAGE
- AIR SPEED INDICATOR
- ENGINE - OIL QUANTITY + CAP SECURE (LOCK PIN FORWARD)
  - COWLINGS
  - OIL LEAKS
  - PROPELLOR
  - EXHAUST
  - OIL FILTER TURNED ONE REV. (FIRST FLIGHT OF DAY)
- PROP. AREA - CLEAR
- PROP - PULL THROUGH 4 BLADES (FIRST FLIGHT OF DAY)
- FUEL - QUANTITY AND CAP SECURE, VENT CLEAR
- STARBOARD UNDERCARRIAGE
- STARBOARD MAIN PLANES
- PITOT HEAD
- STARBOARDAILERON
- (STARBOARD SIDE - CONTROL WIRES AND FUSELAGE UNDERSIDE)
- VHF ANTENNA
- ELT ANTENNA
- TAIL UNIT - CONTROL SURFACES
  - POSITION OF ELEV. TRIM
  - TAIL WHEEL
- PORT SIDE - CONTROL WIRES AND FUSELAGE UNDERSIDE

BEFORE START

- FUEL COCK - ON
- MIXTURE - RICH
- THROTTLE - FULL + FREE MOVEMENT, FRICTION
  - SET FOR START
- ALTIMETER - SET TO FIELD ELEVATION
- CARB HEAT - ON
- RADIO - SECURE
- ELEV. TRIM - FULL MOVEMENT + SET TO NORMAL
- CONTROLS - FULL + PROPER MOVEMENT
- HARNESSES - SET

STARTING

- PRIME - WITH TICKLER
- MAGS - ON (ONLY STARBOARD MAG IF HAND SWINGING)
- ELECTRIC STARTER - ON UNTIL FIRING
- HAND SWINGING - LEFT HAND TRACTOR
- OIL PRESSURE - MINIMUM 30 PSI WITHIN 30 SECS.
  - NORMAL 40-45 PSI
- ENGINE MISS-START - MAGS OFF
  - THROTTLE FULL OPEN
  - PULL PROP THROUGH BACKWARDS 6-8 BLADES

AFTER START

- CARB HEAT - COLD
- RPM - 800-1000 WARMUP
  - 1000-1200 NORMAL
- OIL - TEMP. + PRESSURE
- RADIO - ON
- ALTIMETER - SET
- GROUND EQUIP. - ALL CLEAR

TAXING

- BRAKES
- NEEDLE + BALL

RUN UP

- MAGS - CHECK FOR LIVE MAG
- RPM - 1600 (HOLD CONTROL COLUMN BACK)
- MAG CHECK - MAX DROP 100 RPM
- OIL PRESSURE - 30-60 PSI
- THROTTLE CLOSED - CHECK SLOW RUNNING
- NORMAL IDLE - 1200 RPM

BEFORE TAKEOFF

NOTE: NATURAL SWING OF THE AIRCRAFT IS TO THE RIGHT

- TRIM
- THROTTLE - FRICTION SET
- MIXTURE - RICH
- FUEL - ON + SUFFICIENT
- OIL - PRESSURE + TEMPERATURE
- HARNESSES - SECURE
- CANOPY - CLOSED / OPEN

BEFORE LANDING

- MIXTURE - RICH
- CARB HEAT - OFF NORMALLY
- FUEL - CONTENTS
- HARNESSES - SECURE
- TRIM - SET FOR LANDING
- THROTTLE - FRICTION SET

SHUTDOWN

- BRAKES - SET
- RPM - 800 FOR AT LEAST ONE MINUTE FOR COOLING
- MAGS - CHECK FOR LIVE MAG
- MAGS - OFF
- THROTTLE - OPEN SLOWLY TO FULL THROTTLE, THEN THROTTLE CLOSED
- FUEL - OFF
- RADIO - OFF
- CHOCKS - IN PLACE
- CONTROLS - LOCK WITH HARNESSES IF REQUIRED

WARDAIR "FOX MOTH" CHECKLIST

COMPLETED AND APPROVED

17 JULY 76 *[Signature]* 000087

CF - DJB

all wing fittings OK  
all strut fittings OK  
all cables checked for continuity

copy of windscreen of

fuselage buckled up at nose  
buckled down aft of

gravity feed line separated cabin  
area on impact, other fuel  
lines intact to cart

all linkages hooked up except  
cart fuel disconnected at valve  
(cable?)

pilots not buckled forward  
& twisted, seat belt OK.

key way slot gone on crankshaft  
indication of power at impact.



C-FDJB WEIGHT AND BALANCE CALCULATIONS FOR  
C.N.E. AIR SHOW FLIGHT 5 SEPTEMBER. 1976

Bases

1. Weight and Balance Report of July 6, 1976.
2. Information from Garth M. Martin obtained by telephone September 17, 1976 as to configuration, fuel, cargo, passenger, etc.

Calculations

	<u>Weight</u> <u>(lb.)</u>	<u>Arm</u> <u>(in.)</u>	<u>Moment</u> <u>(in.-lb.)</u>
1. Aircraft empty weight including: hammock seat pilot's cushion glove compartment complete upholstery metal propeller canopy top fire extinguisher starter installation ballast	1458	10.38	15134
2. Portable radio	10	70	700
3. Pilot	170	71.6	12172
4. Fuel main tank (estimated 16 gal.)	120	11	1320
5. Oil (estimated 3 gal.)	25	-28	-700
6. One passenger aft	170	19	3230
7. Brief case forward	10	-12.6	-126
8. Tool kit forward	10	-12.6	-126
TOTALS	<u>1973</u>		<u>31604</u>

Centre of gravity is 16.0 inches aft of datum.

If fuel at 4. above were reduced to 10 gallons,  
c. of g. would be 16.1 inches aft of datum.

Operational c. of g. limits are:

Forward                   12."0   aft of datum  
Aft                       17."75   aft of datum

*A. W. Breck*  
A. W. Breck

s.19(1)

FACT SHEET

GARTH M. MARTIN

YEAR  
EMPLOYED:



POSITION:

Pilot - Boeing 747 Captain

EMPLOYER:

Wardair Canada (1975) Ltd.  
6299 Airport Road,  
Mississauga, Ontario

LICENCE:



FLYING HOURS:



AGE:



# Successful Search Finds Another Fox Moth to Carry Ward's Colors

MISSISSAUGA, ONT. — A replacement has been found for the Wardair Fox Moth — CF-DJB — that crashed during the Canadian International Air Show at Toronto early in September.

Wardair 747 Captain Garth Martin of Mississauga, who was flying the Fox Moth when it crashed, located the replacement aircraft at an aircraft restoration firm in Newburyport, Mass., after a wide ranging search that began shortly after he was released from hospital following treatment for the relatively minor injuries he suffered in the crash.

George Benedik, an engineer who was riding with Martin and is now recovering from serious injuries suffered when the aircraft came down into Lake Ontario at the CNE waterfront, is one of three men who will rebuild the replacement Fox Moth, which arrived in Canada as a basket case, though complete in all essential parts.

## Toronto Harbour Policeman Honored for Rescue of Fox Moth Crash Survivor

TORONTO — The Toronto Harbour Commissioners' Award of Merit has been presented to a Toronto Harbour policeman — Robert Riekstins — who risked his life to rescue seriously injured George Benedik, trapped in the cabin of the Wardair Fox Moth which crashed into Lake Ontario during the Canadian International Air Show, Sept. 5.

The medal, presented during a recent meeting of the Board of Harbour Commissioners, bears the inscription: "Leading Hand Robert Riekstins for heroism and dedication to duty."

Riekstins, 27, who first joined the harbour police as a summer lifeguard in 1965, was a member of the police patrol boat teams keeping the harbour free of traffic during the air show. His was the first boat at the scene of the crash, and when pilot Garth Martin, who had managed to climb atop the floating fuselage, told him there was a man trapped in the submerged plane, Riekstins took off his boots and coat and dove into the water.

Riekstins rescued Benedik on his third



Robert Riekstins receives award from Commissioner Karl Jaffray.

dive. "I don't know how long the whole operation took," he said. "I had lost all track of time because my only concern was for the man trapped in the plane. I was just happy to get him out alive."

The award to Robert Riekstins marked only the second time the THC Award of Merit medal has been presented. It was struck in 1973 to honor those individuals whose outstanding feats of heroism or dedicated service on the Toronto waterfront merit special consideration.


### Airtex Distributor

FORT ERIE, ONT. — Falls Aviation Ltd. has been appointed exclusive Canadian representative for Airtex Products, Fallsington, Pa., manufacturer of aircraft interiors for the general aviation replacement market. Falls Aviation advises that the Airtex line also includes Ceconite and cotton re-cover envelopes, aircraft fabrics, tapes and Randolph finishes.

Working with Mr. Benedik will be Andy Obergfell and Dave Cameron.

The new Wardair Fox Moth is Serial No. 7, built in 1946 and one of 53 produced by de Havilland Canada as a stop-gap bushplane to meet the immediate postwar requirements of Canadian bush operators for new equipment. Max Ward, founder and now president of world ranging Wardair Canada Ltd. began his commercial aviation career with a single Fox Moth.

In addition to the 53 produced postwar by de Havilland Canada, the parent company in England produced 98 Fox Moths before WW II.



Anderson-Greenwood Aries T-250 will be produced Alexandria, Minn. facility and marketed under Bellanca name.

## Ailing Bellanca Gets \$250,000 Injection from Anderson

ALEXANDRIA, MINN. — Bellanca Aircraft Corporation's considerable success in the lightplane market with its popular Champion and Viking lines has not often in recent years been reflected by a healthy balance sheet. The company's continuing financial problems have engendered repeated power struggles at the boardroom level.

Latest development is that management of the Bellanca's Alexandria manufacturing facilities is being taken over through Mar. 31, 1977, by Anderson-Greenwood Aviation Corp., a company whose name is hardly an aviation household word but which nevertheless has aviation associations dating back to 1947.

Anderson-Greenwood Aviation, a recently activated wholly owned subsidiary of Anderson, Greenwood and Co., Houston, Texas, has, simultaneously with the execution of the new management agreement, advanced approximately \$250,000 to Bellanca to cover various operating costs. Announcement of the agreement said that additional advances under the agreement were subject to certain conditions which it was expected would be met by Bellanca "in the near future."

The management agreement follows closely an announcement of an agreement in principle whereby Bellanca will manufacture and market the Aries T-250, a high performance general aviation aircraft designed and developed by Anderson, Greenwood and Co. Implementation of the agreement is subject to the execution and delivery of definitive agreement as well as certain other conditions including the successful raising of outside financing amounting to approximately \$3 million. Manufacture of the Aries T-250, if agreement is reached, would not start until early next year.

## BREEZY

### • From Page Two

the sunlit puffs of vapour, was a different reality to that of the world below, and with it a solitude beyond description. In this solitude, Claude and I shared a unique communion. For a brief few moments he and I and our craft were one, bonded together in a purpose, which if accomplished successfully, would allow him a full five seconds of freedom from when he left Breezy until his parachute opened and returned security and safety to him.

Claude freed himself from his straps and knelt forward, one arm around my shoulders, and the other gesticulating wildly in the wind as the Punch and Judy routine began again.

The jump run had begun.

Now it was up to Breezy and me to make and maintain minor course corrections until our companion was gone. Satisfied with our position, Claude patted me and held his thumb up: "I'M GOING TO JUMP NOW!"

"HAVE A GOOD ONE!"

He crouched by the seat, sprang forward, and Breezy bounded upward freed of his weight. He sailed past in front of us, arms and legs spread-eagled. Then as though nature had seen his defiance and had commanded gravity to once more take hold of him, he descended below and to the right. As the seconds stretched on, Claude dwindled in size until after I was sure some-

Anderson, Greenwood & Co. was formed in 1947 and later in the same year introduced the Anderson Greenwood 14, a two place midwing cantilever pusher monoplane. The all-metal lightplane had a steerable tricycle gear and two vertical fins and rudders mounted on twin booms. Only a

few of the attraction. Since that time, it has maintained unbroken branches of the design through the design of related equipment contracts with the

# CLASSIFIED

## SERVICES

**INSTRUMENT**  
Repair • Overhaul  
Exchange

WRIGHT INSTRUMENTS LIMITED

2762 SLOUGH STREET  
MISSISSAUGA, ONT. L4T 1G3  
Tel. (416) 677-7151 Telex 06-988506

**TITLE SEARCHES  
FAA RECORDINGS**  
Airman Records Information. Quick accurate reports. Competitive rates. Reports wired or phoned, if requested. Airmail confirmation.  
**AIRCRAFT TITLE CORPORATION**  
1411 Classen Boulevard  
Oklahoma City, Okla. 74106, (405) 885-7960

**AEROFILITE SHEET METAL**  
Stuart Puckering  
Box 125, Collingwood, Ont., (705) 445-6050  
**STRUCTURAL REPAIRS TO ALL TYPES OF AIRCRAFT, FLOATS & SKIS**  
Specializing in Amphibians  
Salvage pick-up anywhere

**MAINTENANCE**  
Inspections — Repairs — C of A's  
We're long on experience, but short on overhead. Ask for Peter or Bev.  
**GARRISON AVIATION LTD.**  
Midland Airport, Ont. (705) 526-8451

## TRAINING

**LAKE AMPHIBIAN**  
Check-outs  
and Rentals  
**COLLINGWOOD AIR**  
Box 246, Collingwood, Ont. L9Y 3Z5  
(705) 445-1616, -1619

## WHY WASTE TIME

On Ground Training?  
Come and see us.  
**TIM AND DEBBIE Mc LAUGHLIN**  
(416) 679-4191

## KINGSTON AIR SERVICES

Norman Rogers Airport, Kingston, Ontario  
(613) 389-9000  
**CESSNA PILOT CENTRE**  
Fast efficient training — no waiting — Instructors and aircraft available — Private, Commercial, Instructor, Multi & Instrument — Accommodation on site, \$10 per week — Block time rentals.

**INTERNATIONAL GROUND SCHOOLS**  
Leavens Hangar, Toronto Intl. Airport  
Commercial, Instrument & Instructor  
Ground Briefing  
Results guaranteed  
For information contact Charles Rampulla  
at (416) 677-7549 or (416) 279-2254



**COMMERCIAL HELICOPTER PILOT TRAINING ON BELL 47 and JET RANGER**  
Contact Antony Verrico

## SE

## AIRCRAFT

Wichita-Toronto \$130 — all inclusive  
ATPL-Pilot.  
Call George (416)

## PILOT WATCH

Guaranteed \$1000  
KARL H. S.  
RR 1, Kelso, Ont.  
(416) 298-1414

## RADIO

Update your avionics prices — call or drop them for down-to-earth operators welcome — funds handled. A dealer.

## ELECTRON PARTS

Waterloo-Welch  
Tel: (519) 885-1111  
Approved by C.A.B.

## WESTON

Corp.

## ALL

Oshawa  
Oshawa  
Phon

## TI

for  
D

## Kingston

## T

## HI PILOT

000091

[REDACTED]

HOMR -

[REDACTED] / [REDACTED]

8 m m      MOVIE

s.19(1)

CF - DJ13

SEP 1976				SEPT				DIM	LUN	MAR	MER	JEU	VEN	SAM	NOV 1976			NOV		
DIM	LUN	MAR	MER	JEU	VEN	SAM	SUN	MON	TUE	WED	THU	FRI	SAT	DIM	LUN	MAR	JEU	VEN	SAM	
.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....
5	6	7	8	9	10	11	3	4	5	6	7	8	9	1	2	.....	1	2	3	4
12	13	14	15	16	17	18	10	11	12	13	14	15	16	7	8	9	10	11	12	13
19	20	21	22	23	24	25	17	18	19	20	21	22	23	14	15	16	17	18	19	20
26	27	28	29	30	.....	.....	24	25	26	27	28	29	30	21	22	23	24	25	26	27
.....	.....	.....	.....	.....	.....	.....	31	.....	.....	.....	.....	.....	.....	28	29	30	.....	.....	.....	.....

**OCT 15 OCT**  
**1976**

VENDREDI

FRIDAY

- 8:00
- 8:30
- 9:00
- 9:30
- 10:00
- 10:30
- 11:00
- 11:30
- 12:00
- 12:30
- 1:00
- 1:30
- 2:00
- 2:30
- 3:00
- 3:30
- 4:00
- 4:30
- 5:00

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_ *Call HIEN RIEU - PM* \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_ *[scribble]* \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_ *NOV -* \_\_\_\_\_

\_\_\_\_\_ *AUG - NOV* \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

DEPARTMENT OF TRANSPORT / MINISTÈRE DES TRANSPORTS  
 AIRCRAFT ACCIDENT INVESTIGATION DIVISION / DIVISION DES ENQUÊTES SUR LES ACCIDENTS

DI: POSITION OF AIRCRAFT WRECKAGE

ENLÈVEMENT DUNE L'ÉPAVE D'AÉRONEF

Accident Report No. - Rapport d'accident n°  
 Job Number (CAIE) - N° de travail (CAIE)  
 Serial No. - N° de série  
 s.19(1)

Aircraft Make and Model - Marque et modèle de l'aéronef: **Fox Moth**  
 Registration - Immatriculation: **CF-DSB**

Registered Owner or Representative - Propriétaire enregistré ou représentant: **NEW HARBOR**  
 Address - Adresse: **NEW HARBOR**

THIS IS NOTIFICATION THAT THE AIRCRAFT WRECKAGE IS DISPOSED OF, AS FOLLOWS - L'ÉPAVE DE L'AÉRONEF CONCERNÉ FERA L'OBJET DES MESURES PRÉCISÉES CI-APRÈS

- THE AIRCRAFT IN ITS ENTIRETY IS RELEASED TO THE REGISTERED OWNER OR HIS AUTHORIZED REPRESENTATIVE. L'AÉRONEF DOIT ÊTRE INTÉGRALEMENT RESTITUÉ À SON PROPRIÉTAIRE ENREGISTRÉ OU À SON REPRÉSENTANT QUALIFIÉ.
- SOME PORTIONS OR COMPONENTS OF THE AIRCRAFT HAVE BEEN RETAINED FOR THE TECHNICAL INVESTIGATION. THESE PORTIONS OR COMPONENTS ARE LISTED BELOW. - CERTAINS ÉLÉMENTS OU COMPOSANTS DE L'AÉRONEF ONT ÉTÉ RETENUS POUR LES BESOINS DE L'ENQUÊTE TECHNIQUE. CES ÉLÉMENTS OU COMPOSANTS SONT ÉNUMÉRÉS CI-DESSOUS.

*[Signature]*  
 Investigator-in-charge - Enquêteur responsable

▶ YOUR ATTENTION IS DRAWN TO THE AIRCRAFT ACCIDENT INVESTIGATION PROVISIONS OF THE AIR REGULATIONS - VOIR DISPOSITIONS DU RÈGLEMENT DE L'AIR SUR LES ENQUÊTES D'ACCIDENT D'AVIATION ◀

Part Number N° de pièce	Serial Number N° de série	Description	Since Overhaul Depuis révision	Since New Depuis neuf
<b>8 no. MOVIE OF CRASH.</b>				
<i>[Large diagonal line crossing out the table]</i>				
<b>RETURNED - OCT. 28/76. - K. Howe</b>				

AFTER THE TECHNICAL INVESTIGATION THE ITEMS LISTED ABOVE WILL EITHER BE RETURNED OR SCRAPPED / APRÈS L'ENQUÊTE TECHNIQUE LES ÉLÉMENTS ÉNUMÉRÉS CI-DESSUS SERONT RESTITUÉS OU MIS AU REBUT

IF APPLICABLE PLEASE 'X' YOUR DISPOSAL INSTRUCTIONS ON THE BLUE COPY AND MAIL THIS COPY TO: / VEUILLEZ S'IL Y A LIEU FAIRE CONNAÎTRE VOS INSTRUCTIONS CONCERNANT LES MESURES DONT L'AÉRONEF DOIT FAIRE L'OBJET EN BIFFANT LA CASE CORRESPONDANTE SUR L'EXEMPLAIRE BLEU ET QUI SERA ADRESSÉ À:

RETURN RESTITUTION  
 SCRAP REBUT

Owner or Representative - Propriétaire ou représentant: *[Signature]*  
 Date: **SEP. 20/76.**

▶ IF "RETURN" GIVE SHIPPING ADDRESS EN CAS DE RESTITUTION INDIQUER L'ADRESSE DU DESTINATAIRE ◀

**AS ABOVE.**  
 OR  
 CALL - *[Redacted]*

001654



60102  
FDJB

TO:

Transport Canada.  
Aircraft Accident Investigation.  
7TH Floor,  
Toronto-Dominion Center  
Toronto 111, Ontario.

Dear Mr Musson.

Regarding the Photo's of the For Moth at the  
Canadian International Air Show (C.N.E.).

5-11x12 AT 4:75 each \$23.75

3- 5x7 AT 2.00 each \$6.00

TOTAL 8 prints to the amount of \$29.75.

Yes the \$29.75 did come out of my pocket.

COST / RESP. 412 104	ACTIVITY 0000
WARRANT 0000	ENCUMBRANCE 4154
LINE OBJECT 4808	ORDER A-7633-TZ
I CERTIFY THAT THE TOTAL AMOUNT SPECIFIED IS A PROPER CHARGE TO MY CENTRE. 19/10/76	
<i>W. Musson</i> APPROVED COST / RESP. MGR.	

YOURS TRULY

*W. Wilson*  
WILLIAM (BILL) WILSON.

60102

To:  
Transport Canada  
Aircraft Accident Investigation  
7th Floor  
Toronto-Dominion Center  
Toronto 111, Ontario.

From:  
William Wilson  
Editor C.A.T.C.A.-ONE  
25, Strong Crt.  
Downsview, Ontario.  
H3N-1P1

29/Sept/1976

Dear Mr Musson,

This is for the Photo's of the Fox Moth  
in the Canadian International Air Show ( C.M.E. ).

5 - 11x12 at 4:75 each - 23:75

3 - 5x7 at 2:00 each - 6:00

€ print's to the amount of 29:75.


Sincerely Yours  
C.A.T.C.A.-ONE



Wm ( BILL ) Wilson  
EDITOR


We discussed cost prior to you supplying these and you stated there would not be any. We don't want you to be out-of-pocket. Does the above represent your true cost?

Please advise.



S. A. Musson

**EDDIE BLACK'S LIMITED** HEAD OFFICE: 10 DYAS ROAD, DON MILLS, ONT.



**BLACK'S CAMERAS**

PRINT CLEARLY

NAME <i>Transport Canada</i>		
NO. <i>Pa. Box 7. T.D Centre</i>	STREET	
POST OFFICE <i>Toronto, Ont.</i>	DATE <i>Oct. 14 1976</i>	
<i>3</i>	Photo Finishing	<i>12.50</i>
		<i>12.50</i>
		<i>12.50</i>
REMARKS		SUB TOTAL <i>37.50</i>
		TAX <i>0</i>
		TOTAL <i>37.50</i>

PAYMENT RECEIVED	CASH CHEQUE CHARGE X	CHARGE X NUMBER	LESS PAYMENT REC'D
<input type="checkbox"/> C.O.D.	<input checked="" type="checkbox"/> CHARGE	THIS IS YOUR ONLY INVOICE	BALANCE <i>37.50</i>
DELIVERY <i>take</i>		CUSTOMER SIGNATURE <i>S. Munro</i>	

SOLD BY <i>CONNIE</i>	STORE <i>1223 021</i>	269066
--------------------------	--------------------------	--------

RETAIN THIS SALES SLIP - IT IS YOUR ONLY RECORD OF PURCHASE AND MUST BE PRESENTED SHOULD WARRANTY SERVICE BE REQUIRED. EXCHANGE OR REFUND MAY BE MADE ONLY WITHIN FIFTEEN DAYS.

*Connie Munro*

 Paterson, Lane and MacDougall

Barristers & Solicitors

Box 411

Commerce Court North  
Toronto, Ontario M5L 1G3

416-360-8414  
Telex: 06-23163

---

Eric M. Lane

000098

---



## Hugh Whittington Intercom

### 747 to Moth

FLYING A BOEING 747 across countries and oceans is commonplace; so is a pleasant crosscountry flight by lightplane. Hardly worth a yawn. But flying a tired and out-of-rig de Havilland Fox Moth from Edmonton to Toronto, burning — or throwing — far more oil than gasoline, with true air speeds creeping up on 85 mph and bucking abnormal easterly winds all the way, is something else. That is an adventure. And, as Capt. Garth Martin, a Wardair Canada Ltd. 747 pilot succinctly put it, "That trip turned me into a bush pilot in five days."

Now, 747 captains do not, under normal circumstances, concern themselves with such mundane things as changing spark plugs, bending trim tabs, losing propeller spinners in flight, or topping off the tanks, oil and avgas. Nor is their only means of navigation a well-creased VFR map, their only link with the ground a portable Genave Alpha 100 communications transceiver. So in some quarters it will be said that Capt. Martin has joined the real world of flying, where the ingenuity of the pilot is often solely responsible for getting the damn airplane off the ground.

So, gentlemen and ladies, welcome Capt. Martin to your group, for yea and verily he has passed your test. With honors.

Max Ward, one of Canada's few honest-to-goodness heroes, first set up shop as Polaris Charter Co. at Yellowknife in 1946, and the company's sole asset was a de Havilland Fox Moth, purchased from the late Phil Garratt for \$2,000 down, \$716 a month. Twenty-seven years later, when Ward travelled to Seattle to collect the keys for his first Boeing 747 — C-FDJC, the "Phil Garratt" — a Fox Moth was there, too, sitting proudly beside the aeronautical giant. Max had bought the Moth from Jack Edwards, of Kenora, Ont. Max said then the Moth would be restored to flying condition at his Edmonton shops. Three years later, it has been and that's the airplane — C-FDJB — that Capt. Martin flew to Toronto in July. It has been donated to the Ontario Aviation Historical Society, which will keep it in flying condition and display it at air shows to keep alive another little segment of Canada's long flying heritage.

When Garth Martin set out from Edmonton, his Fox Moth time totalled about 1.5 hours, most of which were consumed in the circuit. The newly-overhauled Gipsy engine was running rough, the airplane was so badly out of rig that almost full rudder pressure was required to keep it aiming straight and already Martin was beginning to have second thoughts.

Finally, after some more tinkering, the engine began to sound a little healthier, and the airplane began to fly just a little straighter without so much rudder pressure.

"It took eight changes of the trim tab on the way east to get it okay, but now it flies hands off," Martin said.

After take-off from Edmonton, Martin flew the highway south to Calgary, landing there minutes ahead of a Wardair 747 in from London. "I kind of waited for him, and led him into the ramp," Martin laughed.

On the leg from Calgary to Swift Current, he met the headwinds that would plague him the rest of the way.

"Between Edmonton and Calgary, I passed some cars and some passed me," he said. "Enroute to Swift Current, they all passed me."

With Regina 15 minutes behind, the engine began to run rough again. "The right side door was partly open, and I didn't know if the roughness was caused by the engine or the door. So I went back to Regina, landed, got out and closed the door. I fired up — the mags checked okay — and did a circuit. The problem had been the door."

Nearing Virden, Man., the oil pressure began to drop. Martin again checked the mags, and the pressure jumped up again, so he continued.

"Then when I was on approach into Brandon, the oil pressure dropped right off," he said. "Nobody told me that when you put the nose down the oil can't get from the tank so the pressure drops."

At Brandon he discovered that the prop spinner was missing. "We parted company somewhere over the Prairies."

Winnipeg was next, then Thunder Bay, with an overnight stop at Kenora to see Jack Edwards, from whom the Moth had been purchased.

"You meet really nice people with an old airplane," Martin mused. "I only had an Esso credit card and the dealer at Kenora sold Shell. He said he'd bill the company because it would be nice

(Continued on page 58)

## Canadian Aviation

Published monthly by  
MACLEAN-HUNTER LTD.

Publisher  
Charles Turner  
Editor

Hugh Whittington  
Editorial/Advertising Assistant

Melanie Wojcik  
Contributing Editors

Neil A. Macdougall  
Johh Gellner

Capt. J. R. Desmarais  
Capt. J. D. Gallagher

Creative Director  
Roger Fountain

Sales Promotion Manager  
Brian Gordon

Production Supervisor  
Mary Kelly

Circulation Manager  
J. C. Henry

Executive, Editorial  
and Circulation Offices 481 University Avenue  
Toronto, Ont. M5W 1A7 Telephone (416) 595-1811  
Donald F. Hunter/Chairman  
Donald G. Campbell/President  
R. W. Robertson/Vice-President,  
Business Publications Division  
Ben Inwood/Group Publisher

ADVERTISING HEADQUARTERS  
481 University Avenue Toronto, Ont. M5W 1A7  
Telephone (416) 595-1811  
Charles T. Turner/W. R. Poutney

ADVERTISING SALES OFFICES  
Montreal  
625 President Kennedy Ave. (514) 845-5141  
Anna Trollo  
Edmonton  
Professional Building 10830 Jasper Ave.  
Room 902 (403) 422-8668 Glyn Murphy  
Vancouver  
#890, 777 Hornby St. (604) 683-8254 T. H. Wylie  
Decatur, Ga. 30032  
Media Representatives, Inc.,  
4319 Covington Highway, Suite 309D  
(404) 284-7072-73  
London W1X 2AE, Eng.  
30 Old Burlington St. 437-0644 Julian Primett  
Los Angeles, Calif. 90057  
Jobson, Jordan, Harrison and Schulz, Inc.  
1901 West 8th St.  
San Francisco, Calif. 94104  
Jobson, Jordan, Harrison and Schulz, Inc.  
Suite 712-715, 57 Post St.

### CONTRIBUTIONS

Material for publication in Canadian Aviation is invited from authors, pilots, instructors, engineers, etc. However, the editors assume no responsibility for return or safety of art-work, photographs, or manuscripts.

Subscription rates: Canada, 1 year \$10; 2 years \$18; 3 years \$22. U.S. and Britain, \$12 yearly; elsewhere \$25 yearly. Single copy price \$1, Directory Issue: \$2.50.


Subscription address: Box 9100, Station "A", Toronto, Ont. M5W 1V5.

All rights reserved. The contents of this publication may not be reproduced either in whole or in part without written consent of the editors.

Copyright 1976 Maclean-Hunter Ltd.  
Member Canadian Business Press  
Member Canadian Circulation Audit Board  
Second class mail registration number: 0983  
ISSN 0008-2953

Return postage guaranteed.  
Post Office returns to this address:  
Canadian Aviation  
481 University Ave.  
Toronto, Ontario M5W 1A7





Capt. Garth Martin and Max Ward at Toronto

### Hugh Whittington

(Continued from page 6)

to get a cheque from Wardair. He said he'd photocopy it and hang the photocopy on the wall."

From Thunder Bay, he had to turn south into the U.S. to get around some weather and later landed at International Falls, Minn. After take-off from there, the engine began to run rough again, developing only 2,000 rpm instead of 2,400. Martin went back to International Falls, ran some checks, took off, had the same problem, and returned again.

A representative of the FBO arrived on the scene, warned Martin that complaints about the low-flying Moth had been received from some of the locals, and offered to help. "I told him the problem, and what he did was to smear wax crayon on each exhaust stack," Martin said. "I fired up, let it run a little while, and shut down. Sure enough, the wax was still on the one stack, so I had a cool cylinder."

Changing the plug didn't help, and that is when one of the "really nice people" one meets with an old airplane came on the scene.

"One of the local old-timers came up

to me and said, 'Sounds to me like she's runnin' on three.' I said, 'Yep . . . guess so.' The old-timer took out a plug, looked at the gap and said, 'You got about fifteen thou here; y'need 25 thou.' I said, 'Yep.' The old-timer took out his jackknife and opened the gap a bit. We replaced the plug, started the engine, and away I went.

"That's what I mean when I say I became a bush pilot in five days."

Next layover was at Sault Ste. Marie, Ont., where Martin met Al Coggan, aviation manager and chief pilot for Algoma Steel Corp. "He's the world's greatest Fox Moth bug. He knows more about Fox Moths than de Havilland."

It was from Coggan's wealth of information on Fox Moths that Martin learned more about the airplane he was flying. He learned that DHC had built 53 Fox Moths in the immediate post-war period; one was being rebuilt in the U.S., some were in India and Pakistan, two were in New Zealand and two more were in bits and pieces at Lac du Bonnet, Man.

"Coggan is building a Fox Moth, as a matter of fact," Martin said. "Max, you only just beat Coggan to that Moth you bought."

Next stop was Wiarton, Ont., for fuel. Despite the headwinds, Martin had the timing just right; take-off from Wiarton right after refuelling would put him at Toronto International Airport, where a reception committee was waiting, at 4 p.m. local time.

"But the engine wouldn't start," he said. "We did everything, but it just wouldn't start. Finally, for no reason at all, it started."

At one minute to four, the reception committee standing outside the cavernous Air Canada maintenance hangar at Toronto saw a Fox Moth pass by a few hundred feet off the ground, the pilot waving at the crowd. Five minutes later, the Moth was once again parked beside Wardair 747, C-FDJC, the "Phil Garratt."


ONE OF THE WELL-WISHERS on hand to greet the arrival of the Fox Moth was Bill McVean. Bill is a pilot, popular Toronto radio personality and air show commentator, who was horribly injured when the replica Nieuport 17 he was flying crashed during an air show at North Bay, Ont.

Bill wasn't expected to recover, let alone fly again, when first taken to the hospital. Later it was said that he would never walk without the aid of a cane.


But after more than a year of rehabilitation during which he showed great courage and spirit, McVean not only walks without a cane, but he has flown again.

"I went up in a 172 with an instructor and told him not to sit there and not do anything unless I was going to get us killed," Bill said. "I wanted to find out if I had any hang-ups about flying. There were none."


And like thousands of other Canadian pilots, he was impatiently awaiting for an end to the work-to-rule campaign by the Civil Aviation Inspectors, so he could get his licence back.



DECATHLON



CITABRIA



**BELLANCA -  
for ABSOLUTE  
VERSATILITY!**

**BELLANCA -  
UNMATCHED in  
VALUE!**

### SCOUT

**YOUR FINEST, LOWEST COST, MOST VERSATILE SINGLE!**

**CITABRIA** - ideal choice for flight schools primary trainers. Aerobatic. Tough. Stable. Takes skis or floats, too.

**DECATHLON** - designed for aerobatics. Capable of competition-beating performance. For all-climate, year-round use.

**SCOUT** - multi-purpose single. Use whole aft section for cargo. Spray. Patroller. Glider Tow Plane. Takes skis or floats, too.

**CALL THESE CANADIAN BELLANCA DISTRIBUTORS FOR INFORMATION, PRICES**

WESTERN CANADA  
DISTRIBUTOR:



**PEACOCK AIRCRAFT**

Lease & Overhaul Ltd.  
P.O. Box 9, Site 16  
Springbank Airport  
R.R. 2, Calgary, Alberta T2P 2G5  
Tel.: (403) 288-1333

EASTERN CANADA  
DISTRIBUTOR:



**BUTTONVILLE  
AIRPORT**

Buttonville, P.O.,  
Ontario  
Tel.: (416) 297-2900  
Telex: 06-219844

P. O. Box 7  
Toronto-Dominion Centre  
King Street West  
TORONTO, Ontario M5K 1A5

September 15th, 1976

5002-060102

Paterson, Land and MacDougall  
P. O. Box 411  
Commerce Court North  
TORONTO, Ontario M5L 1G3

ATTN: MR. A. WILLIAM BRECK

Dear Sir:

As per a letter received from Wardair Canada Limited, Toronto International Airport dated September 13th, 1976, we are hereby releasing the following to your firm:

Aircraft Journey Log  
Aircraft Weight and Balance Report  
Technical Logs  
Additional Work Sheets

Picked up by Mr. Breck September 15th, 1976.

Yours truly,



V. H. McPherson  
Regional Superintendent  
Accident Investigation

SM/rb

Received  
Rev. Breck  
Sep 15/76.

5002-80102

001580



P.O. Box 26,  
Toronto International Airport,  
Toronto AMF, Ontario.  
L5P 1A2

September 13, 1976

Ministry of Transport,  
Aircraft Accident Investigation Division,  
7 King Street West,  
Toronto Dominion Centre,  
P.O. Box 7,  
Toronto, Ontario.



Attention: Mr. Steve Musson - Aircraft Accident Investigation Division

Dear Sirs:

Re: C-FDJB - Fox Moth - owned by Wardair Canada (1975) Ltd.

This letter will serve as your authority to release all documents supplied by our Toronto Maintenance Department and removed from the aircraft wreckage which entailed:

- Aircraft Journey Log
- Aircraft Weight and Balance Report
- Technical Logs
- Additional Work Sheets

These documents are to be released to the law firm of:

Paterson, Lane and MacDougall,  
P.O. Box 411,  
Commerce Court North,  
Toronto, Ontario.  
M5L 1G3

to the attention of: Mr. A. William Breck

Yours very truly,

WARDAIR CANADA (1975) LTD.,

*C. D. McNiven*

C. D. McNiven,  
Superintendent Base/Line Maintenance,  
Eastern Region.


CDM/gh

cc. Mr. A. W. Breck  
Mr. T. L. Spalding



**DE HAVILLAND D.H.82 TIGER MOTH**

Flown for the first time on October 26, 1931, the Tiger Moth was derived from the immediate development of the D.H.60 Moth and was known initially as the D.H.60T Tiger Moth. The initial model, the D.H.82, was powered by a 120 h.p. Gipsy III engine, but the D.H.82A which appeared in 1937 received the more powerful Gipsy Major. More than 1,000 Tiger Moths had been delivered before W.W.II, and subsequently 4,005 were built in the U.K. for the R.A.F., 1,747 were built in Canada (the majority of these being D.H.82Cs with enclosed cockpits), 1,085 were built in Australia, and 345 were built in New Zealand. At the time of closing for press a total of 383 Tiger Moths was registered in Europe, 136 of these in the United Kingdom, 312 were registered in Australasia, and sixty-one in Canada. A number have been converted as four-seat cabin biplanes as the Jackaroo (see page 178).




**Power Plant:** One 130 h.p. de Havilland Gipsy Major I four-cylinder air-cooled engine. **Performance:** Max. speed, 109 m.p.h. at sea level; cruising, 90 m.p.h.; initial climb, 673 ft./min.; service ceiling, 13,600 ft.; range, 285 mls. **Weights:** Empty, 1,115 lb.; loaded, 1,825 lb. **Dimensions:** Span, 29 ft. 4 in.; length, 23 ft. 11 in.; height, 8 ft. 9½ in.; wing area, 239 sq. ft.




**DE HAVILLAND D.H.83 FOX MOTH**

Accommodating four passengers in an enclosed cabin with the pilot in an open cockpit aft, the D.H.83 Fox Moth was flown for the first time on January 29, 1932, and standard Tiger Moth mainplanes, tail unit undercarriage and engine mounting were employed. Wooden construction being used throughout. A total of ninety-eight Fox Moths was built prior to the Second World War, and in 1946, a production line was established by de Havilland Aircraft of Canada for a version of the Fox Moth designated D.H.83C. This employed war surplus D.H.82C Tiger Moth components, was powered by a 145 h.p. Gipsy Major IC in place of the 130 h.p. Gipsy Major, carried a maximum of three passengers, had a strengthened cabin area and enlarged door to facilitate freight loading, and introduced a sliding cockpit canopy. A total of fifty-two was built. Two Fox Moths are registered in the U.K., eight in Canada, three in Australia and three in New Zealand.




**Power Plant:** One 130 h.p. de Havilland Gipsy Major four-cylinder air-cooled engine. **Performance:** Max. speed, 123 m.p.h.; cruising, 105 m.p.h.; initial climb, 605 ft./min.; service ceiling, 15,000 ft.; range at econ. cruising, 415 mls. **Weights:** Empty, 1,100 lb.; loaded, 2,070 lb. **Dimensions:** Span, 30 ft. 10½ in.; length, 25 ft. 9 in.; height, 8 ft. 9½ in.; wing area, 261.5 sq. ft.



**DE HAVILLAND D.H.84 DRAGON**

The D.H.84 Dragon six-passenger two-bay biplane was flown for the first time on November 24, 1932, and production continued until 1937 by which time a total of 115 had been produced. From the sixty-seventh aircraft individually framed windows and faired undercarriage struts were introduced to result in the Dragon II, and eighty-seven aircraft similar to the Dragon I were built by de Havilland in Australia as radio and navigational trainers in 1942-43. Seven Australian-built Dragons are currently registered in Australia and another in New Zealand, and two pre-war Dragons are registered in the United Kingdom, one of these being illustrated below.


**Power Plants:** Two 130 h.p. de Havilland Gipsy Major I four-cylinder air-cooled engines. **Performance:** Max. speed, 134 m.p.h.; cruising, 114 m.p.h.; initial climb, 365 ft./min.; service ceiling, 14,500 ft.; range, 545 mls. **Weights:** Empty, 2,336 lb.; loaded, 4,500 lb. **Dimensions:** Span, 47 ft. 4 in.; length, 34 ft. 6 in.; height, 10 ft. 1 in.; wing area, 376 sq. ft.



**DE HAVILLAND D.H.90 DRAGONFLY**

The Dragonfly five-seat light transport biplane flew for the first time on August 12, 1935, and the prototype was followed by sixty-six production examples, the last of which was delivered in 1938. Of these three remain, one being registered in South Africa, one in Australia (illustrated below) and one in the United Kingdom pending sale in the U.S.A. The Dragonfly is of wooden construction throughout with a monocoque fuselage. Heavy duty spars built into the lower wing centre section have permitted the elimination of all struts and wires from the inner wing bay. The undercarriage units are of cantilever type, and dual controls are provided.

**Power Plants:** Two 130 h.p. de Havilland Gipsy Major I four-cylinder air-cooled engines. **Performance:** Max. speed, 144 m.p.h.; cruising, 125 m.p.h.; initial climb, 730 ft./min.; ceiling, 18,100 ft.; range, 900 mls. **Weights:** Empty, 2,487 lb.; loaded, 4,000 lb. **Dimensions:** Span, 43 ft. 0 in.; length, 31 ft. 8 in.; height, 9 ft. 2 in.; wing area, 256 sq. ft.



# Wardair Canada



WARDAIR "FOX MOTH" C-FDJB

## SPECIFICATIONS OF THE FOX MOTH

Wing Span	30 Feet 10 inches	Passenger Capacity	3 Passengers
Length	25 Feet 9 inches	Cargo Capacity	530 Pounds
Height	8 Feet 5 inches	Engine Power	140 Horsepower
Empty Weight	1458 Pounds	Fuel Capacity	25 Gallons
Maximum Weight	2100 Pounds (Land) 2300 Pounds (Sea) 2100 Pounds (Ski)	Maximum Range	375 Miles
		Speed	85 M.P.H.



95 AA - 928

The DeHavilland Fox Moth first flew in 1932, a short three months after the first flight of the famous "Tiger Moth". DeHavilland Aircraft in England produced the Fox Moth as a derivative of the Tiger Moth to fill the need for a light utility aircraft that could lift three passengers or five to six-hundred pounds of freight from the turf airfields of the time.

During the 1930's, ninety-eight Fox Moths were produced in England. Production costs were kept to a minimum by using the existing and proven components of the Tiger Moth. The wings, tail section, under carriage, engine and propeller were the same and only the wider fuselage of the Fox Moth and its fuel system were new.

After World War II, DeHavilland Aircraft of Canada in Toronto commenced production of the Canadian version of the Fox Moth. At this time there was a requirement for such an aircraft in the expanding bush flying operations of Canada's Northland. The Fox Moth came complete with wheels, skis and floats. DeHavilland was able to utilize many war surplus components from its Tiger Moth production and in all, manufactured fifty-three Fox Moths in the late 1940's.

In 1946, Max Ward acquired one of these Fox Moths, CF-DJC, and commenced his charter operations at Yellowknife, Northwest Territories. This one-plane, one-man operation subsequently grew to become Canada's largest charter airline, Wardair. The registration letters of this first Fox Moth, now C-FDJB, fly proudly on one of Wardair's Boeing 747's.

Five years ago, Wardair acquired one of the last remaining Fox Moths, C-FDJB, and has completely restored the aircraft to its present flying condition. Of the one-hundred and fifty-one Fox Moths originally produced, only six are known to have survived, two in England, one under restoration in the United States and two in New Zealand. C-FDJB is the sole surviving Fox Moth in Canada.

Wardair is proud to present the Fox Moth as a salute to Canada's flying heritage.

The Fox Moth is being flown by Captain Garth Martin of Toronto, who regularly pilots one of Wardair's Boeing 747's.

Metis Police 8:10 9/9/76

8mm - "all of  
ft. on film"

s.19(1)



1 hr

11 Division  
967-2407

Wrong telephone #  
Could not locate  
gm. 

Star

Original As is

PUSLINCH LAKE WATER SKI CLUB

BULLETIN

Puslinch Lake Ski Show which was held on Sat. June 26/76, was rained out and postponed to Sunday June 27th at 2;30 p.m. This turned out to be a super day with great weather and water conditions.

The show was a big success all around with a large crowd that seemed overwhelmed by the feats of our skiers.

A special thank you, to all who worked hard, to make our first Show of the season a success.

A social was held on Sunday June 27th, on the lawn of the McArthur family, after the ski show. An estimated 35 to 40 members attended. Thanks to Irene Dennis and Claudine Hodgson for making this social possible.

The Disabled Clinic was a big success and a note of  
... those who spent many hours to make

DEPARTMENT OF TRANSPORT  
AIR SERVICES BRANCH  
OTTAWA, CANADA

A 3 ISSUE 1  
DH FOX MOTH 83C  
June 21, 1952

AIRCRAFT TYPE APPROVAL

Manufacturer: The de Havilland Aircraft of Canada Limited,  
Postal Station "L",  
Toronto, Canada.

Model DH 83C: Normal Category.

Engine: DH Gipsy Major IC.

Fuel: 77 minimum octane aviation gasoline.

Engine Limits: Normal B.H.P. 130 at 2100 r.p.m.  
Max. B.H.P. 140 at 2400 r.p.m.

C.G. Range: 12 inches to 17.75 inches aft of L.E. of lower wing.


Maximum Weights:  
Landplane - 2150 lbs.  
Skiplane - 2100 lbs.  
Seaplane - 2300 lbs. with item 3(a) installed.  
do - 2100 lbs. with item 3(b) installed  
do - 2050 lbs. with item 3(c) installed.

Number of Seats: Four, including crew.

Approval Basis: A.P. 1208.

Equipment:

1. Fixed pitch metal propeller  
Fairey Reid to Drawing No. 94103A/X1.
2. (a) Ski Installation, Consolidated Mining and  
Smelting Co. Ltd. Drawings 24A/7 and 24A/8.  
Main Ski, Elliott Bros. A-11  
Main Pedestal, DHC W104.
- (b) Ski Installation, DHC Drawing 83006  
Main Ski, Elliott Bros. E10 $\frac{1}{2}$   
Main Pedestal, DHC W104T.
3. (a) Float Installation, DHC Drawing No. 83005 and  
Edo Drawing No. 44-S-121A using Edo 44-2425  
floats.
- (b) Float Installation, Edo Drawing L-3224  
using Edo L floats.
- (c) Float Installation, Fairchild Drawing 0130-D/A  
using Fairchild P $\frac{3}{2}$  floats.

  
(H.S. Rees),  
Chief Aeronautical Engineer,  
Department of Transport.

000108


# The Toronto Star

Holiday edition

on-Fri. 478,383; Sat. 754,360

Monday, September 6, 1976—52 pages

Monday-Friday 15c; Saturday 35c; Home delivery \$1



—Star photo by Patrick Hagev

JUST BEFORE CRASHING into Lake Ontario at the CNE air show yesterday and narrowly missing hundreds of spectators, Fox Moth biplane banks over waterfront. One of 53 produced in Canada after

World War II, it was only one left and had been obtained by Wardair five years ago and restored. This type was among first used when company was established. The crash left it a complete write-off.

## Air crash horrifies thousands at CNE

By DALE BRAZAO  
Star staff writer

A 30-year-old Fox Moth biplane with two men aboard crashed into Lake Ontario at the Canadian National Exhibition air show yesterday,

narrowly missing hundreds of spectators.

Wardair pilot Garth Martin, 42, of Mississauga, dazed and bleeding about the mouth and face, emerged almost immediately from the rear cockpit. He

sat on the fuselage as the nose of the plane sank slowly in 15 feet of water.


His passenger, Wardair mechanic George Benedik, 35, of Berry Rd., was pulled unconscious from the front cockpit.

Rescue personnel massaged Benedik's heart after being unable to perform mouth-to-mouth resuscitation because of the amount of blood coming out of his mouth. "He was hemorrhaging badly inside," an

ambulance attendant said.

Benedik was in critical condition at Toronto Western Hospital. Martin, a pilot for 21 years who usually flies one of Wardair's Boe-

See HORRIFIED, page A3



—Star photo by Fred Guthrie

DAZED AND BLEEDING, Wardair pilot Garth Martin (in flying helmet), 42, is helped by unidentified swimmers. His passenger, Wardair mechanic George Benedik, 35, was pulled unconscious moments

later from front cockpit. It was suspected engine failure caused accident. Witnesses said plane appeared to go out of control on a climbing left turn and plunged sideways into water near Ontario Place.

# Horrified crowds at CNE watch as plane crashes

Continued from page 1

ing 747's was in satisfactory condition at St. Joseph's Hospital with a number of cuts on his face.

The vintage biplane, the only one in Canada, took off from Toronto Island Airport around 2.20 p.m.

It was near centre stage at the CNE waterfront when it appeared to go out of control during a climbing left turn and plunged sideways into the water, 100 feet off the West Island of Ontario Place.

Among the estimated 50,000 people who saw the crash was Star reporter Pat Brennan.

He said it appeared the biplane stalled in midair. "My first reaction was that he was awful low to be pulling a stunt like that," said Brennan adding that a few other planes had stalled their engines on purpose as part of their show.

"A lot of the people around me were convinced it was part of the program. It was so well staged — they thought."

Brennan said a number of people near the crash scene ran back screaming. A few seconds later three men swam out from the West Island at Ontario Place to the plane to help the pilot.

Ross Brewitt of Rexdale said when he saw the plane

begin to make the turn, he had "the eerie feeling something was wrong."

"When I first saw this guy, I said to myself, 'That's no trick,'" he said. "It was sickening, because there was nothing we could do except watch."

Toronto Harbor Police credited speedy action by one of their officers in saving the life of the passenger, after the plane crashed and began sinking.

Harbor policeman Robert Rickstins said he was on the scene with the rescue boat within a minute, but it took him another minute to find the passenger.

"The pilot told me he was all right, and said there was someone trapped below," Rickstins said. "I had to dive three times before I was able to undo his seat-belt and drag him out."

A spokesman for the air show could not explain why Benedik, who was not on board, but added that the biplane was a three-seater and said "the pilot probably just took him along for the ride."

A press release put out by the Canadian International Air Show said engine failure was suspected to be the cause of the accident. Martin, the pilot, refused to comment on the accident.

CNE assistant general

manager Howard Tate, said the rest of the air show went off as scheduled and said there was no reason to cancel today's show to begin at 1.30 p.m.

The federal Transport Ministry is investigating the accident, Tate said.

The pilot's wife, Shaune Martin, said in an interview she was sure "that whatever happened was mechanical because my husband is a perfectionist.

"He's a man who enjoys his life," she said, "I mean he's there too, so anyone who flies with him is going to be as safe as he is."

She and her two children had been up on the Fox Moth and found it to be fun, Mrs. Martin said.

The Moth was one of 53 produced in Canada after World War II. It was obtained by Wardair five years ago, and after being completely refurbished, the Moth took to the skies in July.

Martin flew the aircraft (top speed 85 m.p.h.) from Edmonton to Toronto in five days. It was to perform for the second time today.

The crash was the fourth since the air shows started in 1954 and the first in 10 years.

The last mishap occurred in 1966 when a U.S. Navy pilot was killed when his jet crashed off the Island Airport.

HOLLOWAY  
AIR  
MARKETING



Weekdays: (519) 824-7000  
Evenings & Weekends: (519) 824-8356

001568

19 Clarke Street, East,  
Guelph, Ontario N1H 1S6,  
September 8, 1976.

Mr. Steve Musson,  
Aircraft Accident Investigation Branch,  
Ministry of Transport,  
7th Floor,  
Toronto Dominion Center,  
Toronto 111, Ontario.

Dear Steve:

Enclosed please find a sketch of Garth  
Martin's flight sequence that you requested. I hope  
it is of some assistance.

If I can be of any further help to you  
in the future, please do not hesitate to contact me.

Yours sincerely,

A handwritten signature in cursive script that reads "Stuart".

Stuart W. Holloway.

SWH:wlr

Handwritten initials and the number "000111".

HOLLOWAY  
AIR  
MARKETING

Weekdays: (519) 824-7000

Evenings & Weekends: (519) 824-8356

19 Clarke Street, East,  
Guelph, Ontario N1H 1S6,  
September 8, 1976.

Mr. Steve Musson,  
Aircraft Accident Investigation Branch,  
Ministry of Transport,  
7th Floor,  
Toronto Dominion Center,  
Toronto 111, Ontario.

Dear Steve:

Enclosed please find a sketch of Garth  
Martin's flight sequence that you requested. I hope  
it is of some assistance.

If I can be of any further help to you  
in the future, please do not hesitate to contact me.

Yours sincerely,

Stuart W. Holloway.

SWH:wlr



CANADIAN  
INTERNATIONAL  
AIR SHOW

CANADIAN INTERNATIONAL AIR SHOW EXECUTIVE  
KEN R. ALLEN  
Chairman  
GARY W. McMAHON  
Deputy Chairman  
ARTHUR SCRIVEN  
Director, Ground Operations  
RUSS BOWDERY  
P. R. and Publicity  
GERRY R. SPRACKLIN  
Director, Air Operations  
ARTHUR G. JONES  
Director, Airports and Aircraft Facilities  
TREVOR MOORES  
Official Show Commentator  
HOWARD C. TATE  
CANADIAN NATIONAL EXHIBITION

001581

September 14, 1976



Mr. James A. Cochrane  
6124 - 149th Avenue  
Edmonton, Alberta  
T5A 1V8

Dear Mr. Cochrane:

I have forwarded your pictures of the accident involving  
the Fox Moth along with a copy of your letter to:

Mr. V. McPherson  
Regional Superintendent  
Aircraft Accident Investigation  
Ministry of Transport  
P.O. Box 7  
Toronto Dominion Centre  
Toronto, Ontario  
M5K 1A5

We appreciate your consideration in this matter.

Yours very truly,

J. A. Kirby (Mrs.)  
Executive Secretary

cc: Mr. V. McPherson ✓

*J* 000113

9 Sept 76


Dear Mr. Allan.

I was talking to Russ Bowdry today at the Commonwealth Wartime pilot's get together and told him of these pictures, offering a set for possible use in the investigation, so he suggested your name.

I was covering the event for the armed forces Skyhawks and managed to grab these. The first one is rather unique and may be of some help.

They are personally owned photographs and I would appreciate it if they were not used commercially without my approval...I am planning on a couple of different releases with them....Any further requests can be directed to me in Edmonton, either at the DND Information Office, Alberta region, CFB Edmonton or at my home (phone 478-1256)

Sincerely,



James A. Cochrane

6124-149 Ave.,

Edmonton, Alberta

T5A 1V8



Government of Canada  
Gouvernement du Canada

MEMORANDUM

NOTE DE SERVICE

TO  
A

O C A I

FROM  
DE

Steve Musson

SUBJECT  
OBJET

AIRCRAFT ACCIDENT - C.N.E. WATER FRONT

SECURITY-CLASSIFICATION - DE SÉCURITÉ
OUR FILE - N/RÉFÉRENCE 5002-060102
YOUR FILE - V/RÉFÉRENCE
DATE September 13th, 1976

On Sunday September 5th, 1976, at 14:16 EDT, a De Havilland model DH-83C (Fox Moth) aircraft C-FDJB was involved in an accident while being flown at the Canadian International Air Show, C.N.E. Water Front. The aircraft came to rest approximately 50-75 feet off shore.

The undersigned was present and in fact witnessed the accident.

Immediately following the accident, rescue boats and personnel converged on the scene in the water. Air Show officials on foot and with walkie talkie radio's arrived along the shoreline. I immediately identified myself to one of the officials, who in turn communicated with "BOSS CONTROL" by walkie talkie that I was on the scene. "BOSS CONTROL" requested that I proceed to their location, where I spoke with Mr. Ken Allen, Chairman of the air show. He advised that their intentions were to continue with the show as soon as it was safe to do so. I advised him there would be no problem from our Air Investigation procedure stand point, provided the crash scene was secured and personnel kept away from the wreckage.

The shoreline was roped off in the area of the accident scene and security was maintained by the Ontario Provincial Police.

The air show resumed and I remained at "BOSS CONTROL" where I was in full view of the accident scene, and had access to a telephone.

During the remaining portion of the air show, Wardair was contacted and arrangements to remove the wreckage from the water after the show were made.

The aircraft was removed from the water at approximately 22:00 hours that same evening while I was present, and was transported to a hanger at Toronto Island Airport, where it was placed under secure cover and our investigation continued Monday, September 6th, 1976.

From an accident investigation stand point, our system of notification functioned normal.

Steve Musson  
Aircraft Accident Investigator

000115

MR. MORREY

POLICE

863-2256

~~WATER FRONT~~ BETWEEN  
YORK & SPADINA

SPADINA

EAST

9

DEPARTMENT OF TRANSPORT

MINISTÈRE DES TRANSPORTS

ROUTE SLIP

BORDEREAU D'ACHEMINEMENT

Name - Nom	Routing Symbol Symbole d'acheminement	Date
TO: A:		<input type="checkbox"/> Comment Observations
		<input type="checkbox"/> For your information Pour votre gouverne
		<input type="checkbox"/> Per our conversation Selon notre conversation
		<input type="checkbox"/> Approval Approbation
		<input type="checkbox"/> Discuss with me Discuter avec moi
		<input type="checkbox"/> Take appropriate action Prendre les mesures appropriées

REMARKS:  
REMARQUES:

FROM:  
DE:

Routing Symbol  
Symbole d'acheminement

000117

671-1207




671-1319




826-7939

GARTH MARTIN HM.



6299

AIRPORT RD.



AOÛT 1976				AUG				DIM	LUN	MAR	MER	JEU	VEN	SAM	OCT 1976				OCT		
DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM	
SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT	
1	2	3	4	5	6	7	5	6	7	8	9	10	11	1	2	3	4	5	6	7	8
8	9	10	11	12	13	14	12	13	14	15	16	17	18	9	10	11	12	13	14	15	16
15	16	17	18	19	20	21	19	20	21	22	23	24	25	17	18	19	20	21	22	23	24
22	23	24	25	26	27	28	26	27	28	29	30	.....	.....	24	25	26	27	28	29	30	31
29	30	31	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....

## SEP 11-12 SEPT 1976

SAM-DIM

SAT - SUN

8:00	_____
8:30	_____
9:00	_____
9:30	_____
10:00	_____
10:30	_____
11:00	_____
11:30	_____
12:00	_____
12:30	_____
1:00	_____
1:30	_____
2:00	_____
2:30	_____
3:00	_____
3:30	_____
4:00	_____
4:30	_____
5:00	_____



Government of Canada / Gouvernement du Canada

MEMORANDUM

NOTE DE SERVICE

TO / A

AS I OTTAWA

FROM / DE

O C A I TORONTO

SUBJECT / OBJET

DE HAVILLAND DH-83C, C-FDJB  
ACCIDENT: TORONTO (C.N.E. WATER FRONT) ONTARIO  
SEPTEMBER 5TH, 1976

SECURITY-CLASSIFICATION - DE SÉCURITÉ
OUR FILE - N/RÉFÉRENCE 5002-060102
YOUR FILE - V/RÉFÉRENCE
DATE September 10th, 1976

Enclosed are pages 1 and 2 of Form 23-0059 pertaining to the above mentioned aircraft accident.

  
L. H. McPherson  
Regional Superintendent  
Accident Investigation

Enclosure

SAM/rb

~~1100~~  
1100

STREET

FACH

438-7341

      
BLACK & WHITE

1080 KINGSTON  
RD

KINGSTON RD

&  
VICTORIA

NIE / car

APT - 810

JUIL 1976							JULY							1976				SEPT			
DIM SUN	LUN MON	MAR TUE	MER WED	JEU THU	VEN FRI	SAM SAT	1	2	3	4	5	6	7	DIM SUN	LUN MON	MER WED	JEU THU	VEN FRI	SAM SAT		
4	5	6	7	8	9	10	8	9	10	11	12	13	14	5	6	7	8	9	10	11	
11	12	13	14	15	16	17	15	16	17	18	19	20	21	12	13	14	15	16	17	18	
18	19	20	21	22	23	24	22	23	24	25	26	27	28	19	20	21	22	23	24	25	
25	26	27	28	29	30	31	29	30	31	.....	.....	.....	.....	26	27	28	29	30	.....	.....	

# AOÛT 20 AUG

1976

VENDREDI

FRIDAY

8:00

8:30

9:00

9:30

10:00

10:30

11:00

11:30

12:00

12:30

1:00

1:30

2:00

2:30

3:00

3:30

4:00

4:30

5:00



DENYING CLAIM

PARKED CAR - KING CITY

~~.....~~ RIEG

MRS. HEMANN

STATE FARM

2916 76.01

~~SECRET~~  
SENT. 5

14:16 z

~~SECRET~~  
NO ELT SIGNAL  
RECEIVED - TZ TWR.

A  
~~SECRET~~  
Original As is

121.5

AOÛT 1976							AUG							OCT 1976							OCT													
DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM							
SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT							
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	.....	.....	.....	.....
.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....							
.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....							

SEP 7 SEPT

1976

MARDI

TUESDAY

8:00	
8:30	<i>SB. Queen St.</i>
9:00	
9:30	<i>IFR - RIDE</i>
10:00	<del>.....</del>
10:30	
11:00	
11:30	<i>DAN &amp; CAMERA.</i>
12:00	
12:30	<del>.....</del>
1:00	
1:30	
2:00	
2:30	
3:00	
3:30	
4:00	
4:30	
5:00	

6251

000124

M. R. ALLEN  
CHAIRMAN  
AIR SHOW




KEN REID

868-2523

OFFICE

J. M.  
MUSIC



- HOME.

will call when movie is ready.

≡

s.19(1)



of Mr. MUIE

OFF.

will call when he develops movie.

FA8PT. M<sup>AC</sup> NON ACD

- ME70

# 1st show in 10 years man helps rescue pilot

A man visiting the Canadian National Exhibition air show for the first time in 10 years suddenly found himself part of the show's most dramatic moment Sunday — the rescue of two airmen from their Fox Moth biplane which crashed into Lake Ontario before thousands of horrified spectators.

"I had just finished jostling for half an hour for a good place to see the show," Bernie Schaeffer said. "It was the first time I'd been to the airshow in 10 years and I was really looking forward to it.

"Suddenly the plane hit the water and the next minute so did I. I don't even remember running into the lake but suddenly I was swimming towards the sinking plane."

Schaeffer was one of two men who helped Harbor Police rescue pilot Garth Martin, 42, of Mississauga and his passenger, mechanic

helped comfort pilot Martin before the Harbor Police arrived.

"He (Martin) was on his knees on the plane," Schaeffer said. "The nose of the aircraft was under water. We kept telling him, 'It's all right, everything's okay' but it took a few minutes before he realized anyone was with him.

"Suddenly he said, 'Where's my partner?' and we freaked out. We didn't realize there was a second man."

Schaeffer said he started pulling debris off the plane and then the police arrived. A Harbor Police diver went under three times before he freed Benedik from his seatbelt and brought him to safety.

Benedik was loaded unconscious on to a waiting boat, but, Schaeffer said: "He sort of came to before we touched land — sort of groaning."


Schaeffer, 27, said his rescue attempt wasn't heroism, "just an instant response. I didn't even realize what I was doing until I got wet."

A federal transport department spokesman said an investigation of the crash is under way. Investigators have examined the plane, which showed no evidence of structural defects, but were still waiting to talk with the pilot.

Yesterday, Martin was having trouble talking through a swollen mouth but, otherwise, he said, he feels okay.

CLARM

826-1420  
BUZZS



SOUTH EAST  
MAIN FARM ROAD  
100'  
stepped the turn  
1/2 turn

JUIL 1976							JULY							SEP 1976						
DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM
SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT
....	....	....	....	1	2	3	1	2	3	4	5	6	7	....	....	....	1	2	3	4
4	5	6	7	8	9	10	8	9	10	11	12	13	14	5	6	7	8	9	10	11
11	12	13	14	15	16	17	15	16	17	18	19	20	21	12	13	14	15	16	17	18
18	19	20	21	22	23	24	22	23	24	25	26	27	28	19	20	21	22	23	24	25
25	26	27	28	29	30	31	29	30	31	....	....	....	....	26	27	28	29	30	....	....
....	....	....	....	....	....	....	....	....	....	....	....	....	....	....	....	....	....	....	....	....

# AOÛT 13 AUG

## 1976

VENDREDI

FRIDAY

8:00

8:30

9:00

9:30


10:00

10:30

11:00

000131

s.19(1)



SIDE A after music

TAPÉ

DR. CAROL — WAD AIR CO. DOCTOR

791-2165 OFFICE.

~~///~~  
000133

HOLLOWAY  
AIR  
MARKETING

YE OLDE SCOTT FARM  
RR #5 GUELPH  
N1H 5J2

*19 CHARLES ST*  
*Guelph*

**STUART W. HOLLOWAY**

**COMMUNICATIONS CONSULTANTS  
MEDIA PROJECT PLANNERS  
AIRSHOW SPECIALISTS**

**(D)** 59000134 00  
**(H)** [519] 824-8356

PLAN FOR

SHOW.



000135



CANADIAN  
INTERNATIONAL  
AIR SHOW

GERRY R. SPRACKLEIN  
AIR DIRECTOR

274-8977

000136

Executive Offices, Queen Elizabeth Building, Exhibit  
Toronto, Ontario, Canada M6K 3C3. Telephone (416) 366-7551

Bill Wilson  
C.A.T.C.A.-ONE  
638-3967

35 mm

STILL PICTURE

000137

CHUCK

NOT

MISS

central.

THAT'S



US COAST GUARD

s.19(1)

8 mm MOVIE

AOÛT 1976							AUG							OCT 1976						
DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM
SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT
1	2	3	4	5	6	7	5	6	7	8	9	10	11	3	4	5	6	7	8	9
8	9	10	11	12	13	14	12	13	14	15	16	17	18	10	11	12	13	14	15	16
15	16	17	18	19	20	21	19	20	21	22	23	24	25	17	18	19	20	21	22	23
22	23	24	25	26	27	28	26	27	28	29	30	.....	.....	24	25	26	27	28	29	30
29	30	31	.....	.....	.....	.....	.....	.....	.....	.....	.....	.....	31	.....	.....	.....	.....	.....	.....	

SEP 3 SEPT  
1976

VENDREDI

FRIDAY

8:00

8:30

9:00

9:30

10:00

10:30

11:00

11:30

12:00

12:30

1:00

1:30

2:00

2:30

3:00

3:30

4:00

4:30

5:00

BEAVER - AL Scully.

6247


247

SEP 3 SEPT

000140

s.19(1)

Y  
US COAST  
GUARD



8 mm  
Film

MAR 11 1971

51m MESSER  
WANTHAR

MIKE CALIGARLEGER

OPS MAN.

671-1207

Document disclosed under the *Access to Information Act* -  
Document divulgué en vertu de la *Loi sur l'accès à l'information*



**C. D. (DAN) McNIVEN**

SUPERINTENDENT  
MAINTENANCE  
EASTERN REGION

**WARDAIR CANADA (1975) LTD.**

P.O. BOX 26

TORONTO A.M.F. ONTARIO L4V 1N3

OFFICE PHONE 676-3764

RES. PHONE GEORGETOWN **000143**

TELEX 06-968642

SITA - YYZMMWD

Document disclosed under the Access to Information Act -  
Document divulgué en vertu de la Loi sur l'accès à l'information



TORONTO INTERNATIONAL AIRPORT, P.O. BOX 130, MALTON, ONT.

TELEPHONE (416) 677-6901

AIR-GROUND-RADIO

129.75 MHz

WILLIAM (BILL) TATE

*FILED* 000144

Document disclosed under the Access to Information Act -

~~Document divulgué en vertu de la Loi sur l'accès à l'information~~  
Skycharter ~~Document divulgué en vertu de la Loi sur l'accès à l'information~~  
your safety and comfort our twin engine and Jet  
aircraft are equipped to airline standards and main-  
tained for all weather operations by government  
licensed technicians.

All charter flight operations are flown — by two  
professional pilots under Department of Transport  
Instrument Flight Rules and Controls. Insurance  
substantially exceeds the Canadian Air Transport  
Requirements.

Skycharter is a member Company of the Air Transport Association **000145** a

GEO

NEAL

633-7310  
7862787

DAN

Light on CONTRULS

==

~~HT~~

FLIGHT AB

~~HT~~

+ 70 EMPTY

TAKEN OUT AT

DEHAULMAN

LEFT DOWNSTAIRS  
WITH OUT

~~WED.~~  
WED.  
1ST

~~HT~~

JUL 1976				JULY				DIM	LUN	MAR	MER	JEU	VEN	SAM	SEP	1976				SEPT
DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM
SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT
....	....	....	....	1	2	3	1	2	3	4	5	6	7	....	....	....	1	2	3	4
4	5	6	7	8	9	10	8	9	10	11	12	13	14	5	6	7	8	9	10	11
11	12	13	14	15	16	17	15	16	17	18	19	20	21	12	13	14	15	16	17	18
18	19	20	21	22	23	24	22	23	24	25	26	27	28	19	20	21	22	23	24	25
25	26	27	28	29	30	31	25	26	27	28	29	30	....	26	27	28	29	30	....	....
....	....	....	....	....	....	....	29	30	31	....	....	....	....	....	....	....	....	....	....	....

# AOÛT 21-22 AUG 1976

SAM-DIM

SAT - SUN

8:00	_____
8:30	_____
9:00	_____
9:30	_____
10:00	_____
10:30	_____
11:00	_____
11:30	_____
12:00	_____
12:30	_____
1:00	_____
1:30	_____
2:00	_____
2:30	_____
3:00	_____
3:30	_____
4:00	_____
4:30	_____
5:00	_____

6234

6235

AOÛT 21 AUG  
234 132

AOÛT 22 AUG  
235 000147


10/2-  
[Redacted]

DOUGLAS

~~1~~

s.19(1)

A




200 FEET



SUPER 8" FILM. D



KEN HAIRIE




JUL 1976			JULY				SEP 1976							SEPT						
DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM
SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT
.....	.....	.....	.....	1	2	3	1	2	3	4	5	6	7	.....	.....	.....	.....	2	3	4
4	5	6	7	8	9	10	8	9	10	11	12	13	14	5	6	7	.....	9	10	11
11	12	13	14	15	16	17	15	16	17	18	19	20	21	12	13	14	15	16	17	18
18	19	20	21	22	23	24	22	23	24	25	26	27	28	19	20	21	22	23	24	25
25	26	27	28	29	30	31	29	30	31	.....	.....	.....	.....	26	27	28	29	30	.....	.....

**AOÛT 14-15 AUG 1976**

SAM-DIM

SAT - SUN



6227

6228

**AOÛT 14 AUG**  
227 139

**AOÛT 15** 000149  
228

DEPARTMENT OF TRANSPORT / MINISTÈRE DES TRANSPORTS  
AIRCRAFT ACCIDENT INVESTIGATION DIVISION / DIVISION DES ENQUÊTES SUR LES ACCIDENTS

POSITION OF AIRCRAFT  
WRECKAGE

ENLÈVEMENT DUNE L'ÉPAVE  
D'AÉRONEF

Accident Report No. - Rapport d'accident n°  
Job Number (CAIE) - N° de travail (CAIE)  
Serial No. - N° de série

Aircraft Make and Model - Marque et modèle de l'aéronef  
**DE HAUILLAN 11 FOX**  
Registration - Immatriculation  
**CF-0513**

Serial No. - N° de série  
**FM-28**

Registered Owner or Representative  
Propriétaire enregistré ou représentant  
TO / À  
**WARD AIR CANADA LTD**

Address - Adresse  
**2671 FLYER CND TOWER  
EDMONTON ALTA.**

THIS IS NOTIFICATION THAT THE AIRCRAFT WRECKAGE IS DISPOSED OF, AS FOLLOWS - L'ÉPAVE DE L'AÉRONEF CONCERNÉ FERA L'OBJET DES MESURES PRÉCISÉES CI-APRÈS

- THE AIRCRAFT IN ITS ENTIRETY IS RELEASED TO THE REGISTERED OWNER OR HIS AUTHORIZED REPRESENTATIVE. L'AÉRONEF DOIT ÊTRE INTÉGRALEMENT RESTITUÉ À SON PROPRIÉTAIRE ENREGISTRÉ OU À SON REPRÉSENTANT QUALIFIÉ.
- SOME PORTIONS OR COMPONENTS OF THE AIRCRAFT HAVE BEEN RETAINED FOR THE TECHNICAL INVESTIGATION. THESE PORTIONS OR COMPONENTS ARE LISTED BELOW. - CERTAINS ÉLÉMENTS OU COMPOSANTS DE L'AÉRONEF ONT ÉTÉ RETENUS POUR LES BESOINS DE L'ENQUÊTE TECHNIQUE. CES ÉLÉMENTS OU COMPOSANTS SONT ÉNUMÉRÉS CI-DESSOUS.

*S. J. ...*  
Investigator-in-charge - Enquêteur responsable

▶ YOUR ATTENTION IS DRAWN TO THE AIRCRAFT ACCIDENT INVESTIGATION PROVISIONS OF THE AIR REGULATIONS - VOIR DISPOSITIONS DU RÉGLEMENT DE L'AIR SUR LES ENQUÊTES D'ACCIDENT D'AVIATION ◀

Part Number N° de pièce	Serial Number N° de série	Description	Since Overhaul Depuis révision	Since New Depuis neuf
- AIRCRAFT		JOURNEY LOG BOOK C-FDJB		
- AIRCRAFT		WEIGHT & BALANCE - C-FDJB		
/				
/				
/				
/				
/				
/				
/				
/				
/				

AFTER THE TECHNICAL INVESTIGATION THE ITEMS LISTED ABOVE WILL EITHER BE RETURNED OR SCRAPPED  
APRÈS L'ENQUÊTE TECHNIQUE LES ÉLÉMENTS ÉNUMÉRÉS CI-DESSUS SERONT RESTITUÉS OU MIS AU REBUT

IF APPLICABLE PLEASE 'X' YOUR DISPOSAL INSTRUCTIONS ON THE BLUE COPY AND MAIL THIS COPY TO:  
VEUILLEZ S'IL Y A LIEU FAIRE CONNAÎTRE VOS INSTRUCTIONS CONCERNANT LES MESURES DONT L'AÉRONEF DOIT FAIRE L'OBJET EN BIFFANT LA CASE CORRESPONDANTE SUR L'EXEMPLAIRE BLEU ET QUI SERA ADRESSÉ À:

- RETURN RESTITUTION
- SCRAP REBUT

*C. J. ...*  
Owner or Representative - Propriétaire ou représentant

*Sept. 6/76*  
Date

▶ IF "RETURN" GIVE SHIPPING ADDRESS EN CAS DE RESTITUTION INDIQUER L'ADRESSE DU DESTINATAIRE ◀

**WARD AIR CANADA LTD**  
**Box 26**  
**TORONTO ONT M1F**  
**ATTEN: DAVID McNEIVEN**



Transport  
Canada

Transports  
Canada

# MESSAGE

FILE NO. / DOSSIER N° 5002-060102  
1756-10

DATE September 7, 1976 19

COMPLETE THIS SECTION-REPLIR CETTE PARTIE  
FOR COMMERCIAL MESSAGES CHARGE ONLY | POUR MESSAGES COM-  
MERCIAUX UNIQUEMENT

CHARGE  
TARIF ▶

WCAI EDMONTON

OCAI 148 PLEASE FORWARD AIRCRAFT AND PILOT FILES: C - FOXTROT

DELTA JULIETT BRAVO AND PILOT FILE GARTH McLEAN MARTIN, XDA-867

FOR ACCIDENT INVESTIGATION PURPOSE ONLY.

OCAI TORONTO

5002-060102

FILE NO. / DOSSIER NO. 5008-FDJB  
5802-063128

DATE September 7, 1976<sup>19</sup>

COMPLETE THIS SECTION-REPLIR CETTE PARTIE  
FOR COMMERCIAL MESSAGES CHARGE ONLY | POUR MESSAGES COMMERCEIAUX UNIQUEMENT  
CHARGE TARIFF



Transport Canada

Transports Canada

# MESSAGE

ASI OTTAWA

OCAI 147 RE ACCIDENT FILE 5002-060102 (A) DeHAVILLAND DH-83C  
(FOX MOTH) C - FOXTROT DELTA JULIETT BRAVO (B) WARDAIR CANADA  
(C) GARTH McLEAN MARTIN, XDA-867 (D) SEPTEMBER 5, 1976 14:16EDT  
(E) TORONTO ISLAND AIRPORT / LOCAL (F) WATER FRONT CANADIAN  
NATIONAL EXHIBITION (LAKE ONTARIO) (G1) NIL / ONE (g2) NIL / ONE  
(H) WHILE PERFORMING AT THE CANADIAN NATIONAL EXHIBITION AIR SHOW  
THE AIRCRAFT STRUCK THE WATER IN A STEEP NOSE DOWN RIGHT WING LOW  
ATTITUDE. MUSSON INVESTIGATING.

OCAI TORONTO

cc: OCAR OCAE

5-22-77

person request aircraft  
file C-FDJB, ~~file~~ ~~and~~

~~Edmonton Region~~

and Pilot File for

CAROL McLEAN MARTIN



from  
Edmonton Region.

s.19(1)

JUL 1976							JULY							SEP 1976						
DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM	DIM	LUN	MAR	MER	JEU	VEN	SAM
SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT	SUN	MON	TUE	WED	THU	FRI	SAT
.....	.....	.....	.....	1	2	3	1	2	3	4	5	6	7	.....	.....	.....	1	2	3	4
4	5	6	7	8	9	10	8	9	10	11	12	13	14	5	6	7	8	9	10	11
11	12	13	14	15	16	17	15	16	17	18	19	20	21	12	13	14	15	16	17	18
18	19	20	21	22	23	24	22	23	24	25	26	27	28	19	20	21	22	23	24	25
25	26	27	28	29	30	31	29	30	31	.....	.....	.....	.....	26	27	28	29	30	.....	.....

# AOÛT 31 AUG 1976

MARDI

TUESDAY

8:00	_____
8:30	_____
9:00	_____
9:30	_____
10:00	_____
10:30	_____
11:00	_____
11:30	_____
12:00	_____
12:30	_____
1:00	_____
1:30	_____
2:00	_____
2:30	_____
3:00	_____
3:30	_____
4:00	_____
4:30	_____
5:00	_____

s.19(1)

- (a) Type, nationality and registration  
DE HAUVILLAND DH-83C (Fox Moth) C-FDJB
- (b) Name of owner and operator or hirer  
WARD AIR CANADA
- (c) Name of pilot in command  
GARTH MCLEAN MARTIN
- (d) Date and time of accident (EST)  
SEPT 5 1976 14:16 EDT
- (e) Point of departure and intended landing  
TORONTO ISLAND AIRPORT / LOCAL
- (f) Position of aircraft  
WATER FRONT CANADIAN NATIONAL EXHIBITION (LAKE ONTARIO)
- (g1) Number of crew killed / seriously injured  
NIL / ONE
- (g2) Number of passengers killed / seriously injured  
NIL / ONE
- (h) Nature of accident and extent of damage

WHILE PERFORMING AT THE C.N.E.  
AIR SHOW THE AIRCRAFT STRUCK THE  
WATER IN A STEEP NOSE DOWN RIGHT  
WING LOW ATTITUDE.

NOTIFICATION: Time AT THE SCENE Date SEPT. 5 1976

PLACE	<input type="checkbox"/> Home	METHOD	<input type="checkbox"/> Phone	BY WHOM	<input type="checkbox"/> ATC	.....
	<input type="checkbox"/> Office		<input type="checkbox"/> Personal		<input type="checkbox"/> Owner/Op.	.....
	<input type="checkbox"/> _____		<input type="checkbox"/> Telegram		<input type="checkbox"/> Pilot	.....
			<input type="checkbox"/> Teletype		<input type="checkbox"/> OPP	.....
			<input type="checkbox"/> _____		<input type="checkbox"/> Police Dept.	.....
					<input type="checkbox"/> _____	.....

PERSONNEL NOTIFIED -		Date	Time
1)	_____	_____	_____
2)	_____	_____	_____
3)	_____	_____	_____

PASS.  
 GEORGE BENEDIK






## Canadian National Exhibition

Mr. V. McPherson  
Aircraft Accident Investigation  
Ministry of Transport  
P.O. Box 7  
Toronto Dominion Centre  
TORONTO, Ontario M5K 1A5

Exhibition Place, Toronto, Canada M6K 3C3

*PHOTOS*

*PLEASE DO NOT BEND*





000158



000159



000160



000161



000162






000164




000165



000166



000167



000168






000170



000171















PHOTOS